AGENDA

Oakland-Macomb Interceptor Drain Drainage Board

Macomb and Oakland Counties

August 17, 2022 – 11:30 a.m.

Office of the Macomb County Public Works Commissioner 21777 Dunham Road, Clinton Township, Michigan, and Microsoft Teams

1. Call meeting to order

Board Members:

Michael Gregg, Chair, Michigan Department of Agriculture and Rural Development Candice Miller, Macomb County Public Works Commissioner Jim Nash, Oakland County Water Resources Commissioner

- 2. Motion to approve the meeting agenda for August 17, 2022
- 3. Motion to approve the Drainage District Board Meeting Minutes from July 20, 2022
- 4. Public Comment
- 5. Present Memorandum regarding Great Lakes Water Authority 96" Dia. Water Transmission Main Relocation Projects
- 6. Motion to approve the following Change Orders:
 - a) Walsh Construction Change Order No. 25 for the NESPS Pump & Electrical Upgrades Project for a net increase in the amount of \$278,972.37
 - b) Walsh Construction Change Order No. 1 for Construction of the CS-9 Hatch Cover Damage Repair for a net increase in the amount of \$507,481.00
 - c) Marra Services Change Order No. 3 for NI-EA Contract One, PCI-4 Rehabilitation for a net increase in the amount of \$222,276.41 and a time change of an additional 31 calendar days
- 7. Motion to approve the following Construction Estimates:
 - a) Construction Estimate No. 22 for Walsh Construction for NESPS Pump & Electrical Upgrades Project (GMP Phase) in the amount of \$709,025.50 with a transfer to the Oakland County Treasurer in the amount of \$28,533.25
 - b) Construction Estimate No. 17 for Marra Services for NI-EA Contract No. One for PCI 4 Rehabilitation in the amount of \$303,562.22
- 8. Report/Update Status of OMID Repairs Project
- 9. Financial Reports General Financial Report and Status of State Revolving Fund Financing and Other Financing

10.	Mo	tion to approve the following invoices:			
	a)	Reimbursement			
		1) Labor/Fringes/Non-Direct Labor Factor			
		 Segment 5 NI-EA Construction 		\$	9,168.34
		 Segment 5 NESPS Mech./Elect. Construction 		\$	56,255.90
		2) Equipment Charges			,
		Segment 5 NI-EA Construction		\$	188.72
		 Segment 5 NESPS Mech./Elect. Construction 		\$	407.14
	b)	ASI		·	
	,	Invoice No. 42-8199	NESPS	\$	113,280.89
	c)	Clark Hill		·	,
		1) Invoice No. 1220403	O&M	\$	13,608.00
		2) Invoice No. 1220405	NI-EA	\$	135.00
	d)	Dickinson Wright			
		Invoice No. 1715594	O&M	\$	1,619.50
	e)	Hesco			
		Invoice No. 2213786	O&M	\$	4,016.75
	f)	Jacobs			
		Invoice No. C6A19900-02	O&M	\$	70,618.37
	g)	Kennedy Industries			
		1) Invoice No. 630978	O&M	\$	1,518.00
		2) Invoice No. 631969	O&M	\$	1,040.95
	h)	Metco			
		Invoice No. 1811-43	O&M	\$	80,733.91
	i)	Motor City Electric Company			
		1) Invoice No. 94500	O&M	\$	351.00
		2) Invoice No. 94596	O&M	\$	252.00
	j)	NTH Consultants, Ltd			
		1) Engineering Design Services Rehabilitation of NI-EA Sections PC			
		Invoice No. 630201	NI-EA	\$	1,663.50
		2) Contract No. 1 PCI-4			
		Invoice No. 630202	NI-EA	\$	68,698.49
		3) Eng./Consulting Services NESPS Upgrade			
		Invoice No. 630204	NESPS	\$	1,029.71
		4) Consulting Services – System Inspection			
		Invoice No. 630205	O&M	\$	1,328.50
		5) Rehabilitation Program 2021 Closeout Services			
		Invoice No. 630206	O&M	\$	603.73
		6) Additional NESPS Maintenance Eng. Services			0.00
		Invoice No. 630207	O&M	\$	929.69
	k)	Rotor	0.03.5		1.500.00
		1) Invoice No. 12530	O&M	\$	1,569.00
		2) Invoice No. 12531	O&M	\$	7,082.93
		3) Invoice No. 12532	O&M	\$	2,357.42

11. Other Business

12. Adjourn

Next Regular Meeting: September 21, 2022, 11:30 a.m., Eastern Standard Time.

Oakland-Macomb Interceptor Drain Drainage District

Regular Meeting – Wednesday, August 17, 2022

Agenda Item No. 3

Board Meeting Minutes from July 20, 2022

MINUTES OF THE REGULAR MEETING OF THE DRAINAGE BOARD FOR THE OAKLAND-MACOMB INTERCEPTOR DRAIN DRAINAGE DISTRICT

July 20, 2022

Minutes of the regular meeting of the Drainage Board of the Oakland-Macomb Interceptor Drain Drainage District held at the Office of the Macomb County Public Works Commissioner, 21777 Dunham Road, Clinton Township Michigan on the 20th day of July at 11:30 a.m. Eastern Standard Time and via Microsoft Teams.

PRESENT:

Michael Gregg, Chairperson and Deputy for Gary McDowell, Director of the Michigan Department of Agriculture and Rural Development; Candice Miller, Member and Macomb County Public Works Commissioner; and Jim Nash, Secretary and Oakland County Water Resources Commissioner.

OTHERS PRESENT:

Representing the office of the Macomb County Public Works Commissioner: Brian Baker, Bruce Manning, and Stephen Downing. Representing the office of the Oakland County Water Resources Commissioner: Steve Korth, Brian Coburn, Sid Lockhart, Joel Brown, Evans Bantios, Megan Koss, and Stephanie Lajdziak. Others in attendance: John Michalski, MDARD; Fritz Klingler, FK Engineering; Terry Moore, Metco; Shawn Phelps and Jeff Ragle, OC Fiscal Services; Larry Gilbert and Michelle Kitzinger, NTH Consultants; Sal Saputo and Patrick Kennedy, Meadowbrook Insurance; Dave Pauline, Walsh Construction; Doug Busko, Jacobs.

1. Call meeting to order.

Chairperson Gregg called the meeting to order at 11:32 a.m.

2. Agenda.

Motion by Miller, supported by Nash, to approve the July 20, 2022, agenda as presented.

ADOPTED: Yeas - 3 Nays - 0

Minutes

Motion by Miller, supported by Nash, to approve the minutes of the June 15, 2022, meeting.

ADOPTED: Yeas - 3 Nays - 0

4. Public Comment.

None.

5. <u>Engineering Work Order.</u>

The following Engineering Work Orders were submitted to the Board for approval:

a) NTH Engineering Work Order No. D-449 for CS-9 Hatch Cover Repair Inspection Observation to increase contract #2603 by a not-to-exceed amount of \$59,500 and the creation of the CS-9 Hatch Cover Damage Repair Project. Motion by Miller supported by Nash, to approve the Engineering Work order and the creation of the CS-9 Hatch Cover Damage Repair Project as presented.

ADOPTED: Yeas - 3 Nays - 0

b) NTH Engineering Work Order No. D-450 for Additional Odor and Air Pressure Sampling Effort for NI-EA Rehabilitation Projects to increase contract #2603 by a not-to-exceed amount of \$18,554. Motion by Nash, supported by Miller, to approve the Engineering Work Order as presented.

ADOPTED: Yeas - 3 Nays - 0

6. Change Order.

The following Change Orders were submitted to the Board for approval:

a) Walsh Construction Change Order No. 24 for the NESPS Pump & Electrical Upgrades Project for a net increase in the amount of \$570,665.08. Motion by Nash, supported by Miller, to approve the Change Order as presented.

ADOPTED: Yeas - 3 Nays - 0

b) Walsh Construction Change Order No. 1 for the CS-9 Hatch Cover Damage Repair in the amount of \$507,481. Motion by Nash supported Miller, to approve the Change Order as presented.

ADOPTED: Yeas - 3 Nays - 0

c) Kone Change Order No. 1 for the one year extension of the OMID-DEC Maintenance Services Contract. Motion by Miller, supported by Nash, to approve the Change Order as presented.

ADOPTED: Yeas - 3 Nays - 0

7. <u>Construction Pay Estimates.</u>

The following Construction Pay Estimates were submitted to the Board for approval:

a) Construction Estimate No. 21 for Walsh Construction for NESPS Pump & Electrical Upgrades Project (GMP Phase) in the amount of \$3,600,132.78 with a transfer to the Oakland County Treasurer in the amount of \$43,912.74. Motion by Nash, supported by Miller, to approve the Construction Pay Estimate as presented.

ADOPTED: Yeas - 3 Nays - 0

b) Construction Estimate No. 16 for Marra Services for NI-EA Contract No. One for PCI-4 Rehabilitation in the amount of \$331,260.10. Motion by Nash, supported by Miller, to approve the Construction Pay Estimate as presented.

ADOPTED: Yeas - 3 Nays - 0

8. Report/Update – Status of OMI Project, Segments 1 through 4, NESPS and NI-EA. Fritz Klingler of FK Engineering presented the Project Progress Update to the Board and summarized the status of various projects. Motion by Nash, supported by Miller, to receive and file the report and summary.

ADOPTED: Yeas - 3 Navs - 0

9. <u>Financial Reports</u>.

Shawn Phelps presented the financial reports for NI-EA and the NESPS. Motion by Miller, supported by Nash, to receive and file the financial reports.

ADOPTED: Yeas - 3 Nays - 0

10. Invoices.

The following invoices were submitted to the Board for approval:

a)	ASI		
	Invoice No. 41-8183	NESPS	\$ 82,657.76
b)	Clark Hill		
	1) Invoice No. 1214929	O&M	\$ 2,160.00
	2) Invoice No. 1214934	NI-EA	\$ 1,269.00
c)	Dickinson Wright		
	Invoice No. 1703938	O&M	\$ 3,002.00
d)	Hesco		
	Invoice No. 2213682	O&M	\$ 3,378.80
e)	Jacobs		
	Invoice No. C6A19900-01	O&M	\$ 100,964.56
f)	Kennedy Industries		
	1) Invoice No. 931379-1	O&M	\$ 110.00
	2) Invoice No. 931612	O&M	\$ 3,098.00
g)	Kone		
	1) Invoice No. 1158274162	O&M	\$ 486.66
	2) Invoice No. 1158276230	O&M	\$ 1,009.54
	3) Invoice No. 1158321286	O&M	\$ 273.52
h)	Konecranes		
	Invoice No. 154645862	O&M	\$ 4,483.60
i)	Meadowbrook Insurance		
	Invoice No. 4901	NESPS	\$ 125,000.00

j)	Metco			
3,	Invoice No. 1811-42	O&M	\$	65,326.33
k)	Motor City Electric Company			
	Invoice No. 922567	O&M	\$	225.00
1)	NTH Consultants, Ltd			
	1) Engineering Design Services Rehabilitation of NI-	EA Sections P	CI-4.	
	Invoice No. 629893	NI-EA	\$	19,356.15
	2) Contract No. 1 PCI-4			
	Invoice No. 929894	NI-EA	\$	102,038.22
	3) Eng./Consult. Services NESPS Upgrade			
	Invoice No. 629900	NESPS	\$	4,825.21
	4) Consulting Services – System Inspection			
	Invoice No. 629901	O&M	\$	4,414.01
	5) Rehabilitation Program 2021 Closeout Services			
	Invoice No. 629902	O&M	\$	883.69
	6) Additional NESPS Maintenance Eng. Services			
	Invoice No. 629903	NESPS	\$	2,825.33
m)	PMA Consultants			
	Invoice No. 03559.01-25	O&M	\$	14,423.88
n)	Rotor			
	1) Invoice No. 12522	O&M	\$	2,125.50
	2) Invoice No. 12523	O&M	\$	3,185.74
	3) Invoice No. 12524	O&M	\$	2,403.72
	4) Invoice No. 12525	O&M	\$	548.00
	5) Invoice No. 12526	O&M	\$	959.00
	6) Invoice No. 12527	O&M	\$	11,587.05

Motion by Miller, supported by Nash, to approve the invoices as presented.

ADOPTED: Yeas - 3 Nays - 0

11. Architectural Options and Construction Cost Estimates for ST-S-3

Doug Busko of Jacobs presented a PowerPoint presentation (attached) regarding the architectural options and costs associated with the Meter Station ST-S-3, which is located within the City of Sterling Heights at 17 Mile and Dodge Park. Mr. Busko advised the Board that in December of 2020, performance tests on the meter system were preformed that resulted in the four architectural alternatives presented to the Board. It was decided that a meeting with Board members and Sterling Heights officials would be in order to review the concept options.

Motion my Miller, supported by Nash to receive and file the Architectural Options and Construction Cost Estimates for ST-S-3 Presentation as presented.

ADOPTED: Yeas - 3 Nays - 0

12. Other Business.

None.

13. Adjourn.

Motion by Nash, supported by Miller, to adjourn the July 20, meeting at 1:37 p.m.

ADOPTED: Yeas - 3 Nays - 0

Next Regular Meeting: Office of the Macomb County Public Works Commissioner, 21777 Dunham Road, Clinton Township, Michigan and electronically at 10:00 a.m., Eastern Standard Time on August 17, 2022.

I hereby certify that the foregoing constitutes the minutes of the Drainage Board for the Oakland-Macomb Interceptor Drain Drainage District, at a meeting held on July 20, 2022, and that the meeting was conducted and public notice was given in compliance with the Open Meetings Act being Act 267, Public Acts of Michigan, 1976, as amended, and that the minutes were kept and will be or have been made available to the public as required by the Act.

IN WITNESS WHEREOF, I have hereunto affixed my official signature on this 20^{th} day of July 2022

Jim Nash, Secretary

Oakland-Macomb Interceptor Drain Drainage Board

Oakland-Macomb Interceptor Drain Drainage District

Regular Meeting – Wednesday, August 17, 2022

Agenda Item No. 4

Public Comment

Oakland-Macomb Interceptor Drain Drainage District

Regular Meeting – Wednesday, August 17, 2022

Agenda Item No. 5

GLWA Water Transmission Main Relocation Projects Memorandum

OAKLAND COUNTY WATER RESOURCES COMMISSIONER

MEMORANDUM

TO: Mr. Michael Gregg, Chairperson of the Oakland-Macomb Inter-County Drain Drainage District

FROM: Brian Bennett, P.E., Civil Engineer III

SUBJECT: Great Lakes Water Authority 96" Dia. Water Transmission Main Relocation Projects

DATE: August 17, 2022

On December 7, 2021, WRC received correspondence (copy attached) and plans from the Great Lakes Water Authority requesting a permit to discharge water to OMID from GLWA's 96" dia. Water Transmission Main Relocation project. WRC's review of the plans indicates there are two projects involving OMID facilities as described below:

GLWA 96" Water Transmission Main Relocation - East Avon Road Early Works Package

GLWA is requesting approval to install a temporary connection to OMID Meter No. 1000 for dewatering operations during construction. Although not anticipated, if contaminated groundwater is encountered during construction, the discharge will be required to adhere to the standards governing domestic and industrial wastes as specified in the Oakland County Wastewater Disposal Standards and Regulations adopted by the Oakland County Board of Commissioners on May 11, 1989, GLWA Industrial Pretreatment Requirements, OMID Industrial Pretreatment Requirements and any other statutorily or regulatorily treatments. Daily test results will be submitted to WRC.

GLWA 96" Water Transmission Main Relocation

This project includes the abandonment of an existing 96" dia. water transmission main located in the G & H Industrial Landfill site. A temporary connection to OMID, located approximately northeast of the intersection of Hamlin and Dequindre Roads is proposed to provide an outlet for the water contained within the existing 96" dia. water transmission main and any groundwater that may seep into the water transmission main during its abandonment. Water will be pretreated by a mobile granular-activated carbon treatment system prior to discharging to the OMID. It is estimated that 3 MG of water will be discharged to the OMID at a rate of 400 GPM. Treatment will follow Oakland County Wastewater Disposal Standards and Regulations, GLWA Industrial Pretreatment requirements and other requirements as cited above. Daily test results will be submitted to WRC.

A second temporary connection to OMID Meter No. 1000 is proposed for dewatering operations during construction.

WRC's staff recommends the Drainage Board approve the request from GLWA subject to the discharge to the OMID being metered and with GLWA reimbursing the District all inspection costs.

Respectively submitted,

Brian Bennett, P.E.

Attachment: GLWA 12/7/21 Permit Request Letter



Office of the Interim Chief Executive Officer

735 Randolph Street, Suite 1900 Detroit, Michigan 48226

December 7, 2021

Oakland-Macomb Interceptor Drain Drainage District (OMIDDD) c/o Oakland County Water Resources Commissioner's Office One Public Works Drive, Building 95 West Waterford, MI 48328

Attn.: Michael Gregg, OMIDDD Chair, Michigan Dept. of Agriculture & Rural Development

Ms. Candice Miller, Macomb County Public Works Commissioner Mr. Jim Nash, Oakland County Water Resources Commissioner

Re: Request for Permit to Discharge to the Oakland-Macomb Interceptor Drain (OMID)

GLWA 96-inch Water Transmission Main Relocation Project

Honorable OMIDDD Drain Board,

In June 2020, the Great Lakes Water Authority (GLWA) retained Jacobs Consultants, Inc. (Jacobs) to provide design engineering services and services during construction for a new 96-inch diameter water transmission main (WTM), which will be located between the intersection of 24 Mile Road and the Macomb Orchard Trail and the intersection of Dequindre Road and Hamlin Road. This new location will greatly improve access for future operations and maintenance and allow GLWA to abandon existing 96-inch drinking water transmission main located within the closed G&H Industrial Landfill site.

The construction project will produce a discharge to the Oakland Arm Interceptor of the OMID system that includes (1) draining an estimated three million gallons of water from the existing 96-inch WTM, (2) groundwater from the construction trenches, and (3) groundwater collected in the decommissioned WTM. The Oakland Arm conveys wastewater by gravity to OMIDDD's Edison Corridor, which is then lifted via the Northeast Sewage Pumping Station (NESPS) to the North Interceptor-East Arm (NI-EA), which delivers wastewater by gravity to GLWA's Water Resource Recovery Facility (WRRF).

The discharge of all water will be controlled through a Special Discharge Permit issued by GLWA's Industrial Waste Control group to assure that the discharges are pre-treated for any potential contaminants prior to being discharged to the Oakland Arm Interceptor of the OMID system. GLWA'S WRRF agrees to accept these flows for treatment at the WRRF.

GLWA agrees to meter these discharges to the OMID and report the meter readings to OMIDDD representatives as requested.

GLWA respectfully requests a permit from the OMIDDD to approve the proposed pre-treated discharges resulting from construction of the new 96-inch WTM and decommissioning of a portion of the existing 96-inch WTM. GLWA also requests that OMIDDD provide the sampling frequency that will be required as part of OMIDDD's discharge permit.

A more detailed project summary is attached to this letter for your reference. Please contact Grant Gartrell, P.E., Director of Engineering, Water Operations at 313-269-1147 or Jason Matteo, P.E., Jacobs Project Manager at 586-453-8666 with any questions.

Sincerely,

Suzanne R. Coffey, P.E.

Interim Chief Executive Officer

ATTACHMENTS:

Attachment 1: Request for Permit to Discharge to the Oakland-Macomb Interceptor Drain – Project Summary

Attachment 2: Meeting Summary for April 1, 2021 Meeting Between GLWA and Jacobs Regarding GLWA 96-inch Water Transmission Main Relocation Project 96-inch WTM Decommissioning Plan Coordination

ec: Grant Gartrell, GLWA



Oakland-Macomb Interceptor Drain Drainage District

Regular Meeting – Wednesday, August 17, 2022

Agenda Item No. 6

Change Orders

CHANGE ORDER NO. TWENTY-FIVE

Oakland Macomb Interceptor Drain, Drainage District (OMIDDD) For Construction of the Pump and Electrical Upgrades Project Northeast Sewage Pumping Station (NESPS)

Located in the City of Detroit, Wayne County, Michigan

CONSTRUCTION MANAGER, AT RISK (CMAR) Walsh Construction Co. II, LLC

Authorization for:

1.) Replace Wet Well Pressure Transducers; 2.) Lighting Panel Replacement; 3.) Remove and relocate the HVAC Panel from Mezzanine to north wall of Main (Pump) Floor Level # 1; 4.) Furnish and install fire-rated door with glazing at Door Location No.6; 5) Provide fall protection device Certification for roof top access ladder; 7.) Provide credit for wiring deletion, per RFI # 151.

Address:

Walsh Construction Co. II LLC 3031 West Grand Blvd., Suite 640

Detroit, MI 48202

Change Order No. 25 Date: August 05, 2022

	Location-Description-Reason	Unit	Est. Qty.	Unit Price	Amount Increase	Amount Decrease
	LOCATION: The Northeast Sewage Pumping Station; Detroit, Wayne County, Michigan					
25 -1	DESCRIPTION (Extra/ Add): Furnish and install two ea. Pressure transducers with cabling to Electrical room, two ea. Pressure Transmitters mounted in Electrical Room, two ea. new Stilling Wells with support brackets in Wet Well, new conduit in Wet Well and Dry Well to Control Room, and demolish and remove existing level sensor equipment, conduits, and support system.	LS	1 ea.	\$117,041.68	\$117,041.68	-0-
	REASON: The Wet Well level sensor instrumentation systems provide the basic information for control of the station's dewatering pumps. The existing aged system is antiquated, unreliable, and partially inoperable. In order to ensure accurate					

Page 1 of 7

	Location-Description-Reason	Unit	Est. Qty.	Unit Price	Amount Increase	Amount Decrease
25 -1	and reliable data is provided for the new main sewage pumps, it was considered necessary to replace this instrumentation system in its entirety, including removal of the existing equipment. The work will be sequenced in a manner that the new equipment is integrated into service while the existing equipment is simultaneously phased out such that the station will not be without this critical service. Attachment: Walsh Construction PCI No.970117					
25 -2	DESCRIPTION:(Extra/ Add) Furnish and Install a Lighting Panel System that will replace the existing aged Lighting Panel	LS	ea.	\$60,345.56	\$60,345.56	-0-
	electrical installations.					
	REASON:					
	The existing Lighting panels survive primarily from the original building construction and have deteriorated to a condition where full replacement is considered necessary. The lighting panels provide for electrical power distribution to not only to the building lighting, but also to a significant number of support equipment and related electrical devices. The new panels will provide reliability, improved safety conditions, and the ability to expand with additional circuitry as the future need arises.					
	Attachment: Walsh Construction PCI No. 970122					
25 -3	DESCRIPTION (Change/ Add): Relocate the existing HVAC equipment (Heating/Ventilation, Air Conditioning) panel from the Mezzanine Electrical Gear area to the north wall of the main Pump Level floor # 1.	LS	ea.	\$95,229.33	\$95,229.33	-0-

	Location-Description-Reason	Unit	Est. Qty.	Unit Price	Amount Increase	Amount Decrease
25 -3	REASON: The HVAC Control panels service the Bio-Trickling Filter, the Wet Well Exhaust and Make-up Air Fans, the Dry Well Supply and Exhaust Fans, the Gas Detection Monitoring equipment, Drywell Entry and Exit requests, and various related Alarm Horns and Beacons; as such the panels are a critical component of the facilities control system. As an important segment of the electrical system upgrades, it was considered appropriate to relocate the Panel away from the Mezzanine area to a new location better suited to support the various functions previously mentioned. In addition, this relocation also serves to help "clear" the Mezzanine area for future planned improvements. Attachment: Walsh Construction PCI #970145					
25 -4	DESCRIPTION (CHANGE/ ADD): Furnish and install a fire rated pedestrian door with rated window glazing at the Door # 6 location (connecting the corridor between the existing NESPS Mezzanine area and the new Electrical Building). REASON: Evaluation of the connecting door at Location #6 indicated the existing door should be replaced with a fire rated door to ensure code compliance, and also to include a window to allow entrants to identify individuals who may be entering on the opposite side of the door, thereby avoiding "pedestrian collisions". The existing door will be salvaged for re-use elsewhere in the facility. Attachment: Walsh Construction No.970147	LS	ea,	\$ 2,781.23	\$2,781.23	-0-

	Location-Description-Reason	Unit	Est. Qty.	Unit Price	Amount Increase	Amount Decrease
			Griy's	11100	11010030	Doorodoo
25 -5	DESCRIPTION: (Extra/ Add): Provide testing and formal certification for the MSA (Mine Safety Appliances) fall protection device on the NESPS roof access ladder (Low roof to High roof).	LS	Еа.	\$ 3,611.36	\$3,611.36	-0-
	REASON: The recently installed fabricated steel access ladder fall protection device requires inspection and certification as described in OSHA Standard 1910, 140 (Personal Fall Protection Systems). Certification involves testing and inspection by Qualified Fall Protection personnel, and in this case will be provided by the specialized "Diversified Fall Protection Co." of Cleveland, OH. Attachment: Walsh Construction PCI No. 970149					
25 -6	DESCRIPTION (Change/ Delete): Provide credit for revisions to the proposed power feed to the Ovation RTU and UPS.	LS	Ea.	(\$36.79)	-0-	(\$36.79)
	REASON: A clarifying response to RFI # 151 resulted in the deletion of a previously anticipated feed from a DC panel to alternative Ovation sources. Attachment: Walsh Construction PCI No. 970150					

	End of Change Order No. 25 Line Items					

Location-Description-Reason	Unit	Est. Qty.	Unit Price	Amount Increase	Amount Decrease
				Amount	Amazunt
Summary, Change Order # 25 Line Items				Amount Increase	Amount Decrease
			Totals	\$279,009.16	(\$36.79)
		Net			8 E P R P P 8 P P 8
			Changes (Increase)	\$278,972.37	

OMID DD NESPS; Pump & Electrical Upgrades Project; C.O. # 25 Prepared By: Lawrence T. Gilbert, P.E. NTH Consultants, Ltd. 8/10/2022 Date: Recommended By: John Michalski, P.E. Engineer of Design, Applied Science, Inc. Date: Approved By: Joel Brown, P.E. Project Manager, WRC 8/12/2022 Stephen Downing Date: Approved By: Stephen Downing Construction and Maintenance Manager, Macomb County Public Works Date: Approved By: Sid Lockhart, P.E. Manager of Special Projects, WRC Steven Korth Aug. 17, 2022 Date: Approved by: Steve Korth, P.E. Manager, WRC All of Construction Manager's contractual obligations remain in place and are applicable to all work and payments identified herein. No adjustment to contract time or price shall be made for these issues except as set out in this, or by a subsequent related, Change Order. The Construction Manager agrees to do the work described above and agrees to accept Contract time adjustments in full on the basis indicated. Aug-08-2022 | 8:43 AM CDT Date Accepted by: Title Vice President Walsh Construction Co. II, Inc. of: The Construction Manager is hereby authorized and instructed to do the Work described above in accordance with the terms of the Contract, as amended. This Change Order No. 25 was approved by the Drainage Board on: Date: Page 6 of 7

Attachment No. 1 to Change Order No. Twenty-Five

The Engineer has reviewed the items included in this Change Order and confirms that these adjustments to the Contract are reasonable and in accordance with industry standards and the requirements of the Contract.

Contract Status Summary Change Order No. Twenty-Five OMID NESPS Pump & Electrical Upgrades Project

Construction Manager at Risk: Walsh Construction Co. II

Project Award Date (Pre-Construction Services)	December 16, 2019
Notice to Proceed Date (Construction Phase)	October 23, 2020
Contract Substantial Completion Date	March 24, 2023
Contract Final Completion Date	June 23, 2023
Original GMP Contract Value (Including Control Structure 9)	\$ 42,863,185.19
Pre-Construction Phase, Unused Budget	\$ 70,196.70
C.O. Values, # 7, 8, 9, 10, 11, 12, 13, 14, 15,16, 17,18, 19, 20, 21,2 23, and # 24 (Not Including CS-9 C.O. total of \$ 63,100.29)	2, \$ 46,695,561.73
Change Order Value, this C.O. # 25	\$ 278,972.37
Adjusted GMP Contract Value (incl. this C.O. # 25)	\$ 46,974,534.10

Change Order

CHANGE ORDER NO. 1

Oakland-Macomb Interceptor Drain Drainage District Board For Construction of the OMID CS-9 Hatch Cover Damage Repair (Contract #5977) Located in City of Detroit, Wayne County, MI

CONTRACTOR: Walsh Construction Company II, LLC	Authorization for C	hanges In ar	าd Extras to C	ontract
Address: 3031 West Grand Blvd. Ste. 640				
Detroit, MI 48202	Change Order No:	1	Date:	7/10/2022

Auth No.	Location-Description-Reason	Unit Used	Est. Qty.	Unit Price	Amount Increase	Amount Decrease
	LOCATION:					
1-1	CS-9 and approximately 1400 feet of downstream of PCI-5					
	DESCRIPTION:					
1-1	(Change/Add): Grant Walsh authorization to proceed with repair of damage to the CS-9 fiberglass walkways and PCI-5 HOBAS liner downstream of CS-9, in accordance with their appended repair proposal, that occurred as a result of two CS-9 hatch covers dropping into the interceptor during work on the CS-9 Gate Design project.	LS	1	\$507,481.00	\$507,481.00	-
	REASON:					
1-1	On August 31, 2022, during startup activities related to the CS-9 Gate Design project, two CS-9 hatch covers were inadvertently left unbolted upon conclusion of the day's activities. The hatch covers ultimately became dislodged from the frame and fell into the interceptor between August 31, 2022 and Septemeber 1, 2022 causing damage to the PCI-5 HOBAS liner within the first 1400 feet downstream of CS-9 (see appended NTH Daily Field Report dated 9/10/2021). An insurance claim, #KY21K2817628 was made under the OCIP Builder's Risk Policy #11175077001 issued by ACE American Insurance Company (ACE). Walsh's submitted repair costs, totaling \$532,481 and attached to this change order, were ultimately accepted by ACE, less a \$25,000 deductible to be paid by Walsh, (see appended Proof of Loss Sworn Statement) in addition to construction observation costs by NTH Consultants, Inc for a total of \$59,500 (work to be issued separately from Walsh). A check will be issued to OMIDDD to disburse the balance of \$507,481 to Walsh as the repairs are made. This effort is being facilitated under a different project to avoid capitlizing these costs against the installed CS-9 gate infrastructure, as they are repair efforts to existing work and not part of the CS-9 Gate Design.					
				Item A Total	\$507,481.00	\$0.00
				Total	\$507,481.00	

Change Order

	CHANGE ORDER NO1	
For Constr	Oakland-Macomb Interceptor Drain Drainage District B uction of the OMID CS-9 Hatch Cover Damage Repair (coard (Contract #5977)
Prepared by: WRC:	Joel Brown, P.E., Chief Engineer	Date:8/9/2022
Recommended by: Applied Science	John Michalski, P.E., Vice President	Date: 8/3/2022
Approved by: MCPWO Manager:	Stephen Downing Stephen Downing (Construction & Maintenance Management)	Date: 8/9/2022 ger)
Approved by: WRC Manager:	Sid Lockhart, P.E. (Special Projects Manager)	Date:
Approved by: WRC Manager –	Steven Korth Steven Korth, P.E.	Date:Aug. 17, 2022
The Contractor agrees to do to pasis indicated.	he work described above and agrees to accept paymen	t in full on the
Accepted by:	Title Vice President	Date: Aug-02-2022 7:36 AM CDT
of:	Walsh Construciton II, LLC	
The Contractor is hereby auth the terms of the Contract.	orized and instructed to do the work described above in	accordance with
This Change Order No. 1 was	approved by the Drainage Board on:	Date:



September 9th, 2021

Mr. Sal Saputo

Meadowbrook Insurance Group

26255 American Drive

Southfield, MI 48034

Salvatore.Saputo@Meadowbrook.com

RE: OMID CS-9

Notification of a Potential Builder's Risk Claim

Dear Mr. Saputo,

Walsh is notifying Meadowbrook Insurance Group of a potential claim to the OCIP Builder's Risk policy. The event location is 12601 Ten Mile Road, Warren Michigan 48089. This event occurred between Tuesday August 31st 2:30pm and Wednesday September 1st, 10am. We believe the cost of this claim will exceed the \$25,000 deductible.

This event involves two of the shaft hatch covers being lifted by air pressure in the interceptor and then falling into the shaft / interceptor. The platform railing and concrete were damaged. Damage to the pipe liner has not been verified.

Mobilization of equipment and manpower was done on September 1st to secure the site. Further work will occur September 10th in an attempt to recover the lids and verify the extent of damage. The scope of repair work still needs to be quantified. Costs will be manpower, equipment rental, fiberglass handrail, fiberglass grating, concrete repair, and others if the investigation discovers more damage.

I will be the contact for this claim. Please contact me with questions and clarification.

Very truly yours,

WALSH CONSTRUCTION COMPANY II, LLC

Dave Pauline P

David Pauline
Project Manager
dpauline@walshgroup.com

cc: (file)



March 15th, 2022

Joe Andrews, CLCS Executive General Adjuster Engle Martin & Associates Macomb, Michigan 48042 jandrews@englemartin.com

RE: OMID CS-9 HOBAS® Repair Budget

To Mr. Andrews,

Walsh is providing the estimated costs to repair the HOBAS® Liner at the Control Structure CS-9 caused by the lid damage. Based on contractor information they provided the estimated cost is \$532,481. This is a budget based on the following scope of work.

Repair of the Hobas liner will require shaft access with a crane access, safety equipment, and generator. The duration estimate is 15 working days, allowing for weather days or flow control limitations included in this total. The work will consist of the liner repair team and this with access, it will also require a top-side safety person, top side support crew (2) and the crane operator. The tentative plan is to perform this repair starting spring of 2022.

Repair of the fiberglass handrail will require the same shaft access with an estimated duration of 10 days, with 2 additional days to be counted as a weather day. A crew of 2 people will remove and install new handrail to replace the damaged sections. Shaft access will require a top safety person, top side support crew (2) and the crane operator. This work will follow the liner repair and is contingent upon the material order / delivery. The lack of availability of the resin required for the handrail will require extended lead time and not allow the duplication use of the crane.

Costs have been incurred starting with the activity September 1st, 2021, and the activity spent searching for the lids September 10th, 2021. Later in December, a site walk was completed with several parties involved to determine the scope of work.

Walsh will track and manage costs to provide the best value to the client and provide documentation for this work throughout the repair.

Very truly yours,

WALSH CONSTRUCTION COMPANY II, LLC

David Pauline
Project Manager
dpauline@walshgroup.com

cc: Joel Brown (WRC), Larry Gilbert (NTH), (file)

CS-9 REPAIR BUDGET PRICING

Cost Budget Summary

Contractor:	Walsh Construction	by: D. Pauline
Project:	OMIDDD CS-9 HOBAS Liner Repair	•
Estimate Number:	1	
Description of Work	Budget for : Repair the Interceptor Liner and platform handrail.	

	Straight						(Overtime				
Name / Position	Time	Stra	aight Time	St	raight Time	Overtime	La	abor Cost	(Overtime		
	Manhours	Labo	r Cost Rate	L	abor Cost	Manhours		Rate	La	bor Cost	To	otal Labor Cost
Mike Matyaszek	236.0	\$	101.34	\$	23,916.24	4.0	\$	128.60	\$	514.40	\$	24,430.64
Project Manager	232.0	\$	185.34	\$	42,998.88	0.0	\$	125.60	\$	-	\$	42,998.88
Dave Pauline - PM	30.0	\$	185.34	\$	5,560.20	0.0	\$	185.34	\$	-	\$	5,560.20
Ankur Patel - SUP	34.0	\$	149.83	\$	5,094.22	0.0	\$	149.83	\$	-	\$	5,094.22
Mike Graziano - PE	35.0	\$	117.60	\$	4,116.00	0.0	\$	117.60	\$	-	\$	4,116.00
Christian Biolchini - QL	26.0	\$	117.60	\$	3,057.60	6.0	\$	117.60	\$	705.60	\$	3,763.20
	593.0	\$	-	\$	-	0.0	\$	-	\$	-	\$	-
	Subtotals:										\$	85,963.14

(1) Labor Total \$ 85,963.14

(2) Materials Summary								
Material Description	l	Jnit Price	Total Quantity			Total	Material Cost	
Acrylamide grout - gallon	\$	22.00	5			\$	110.00	
				Mater	rial Subtotal	\$	110.00	
				Tax	6%	\$	6.60	
				Material Mark-Up	15%	\$	17.49	
				(2) I	Material Cost	\$	134.09	
(3) Equipment								
ltem		Rate	Duration		Days	Tota	l Equip. Cost	Remarks
EQUIPMENT USING FUEL AND LUBE								
United Rental	\$	7,154.47				\$	7,154.47	Cost already realized
Jay's Septic	\$	600.00	Delivery /	Removal / month rental		\$	600.00	
LGH	\$	5,801.21				\$	5,801.21	Cost already realized
Dunham's - (Wadders)	\$	109.69				\$	109.69	Cost already realized
LGH - Manbasket Rental	\$	550.00	6	weeks		\$	3,300.00	
						\$	-	
				Equipment :	Subtotal	\$	16,965.37	
				Equipment Mark-Up	15%	\$	2,544.81	
				(3) Equip	ment Total	\$	19,510.18	

OMID NESPS Pumping and Electrical System Upgrades

(4) Subcontractors	Quantity	Un	nit cost				
Christman - Landscaping	1	\$	17,772.00		\$	17,772.00	
DeCal Mechanical	1	\$	11,277.00		\$	11,277.00	Cost already realized
Doetsch repair crew	15	\$	8,200.00		\$	123,000.00	
Doetsch Layout	1	\$	6,200.00		\$	6,200.00	
Doetsch Crane	18	\$	2,667.00	Includes 3 Weather days	\$	48,006.00	
Ross Structural Steel - Road Plate	1	\$	3,342.00		\$	3,342.00	Cost already realized
Ross Structural Steel - Handrail	1	\$	130,170.00		\$	130,170.00	
Handrail Crane	12	\$	2,667.00	Includes 2 Weather days	\$	32,004.00	
Hobas Inspector	9	\$	1,000.00	Travel Monday and Friday, on site T/W/Th	\$	9,000.00	
Hobas Tech	9	\$	900.00	Travel Monday and Friday, on site T/W/Th	\$	8,100.00	
Hobas Material	1	\$	5,200.00		\$	5,200.00	
Hobas travel per week	3	\$	3,800.00	This is per 2 Hobas reps	\$	11,400.00	
				(4) Subcontractors Total	\$	405,471.00	
Totals Summary							
Walsh Construction Labor					\$	85,963.14	
Material / Equipment							
	Total Items 2 a	nd 3			\$	19,644.27	
	5.75%	CM	IAR FEE		\$	1,129.55	
Subcontractor							
	Total Items	4			\$	405,471.00	
	5.75%		IAR FEE		¢.	,	
	3.1370	CIVI			φ	20,273.55	
				L			J

Total \$ 532,481.50

Estimated By:	Dave Pauline
Title of Proposer:	Project Manager
Date:	
-	

MANPOWER

STAIGHT TIME	Mike Matyaszek	Project Manager	Dave Pauline - PM	Ankur Patel - SUP	Mike Graziano - PE	Christian Biolchini - QL	
8-Sep	8						
1	8	8					
2	8	8					
3	8	8					
4	8	8					
5	8	8					
6	8	8					
8	8	8 8					
9	8	8					
10	8	8					
11	8	8					
12	8	8					
13	8	8					
14	8	8					
15	8	8					
16	8	8					la da
17 18	0	8 8					landscape landscape
10	U	8					landscape
		J					апассарс
9/1/21			8	8	8	2	
9/3/21			8	8	8	8	
9/4/21	4						
9/10/21	8		8	8	8	8	
11/10/21	8		4	8	8	6	
12/2/21	0	0	2	2	3	2	EDD ank Dave
1 2	8	8 8					FRP only Days FRP only Days
3	8	8					FRP only Days
4	8	8					FRP only Days
5	8	8					FRP only Days
6	8	8					FRP only Days
7	8	8					FRP only Days
8	8	8					FRP only Days
9	8	8					FRP only Days
10	8	8	20	0.4	0.5		FRP only Days
Total	236	232	30	34	35	26	

VENDORS

Invoice	Vendor	Cos	t
	Acrylamide grout - gallon	\$	22.00
Total	_	\$	22.00

Vendor	Cost
	<u> </u>
	Vendor

EQUIPMENT

Invoice	Item	Cost
197511959-002	United Rental	3040.08
197511959-003	United Rental	1431.00
197511959-004	United Rental	-477.00
199199392-001	United Rental	1275.18
200080010-002	United Rental	1673.21
199199392-003	United Rental	212.00
Total		7154.47

Invoice	Vendor	Cost
6000194556	LGH	2400.90
6000197963	LGH	2332.00
6000202681	LGH	1068.31
Total		5801.21

Invoice	Vendor	Cost
	Scotty's Potties	\$ 120.00
Total		\$ 120.00

DATE	Equipment	Hours
	Jay's Septic	600.00
Total		600.00

Invoice	Vendor	Cost
	Dunham's - (Wadders)	109.69
Total		109.69

Invoice	Vendor	Cost
	LGH - Manbasket Rental	
	weekly = \$550	550.00
Total		550.00

Invoice	Sub	Cost		
	DeCal Mechanical	\$ 11,277.00		
Total		\$ 11,277.00		

Invoice	Sub			Cost		
	Ross S	tructural Steel - Road Plate				
				\$	3,342.00	
Total				\$	3,342.00	

Invoice	Sub	Cost		
	Hobas Inspector	\$	1,000.00	
	Hobas Tech	\$	900.00	
Total		\$	1,900.00	

Invoice	Sub	Cost	
	Hobas travel per wee	\$	3,800.00
Total		\$	3,800.00

Invoice	Sub	Cos	Cost	
	Doetsch Crane	\$	2,667.00	
Total		\$	2,667.00	

Invoice	Sub	Cost	
	Handrail Crane	\$	2,667.00
Total		\$	2,667.00

Unit	Sub	Cost	Cost		
	Doetsch repair crew	\$	5,400.00		
	Doetsch standby crew	\$	2,800.00		
Total		\$	8,200.00		

Invoice	Sub	Со	st
	Hobas Material	\$	5,200.00
Total		\$	5,200.00
Invoice	Sub	Co	st
	Doetsch Layout	\$	6,200.00
Total		\$	6,200.00
Invoice	Sub	Co	st
	Ross Structural Steel -	Han	drail
		\$	130,170.00
Total		\$	130,170.00

Invoice	Sub	Cos	Cost	
	Christman - Landscaping			
		\$	17,772.00	
Total		\$	17,772.00	



March 15, 2022

Dave Pauline
Walsh Construction
3031 West Grand Blvd
Suite 640
Detroit MI 48202

Re: CS-9 Hobas repairs

Mr. Pauline,

Doetsch Environmental Services will provide necessary cleaning equipment to make safe entry and repair Hobas pipe as directed

- Entry coordination with OMIDD/MIDD/Metco
- Entry will be made into CS-9 via boom truck and man basket
- Pipe will be temporarily, partially bulkheaded to control water from gate.
- Resulting water will be pumped back over bulkhead
- Repair methods as outlined by Hobas
- Repair of grout ports may require additional acrylamide grouting of ports.

Pricing:

Per day price for men, pumps, bulkheads and ventilation: \$5,400 per day

Stand by price: \$2,800 per day

Repair materials and equipment as outlined by Hobas: \$5,200.00 lump sum

Acrylamide grout if required: \$22.00 per gallon Boom truck with operator: \$2,667.00 per day Manbasket: Price to be added by Walsh

Duration:

Estimated days: 10 based on repairs above the flowline and grout ports. Contingency: 5 days based on unknown condition under flowline

Optional preliminary investigation:

Close gate, ventilate, set sandbag wall and pump water over bulkhead to dewater work area. Use existing MH for access (no boom truck), dewater pipe and count and paint mark defects prior to repair operation: \$6,200 lump sum

Thank you for the opportunity to be of service,

Joe Schotthoefer

Joseph & Stoutof

Doetsch Environmental Services



ROSS STRUCTURAL STEEL, INC.

110 E. Robinwood Detroit, MI 48203

(313) 893-7877

February 24, 2022

Dave Pauline
Walsh Construction Co.
3031 West Grand Boulevard
Suite 640
Detroit, MI 48202

Ph: 313-456-6521 Fax: 313-873-6633

RE: Change Request 17

9445 OMID NE Sewage Pump Station

Dear Dave Pauline:

We are pleased to offer the following specifications and pricing to make the following changes:

CRX #17 - CS-9 FRP Replacement

Remove and dispose of all existing FRP handrail and FRP grating.

Furnish and install new FRP handrail and FRP grating.

Generate and submit shop drawings for new FRP system.

Note on the submittal that Due to unreasonable costs, the material will be modified as needed no field measurements will be done prior to fabrication. Additional pieces included to facilitate this method. If there is a continuous length of handrail that would be best not spliced, it will be ordered longer as the as-built condition of the concrete may be different than shown.

The intent is to allow access shared with the activity of the pipe liner repair as indicated in the schedule provided here. This access would then be provided for you.

The Ross team is to provide all personal safety items, including but not limited to, harnesses, personal gas monitors and standard PPE.

We have considered that our lead will spend 4 hours in LOTO training and then need to be able to lock out the system for flow control (in concert with other doing the same activity). This LOTO activity will delay the start of install about 2 hours.

Ross is to issue a shutdown request for the work.

Ross understands precipitation controls availability of the space, meaning we may be able to work there 3 days out of 5 in a week.

EXCLUSIONS:

- 1. Replacement of structural steel or anchors.
- 2. Shaft ventilation or Odor Control Monitoring.
- 3. Precast removal and reinstallation.
- 4. Bonds, Permits, Inspections.
- 5. Furnish or install temporary cover at end of each shift.
- 6. On-Site confined rescue team.
- 7. Site Security.
- 8. Temporary Railings.

ROSS STEEL

ROSS STRUCTURAL STEEL, INC.

110 E. Robinwood Detroit, MI 48203

(313) 893-7877

- 9. Owner Controlled Insurance Program.
- 10. Replacement of Manhole Rungs.
- 11. Electrical Power.

QUALIFICATIONS:

- 1. Due to information provided by FRP manufacturer, Fibergrate has informed us that shop drawings are 4-5 weeks after receipt of order, procurmenet is 6-7 weeks after shop drawing approval. Installation is approx 3 weeks. *Due to shortage in FRP resins, FRP procurement timing may vary at time of order.
- 2. Our erector, Titus Welding Company, agrees to carry worker's compensation and public liability insurance and to pay all taxes on labor and material furnished under this contract modification.

Sincerely,

Charles Buhagiar Ross Structural Steel Inc.



ROSS STRUCTURAL STEEL, INC.

110 E. Robinwood Detroit, MI 48203

(313) 893-7877

Change Request 17 Price Breakdown Continuation Sheet

Description: CRX #17 - CS-9 FRP Replacement

We are pleased to offer the following specifications and pricing to make the following changes:

Remove and dispose of all existing FRP handrail and FRP grating.

Furnish and install new FRP handrail and FRP grating.

Generate and submit shop drawings for new FRP system.

Note on the submittal that Due to unreasonable costs, the material will be modified as needed no field measurements will be done prior to fabrication. Additional pieces included to facilitate this method. If there is a continuous length of handrail that would be best not spliced, it will be ordered longer as the as-built condition of the concrete may be different than shown.

The intent is to allow access shared with the activity of the pipe liner repair as indicated in the schedule provided here. This access would then be provided for you.

The Ross team is to provide all personal safety items, including but not limited to, harnesses, personal gas monitors and standard PPE.

We have considered that our lead will spend 4 hours in LOTO training and then need to be able to lock out the system for flow control (in concert with other doing the same activity). This LOTO activity will delay the start of install about 2 hours.

Ross is to issue a shutdown request for the work.

Ross understands precipitation controls availability of the space, meaning we may be able to work there 3 days out of 5 in a week.

EXCLUSIONS:

- 1. Replacement of structural steel or anchors.
- 2. Shaft ventilation or Odor Control Monitoring.
- 3. Precast removal and reinstallation.
- 4. Bonds, Permits, Inspections.
- 5. Furnish or install temporary cover at end of each shift.
- 6. On-Site confined rescue team.
- 7. Site Security.
- 8. Temporary Railings.
- 9. Owner Controlled Insurance Program.
- 10. Replacement of Manhole Rungs.
- 11. Electrical Power.



ROSS STRUCTURAL STEEL, INC.

110 E. Robinwood Detroit, MI 48203

(313) 893-7877

QUALIFICATIONS:

- 1. Due to information provided by FRP manufacturer, Fibergrate has informed us that shop drawings are 4-5 weeks after receipt of order, procurmenet is 6-7 weeks after shop drawing approval. Installation is approx 3 weeks. *Due to shortage in FRP resins, FRP procurement timing may vary at time of order.
- 2. Our erector, Titus Welding Company, agrees to carry worker's compensation and public liability insurance and to pay all taxes on labor and material furnished under this contract modification.

Work performed by us:				
Description	Quantity	Unit	Unit Price	Price
Project Management	40.00	Hours	\$125.00	\$5,000.00
			Subtotal:	\$5,000.00
Work performed by subcontractors:				
Description	Quantity	Unit	Unit Price	Price
Erection (Titus Welding Co.)	1.00	lump sum	\$118,496.00	\$118,496.00
			Subtotal:	\$118,496.00
			Subtotal:	\$123,496.00
	Overhead/Profit			\$6,674.00
			Total:	\$130,170.00

February 11, 2022

Ross Structural Steel, Inc 110 E. Robinwood Rood Detroit, Michigan 48203

Attn: Charles L. Buhagiar

Re: CS-09 Fiberglass Platform Replacement

Mr. Buhagiar,

Thank you for inviting us to quote the replacement of the fiberglass reinforced plastic (FRP) platform within Control Structure No. 9. Our quote is based upon the information included in your email dated February 7, 2022 and includes:

- Remove and dispose of all existing FRP handrail and FRP grating.
- · Furnish and install new FRP handrail and FRP grating.
- Submit the shop drawing for the entire FRP system.
- Note on the submittal that "Due to unreasonable costs, the material will be modified as needed – no field measurements will be done prior to fabrication."
- The access will be shared with the activity of the pipe liner repair.
- All personal safety items, including but not limited to, harnesses, personal gas monitors and standard PPE.
- We have considered our lead will spend 4 hours in LOTO training and then need to be able to lock out the system for flow control (in concert with other doing the same activity). We understand this LOTO activity will delay the start of install about 2 hours.
- We understand the owner typically needs locks off by 4pm; and that weather may demand this occur earlier.
- We understand a shutdown request for the work will be necessary and will coordinate with RSS.
- We understand due to the nature of the work, precipitation controls availability of the space. This means we may only be able to work 3 days out of 5 in a week.

Lump Sum Price: \$118,496.00

Below, please also find our exclusions:

Replacement of structural steel or anchors
Shaft ventilation or Odor Control or monitoring
Precast removal and reinstallation
Bonds, Permits or Inspections

STRONGWELL

Furnish or install of temporary cover at end of each shift
On sit confined space rescue team
Site security
Temporary railing around shaft opening
Owner Controlled Insurance Program
Liquidated or consequential damages
Replacement of manhole rungs
Electrical power

We take exception to the schedule supplied with your February 7, 2022 email. The schedule provided is not consistent with the information received from the FRP manufacturer. Fibergrate has informed us shop drawings are estimated to arrive 4 to 5 weeks after receipt of an order; and procurement is 6 to 7 weeks after shop drawing approval. Installation is estimated to take 3 weeks. A duration is also typically allocated for shop drawing approval time.

Titus Welding Company agrees to carry worker's compensation and public liability insurance and to pay all taxes on material and labor furnished under this contract as required by federal laws and of the state in which this work is performed.

Feel free to contact us with any questions or comments. Thank you for the opportunity to be part of this project.

Respectfully Submitted,
TITUS WELDING COMPANY

Brian Pass

ACCEPTANCE

You are hereby authorized to furnish all material, equipment and labor to complete the work described in the above Proposal, for which the undersigned agrees to pay the amount stated in the same Proposal and per the terms thereof.

Date:	Ву:
	Of:



	_													
	me OMID NE Pump Station												Bulletin #	002
CCI Job #	206-076												Cost Code # :	000
PO#												Christm	an Constructors CI#:	30
Date:	2/25/2022			- 1	2	3	4			2		3	4	
CI # 030 E	xtra Seeding and Site Restoration			Labor	Material	Equipment	Sub.	Total	Total	Total	Total	Total	Total	
Date/Ticket#:	Descriptions .	Qty	Unit	Unit	Unit	Unit	Unit	Lobor	Mat./No Tax	Material	Equip./No Tax	Equipment	Subcontract	TOTAL
	Extra Work To Complete													
	Extra Work Re-grading, adding Topsoil, Seeding, Straw Blankets, Fertilizer, and Watering Site													
	Duration of work													
	l Carpenter Foreman 2 Days, I Operator I Day, 3 Laborers 2 Days													
	70													
	Equipment Used													
	I 333 John Deere Skidster. I Day duration. Spread Top-soil. Back blade and level tracks.													
-	,													
H	Carpenter General Foreman	16.00	mh	100.14				1.602.24						1,602.24
	Laborer	48.00	mh	65.99				3.167.52						3,167.52
	Operator	8.00	mh	98.19				785.52						785.52
	Seed Soil Erosion Blankets, Fertilizer, stakes and materials to complete.	1.00	ls	3,850.00	-			3,850.00						3,850.00
	Topsoil	6.00	Yards		38.99					233.94				233.94
	Skidster. 333 John Deere	1.00	Day		55.00	825.00				55.00		825.00		880.00
	Watering, Per Time needed. Typically 3 times a week for 2 weeks. 9 total times. No water on-site. Water truck brought in to supply water each time.	6.00	EA			850.00						5,100.00		5,100.00
	Material/Equipment Delivery and Pick-up charges	- 1	LS	-	-	650.00						650.00		650.00
								9,405,28		288.94		6,575,00		16,269.22
I	Subtotal Direct Cost (In Unit Prices) Sales Tax on Materials @ 6%	6.00%						9,405.28		17.34		6,575.00 394.50		
	Sales Tax on Materials (g) 6% Yard Deliberies Yard Deliberies	6.00%	trps	85.00	125.00	50.00				17.34		394.50		411.84
	Tard Democrats Dumpster, By CM	0	ea		350.00	30.00		-						
	Dumpter: by LP1 Insurances	0.00%	42	-	350.00		-	-		- :		-	-	-
-	Inturances Bond: 1%	0.00%												-
—	some - 1 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2	0.00%				-					l	-		-
—	Santry incruminaty (vs) Small Tools (v8)	0.00%				-								-
	General Superintendent	0.00%								-				
	Subtotal							9,405.28		306.28		6,969.50		\$ 16,681
—	SIDIOUSAL Labor Fee	15.0%				-		2,403.20		300.28	<u> </u>	0,707.30		J 10,001
	Lator rea Macrail/quipment	15.0%								45.94		1.045.43		1,091
	Fee on Sub-contracts	5.0%							-	13.71	<u> </u>	1,013.13		1,071
	Total this Change		\vdash							-	-			\$ 17,772
	rota tris Unange.									l				\$ 17,772



LAMINATION TRAINING VIDEO OUTLINE AND SCRIPT

- Intro
- What you need:
 - o PPE
 - Materials
 - Tools/supplies
- Surface Preparation
 - Making Putty Filler
 - Initial Grinding
 - Catalyzing Putty/Filling gaps
 - Touch-up grinding and cleaning
- Lamination
 - Catalyzing Resin in tub
 - Wetting out lamination 'sandwiches'
 - Applying and rolling out lamination 'sandwiches'
- Closing

INTRODUCTION

This video will cover the general lamination process that HOBAS Pipe USA uses for a variety of things, including fitting fabrication and field repairs. Specific lamination specifications detailing exactly what size, how much bond area, and how thick the lamination should be should be for any particular field application should be requested from HOBAS Pipe USA Field Service.

WHAT YOU NEED

This section of the video will cover PPE, materials, and supplies you will need for field laminations. These lists can be found at www.hobaspipe.com/downloads.

PPE

- Disposable coveralls typically Tyvek material, but if Tyvek is not available, painter's coveralls can be used. Integrated hoods into the coverall help keep the neck clean, but if those aren't available, 'spray socks' or rags can be used to protect the neck.
- Work gloves can be used for setup and grinding. Standard leather work gloves
- Rubber gloves will be use for chemical handling portions of the process. Should be thick
 enough to not deteriorate with the chemicals. Keep in mind, the thicker the glove, the faster
 your hand will fatigue manipulating things with it on.
- Eye protection safety glasses at a minimum. Goggles are ok as long as they don't fog up. Face shield during grinding and overhead work can provide additional protection to the eye and face areas.
- Respirator half face cartridge respirator is what we use at our facility. Quality dust mask or full
 face respirators are acceptable as well. Note that half face and full face respirator fitting should
 be certified.

Materials

- Resin Polyester or Vinylester, depending on what is used for the pipe on your job, but mostly Polyester. We have information on acceptable resin suppliers please contact us for details.
- Catalyst typically MEKP, but others are sometimes provided. Please contact us for details.
- Fiberglass for simplicity in the field, we use 1.5 oz/sq.ft chopped strand mat for all of our field lamination work. This typically comes in wide rolls from a supplier. If they can cut it to width, the most useful widths we use are 8", 10", 12", and 14". Wider than 14" can be difficult to work with due to the size. Most of what we use is 10" wide material for most joints that need lamination work. We typically cut 24" long sheets, which results in a size that is manageable inside most pipe sizes. For 30" pipes, shorter sheets are commonly used.
- Fumed Silica Powder Typical brands are Aerosil and Cabosil. This is extremely lightweight powder for mixing with resin to make the filler putty that will fill in any gaps that need to be filled or to ramp out any abrupt steps across the area to be laminated.
- Acetone will be used to clean the bond area and to clean tools like rollers and putty knives
- Rags for various purposes

Tools and Supplies

- Grinder 4" or 7" can be used. We use corded grinders most often, but have some cordless grinders as well. Note that cordless grinder batteries last a limited amount of time grinding on pipe, so they are better for smaller pipes.
- Grinding disks we use 16-grit semi-flex abrasive discs. These are not generally available from local home improvement or hardware stores. Grainger should have an option or we can send some to you.
- Mud drill with long mixing bit
- 5-gallon buckets several. These will be used for lowering and transporting tools and materials back and forth in the pipe
- Tubs something similar to this. These can typically be found at local home improvement stores or Walmart. This is for mixing and holding resin. Should be deep enough to cover a typical paint roller.
- Grooved rollers these will be used to roll the air out of the lamination and roll the lamination tight to the prepared surface. These should be 3"-4" wide. There are 2 main types barrel rollers are curved and are used inside the pipe on the ID and straight rollers are used on the OD of the pipe.
- Paint roller frame and covers the same 9" wide roller frames you can find at nearly any store are what we use. Roller covers should be 3/8" nap.
- Putty knives 3" and 4" wide putty knives. Other sizes might be necessary depending on what you are doing.
- Plywood this will be used to make a flat 'wet-out' workspace in the pipe. These are typically 2' deep and the width will depend on the pipe size. The corners are sometimes cut off at 45-degree angles as shown here to help maneuver the board into place inside the pipe.

SURFACE PREPARATION

This section of the video will cover all the steps needed to prepare the surface for applying the lamination. This included mixing the resin and fumed silica to make filler putty, grinding the surface of the pipe, catalyzing the filler putty and filling gaps with it, and final touch-up grinding and cleaning.

Making Filler Putty

NOTE: This material is optional. Some laminations have no gap or step to address and do not need any filler. Also, other material can be used as long as it dries completely can provides a smooth, firm surface over which the lamination can be rolled (overhead gap filling is the most challenging part). Alternative materials that have been used in the past include bondo, quickcrete, cement water plug, grout, drywall mud compound, and foam (florist foam can work – some foam dissolves with resin contact). Of all these materials, resin filler putty 'stick' in overhead gaps the best.

The filler putty we mix here will be used to fill in gaps and smooth out any steps in the surface that needs to be laminated. For this you will need PPE, resin, fumed silica, a clean bucket, mud drill, and mixing bit.

- 1. Put about 2-2.5 gallons of resin into a clean, empty bucket. Do not use more than 2.5 gallons of resin.
- 2. Fill most of the remaining space in the bucket with fumed silica.
- 3. Use the mud drill and mixing bit. Insert the mixing portion of the bit into the resin at the bottom half of the bucket and start at slow speed. If you use too high of a speed, you'll lose some of the very light powder from the top of the bucket. Mix until all fumed silica is mixed well into the resin.
- 4. Refill most of the remaining space in the bucket with more fumed silica and continue mixing per step #3
- 5. Repeat step #4 until it becomes the consistency of thick mashed potatoes. If this material is not thick enough, it will not stay in place overhead.
- 6. Cover this bucket and set aside until it is needed.

Initial Grinding of the Pipe Surface

The lamination bonds best to a fiberglass surface. Neither the ID of the pipe nor the OD of the pipe are fiberglass surfaces – both have a protective layer at the surface. These surfaces should be ground to expose the glass layer of the pipe. Note that the glass layer should not be ground into, removing part of the glass layer of the pipe. For this step you will need PPE, grinder, and grinding disc(s).

Grind the surface of the pipe until you start seeing fibers on the surface. When you start seeing fibers on the ground surface, stop grinding that area. Note that the ID liner resin will grind very easily with the aggressive grinding discs. Keep your grinder moving while pressure is applied and take care to avoid grinding into the glass layer of the pipe.

Grind approximately ½"-1" beyond the required bond area. For a joint seal lamination this is about 5" wide on each pipe end. If your lamination requires more bond, grind wider as necessary. Grind the entire area that will be bonded to lamination.

Catalyzing Putty and Filling Gaps

For this step you will need PPE, tub or cardboard sheet, putty knife, the resin filler putty we made earlier, and catalyst.

- 1. Take about ½ gallon of your filler putty and place it in a dishpan or on a large piece of cardboard.
- 2. Make an indention at the top of the putty big enough to contain the amount of catalyst you need for the amount of putty you have. (consult catalyst mix ratios for your specific resin and catalyst from the supplier you purchased them from). Some resins will slightly turn colors as they are catalyzed, helping you identify when catalyst is mixed uniformly
- 3. Using a putty knife, mix the catalyst into the putty. Mix it well so the catalyst is evenly distributed throughout the putty. Depending on mixing ratio, environment temperature, and temperature of the resin material, working time after mixing is typically 10-40 minutes.
- 4. Using a putty knife, fill in the required areas. Any gaps ¼" and larger should be filled and any steps 1/8" and larger should be ramped out to a 4:1 ratio. The finished surface should be smooth.

Touch-up Grinding and Surface Cleaning

For this step you will need PPE, grinder, grinding disc, clean rags, and acetone.

- 1. Once the placed putty is cured, lightly grind off any putty that is on the bond area of the pipe, ensuring that all bonding surfaces are properly ground and free of any contaminants.
- 2. Ensure all filled and ramped areas are smooth and ready for the lamination.
- 3. Take a clean rag with acetone on it and wipe off any grinding dust or any other contaminants on the lamination surface.
- 4. Ensure entire lamination bonding surfaces and all filled/ramped areas are completely dry and all putty filler is cured and cooled (no longer warm to the touch) this is critical

LAMINATION

This section of the video will cover the laminating process including catalyzing the resin, wetting out lamination 'sandwiches', and applying and rolling out of the lamination 'sandwiches'. These steps should be done immediately one after another – once the resin is catalyzed, you typically have 10-40 minutes of work time, similar to the resin filler putty. Set up your plywood work table at this time with your fiberglass sheets and resin tub, leaving a cleared area of about 12" deep X 24" wide. Make sure all the items necessary for all lamination steps are easily and quickly accessible. Together, this is best done as a 2-person process – one worker mixing resin and wetting out 'sandwiches' and another worker taking the sandwiches that are wet out and applying them and rolling them out while the wet-out worker starts on the next 'sandwich'

Catalyzing Resin

For this step you will need PPE, resin, catalyst, clean tub, and either a paint roller frame (WITHOUT a cover) or a grooved roller (to stir with). Before this step is started, make sure you fully understand the entire lamination portion of the process and are prepared.

1. Fill the tub about ½ full of resin.

- 2. Add the correct amount of catalyst for the amount of resin you have in the tub. (consult catalyst mix ratios for your specific resin and catalyst from the supplier you purchased them from)
- 3. With a paint roller frame (WITHOUT a cover) or a grooved roller, stir the catalyst into the resin. Some resins will turn a slightly different color or shade as it becomes catalyzed.

Wetting out Lamination 'Sandwiches'

For this step you will need PPE, fiberglass sheets (cut to proper size), catalyzed resin (in tub), paint roller frame and cover, and plywood (with clean surface).

- 1. Install clean roller cover onto the roller frame (if it isn't already installed)
- Dip the paint roller frame (with cover) into the catalyzed resin and paint the portion of board over which you will be wetting out sandwiches. This is roughly a 12" deep by 24" wide area, depending on how wide/long the sheets you will be using are.
- 3. Place one sheet of fiberglass onto the painted surface of the plywood board. Dip the paint roller/cover into the catalyzed resin and paint over the fiberglass sheet.
- 4. Repeat step #3 until 5 layers are wet out together on the board.

Applying and Rolling out Lamination 'Sandwiches'

For this step you will need PPE, the wet-out 'sandwich' from the plywood, and a grooved roller. For this step, the prepared surface MUST be completely clean and dry and free of contaminants.

- 1. With the paint roller and cover, paint the area for this set of sandwiches
- 2. With the frame edge of either the paint roller or grooved roller, peel up a corner of the sandwich and remove the sandwich from the plywood.
- 3. Apply the wet-out sandwich to the prepared and painted area. If overhead, the paint roller sometimes is the most effective tool to get the sandwich to initially stay in place enough to where you can start rolling it out. Make sure the intended minimum bond width is achieved on each side of the joint/seam/damage/etc.
- 4. With a grooved roller, roll out all air and bubbles from the placed sandwich. Too much pressure will squeegee out the resin and too little pressure will be insufficient to remove the air.
- 5. Repeat steps #2 #4 to cover all the required lamination bonding surface for this sandwich layer. Each subsequent sandwich should overlap a minimum of 1" at the end/edge.

a. And extend 1" beyond last sandwich.

- 6. If this sandwich later finished all of your lamination needs, paint any remaining dry overgrind areas with catalyzed resin and once cured, consider your lamination complete.
- 7. If you require more sandwich layers, allow the current layer to cure and cool.
- 8. Once cured, lightly grind the lamination surface and clean per steps #3 and #4 in the "Touch-up Grinding and Surface Cleaning" portion.
- 9. Repeat previous steps until all sandwich layers are applied and any remaining dry overgrind areas are painted.

Once lamination is cured and cooled, it should be consistently hard to the touch and uniform in color and appearance.

Closing

This concludes our video for general lamination procedures for HOBAS pipes. If you have any questions or need further information our website is www.hobaspipe.com or give us a call at 281-821-2200.

HOBAS PIPE USA

1413 Richey Road Houston, TX 77073



Tel.: 281 821-2200 **HOBAS**

info@hobaspipe.com www.hobaspipe.com

General Reinforcement Lamination Procedures and Lamination Secifications for Joint Seals, Minor Liner Damage, and Damaged Grout Fittings

Materials:

Polyester resin with a 2.4% to 4% minimum ultimate flexural elongation to break suitable for hand lay-up work.

Curing agent (catalyst) for above resin(s).

1.5 oz./sq. ft. chopped strand mat (M), cut to specified width.

Fumed silica to make gap filler resin putty.

General Procedure:

Assure that surface area of pipe to be bonded is completely dry.

Thoroughly clean area to be bonded to remove all dust, grease or other contaminating materials. Remove any items protruding inward past the original ID surface (this includes grout fitting portions protruding past the ID, if possible). Grind or sandblast through the pure resin interior surface or exterior sand layer to the glass layer.

Surfaces should again be cleaned to remove all dust from the area to be bonded.

Fill gaps with resin putty (properly catalyzed) and allow to cool. Any filler material can be used here as long as it completely dries and provides a solid backing on which the lamination can be rolled out.

Assure surface to be bonded is properly ground (full area), clean and dry.

Build ramps with a 4:1 slope or flatter to provide a smooth transition across surfaces that are misaligned more than 0.5".

Apply five (5) ply lay-up "sandwich" to cover the area to be reinforced or of the specified width, 360 degrees around and centered over the pipes to be connected. (Note: Fabrics must be wet-out with properly catalyzed resin.) Roll out tight to the surface, removing all air, etc. prior to gel of the resin. Overlap lay-up segments minimum 1".

Allow lay-up to cool until it is no longer hot to the touch. Repeat previous step until all 5-ply "sandwich" lay-ups have been applied. Note: each successive "sandwich" must be



extend at least 1" further in all directions so the edges of the fabrication have a natural 4:1 taper. Also, stagger lay-up segments so overlaps do not occur at the same locations.

After all lay-ups have been applied, paint all ground surfaces (not covered by lay-up) with catalyzed resin.

Allow lay-ups to cure at least 24 hours (preferably 48 hours) prior to exposure to water or new stresses.

General Criteria:

All lay-ups shall begin and end with a mat ply.

All structural lay-ups shall be constructed with alternating mat-woven roving composition.

All lay-ups must be bonded to a glass layer in the pipe.

Joint Seal Lay-up Specification:

Following lay-ups are for an internal seal across an undamaged joint with full structural integrity that will <u>not</u> have future differential movements:

5 plies of all mat (or alternating M-W) with a width of 8" plus the largest gap width (or plus any ramping due to misalignment), 360 degrees around, centered across the joint or area to be sealed.

Scrape/Gouge/Scuff Repair Specification:

The following applies to minor liner damage (gouges, scratches or scuffs) that are deeper than the liner depth (0.040" to 0.080") or sand exterior depth (on OD) in non-pressure service piping where there is NO pipe wall fracturing in the affected area:

For damage with depth of ~1/8" or less: Sand smooth (sanding disc on grinder works well) the affected area and coat with epoxy.

For damage deeper than ~1/8": Grind the adjacent area to the damage at least 4" past the edge of the damage in all directions. Replace the gouge/scuff depth with a lamination over the ground area. Lamination thickness should match the damage depth (each ply of mat ~0.040" thickness, so ~1/2" damage depth should receive ~12 ply lamination). For anything deeper than $\frac{1}{2}$ " you should contact HOBAS for further assessment.



Damaged Grout Fitting Repair

If possible, remove the portion of the grout fitting protruding past the original pipe ID. Stop any leak and follow the general procedure, using the following lamination specification:

1st "sandwich" - 5 plies (all mat, or alternating M-W) with an area of the

grout fitting hole, plus at least 4" in each direction.

2nd "sandwich" - 5 plies (all mat, or alternating M-W) that extends 1" past

the 1st "sandwich" in each direction.

If the grout fitting flange cannot be removed, flatten the area as much as possible with grinding and finish flattening and ramping with resin putty. Then, following the general procedure, using the following lamination specification:

1st "sandwich" - 5 plies (all mat, or alternating M-W) with an area of the

grout fitting and surrounding ramp, plus at least 4" in each

direction.


2nd "sandwich" - 5 plies (all mat, or alternating M-W) that extends 1" past

the 1st "sandwich" in each direction.

3rd "sandwich" - 5 plies (all mat, or alternating M-W) that extends 1" past

the 2nd "sandwich" in each direction.

COSTS to DATE



Larmamie Invoice #60066824 (9/10 Rental - Crane #2)

Laramie Invoice #60066957 (10/14 Rental - Crane #2)

SUBS TOTAL: SUBS MARK-UP:

SUBTOTAL AMOUNT: \$

SUBS TOTAL:

\$

\$

\$

\$

5%

\$ 11,277 \$ 11,277

1,264

6,017

3,997

TOTAL AMOUNT \$ 11,277

1,699

2,108

3,807

190



DE-CAL, INC.

De-Cal, Inc. Job Number: 120022
Customer Change #: Pending

Issue/RFI/Transmittal Number:

De-Cal Quote Number:

Date:

Walsh Request
120022-9
9/1/2021

Rentals (2021)

Description	Quantity	Unit	Pric	e / Unit	Subtotal
De-Cal Boom Truck - W/ Operator on (9/1) - 20T @ \$232.50 / 1hour DBLT @ \$285.00	1	Total	\$	750	\$ 750
De-Cal Boom Truck - W/ Operator on (9/10) - 8ST @ \$155	1	Total	\$	1,240	\$ 1,240
De-Cal Boom Truck - W/Operator on (10/14) - 8ST @ \$155	1	Total	\$	1,240	\$ 1,240
Man-Basket 2 Man - \$200 per day	3	Days	\$	200	\$ 600
4 Gas Meters - \$100.00 per day	3	Days	\$	100	\$ 300
Breathing Air Survivor Packs (QTY: 4) - \$40 ea / \$160 per day	3	Days	\$	160	\$ 480
			Total	Rentals:	\$ 4,610



DE-CAL, INC. MECHANICAL CONTRACTORS

24659 Schoenherr, Warren, MI 48089 Phone: (586) 754-4370 • Fax: (586) 754-4371

LABOR AND MATERIAL VOUCHER

BILL TO: WALSH CONT.		ם	ATE: 9/1/207	-1_
CUSTOMER'S ORDER NO. 120022		D	E-CAL P.O. # 170	022
DESCRIPTION OF WORK DONE: EMERGENC	y CALL IN	Fon	MISSING LID	INCIDENT

HILLE	NAME				D.T.	MATERIAL			UNIT	SP	RICE	T	OTAL
PFF	THEUOR JONCE	,		2	1								
PF	RILEY Mc CINT	OSH		2	1								
PL	THEUDA JOYCE RILEY MCCINT LUKE BADKE	= 1		2	1								
OP	Nonn BusH			2	1								
					L.								
					 								
			\vdash		 								
			\vdash		-					-			
					 					-			
			-		+					_			
			$\perp \perp$	-	<u></u>					+			
	NTRACTORS (additional work	k orders atta	sched)	AMC	TMUC							-	
De	CAL CRANE.												
						NA.	ARK	IID %					·
SUBC	ONTRACTOR SUB TO	ΤΔΙ						-UP %					
	ONTRACTOR SUB TO						SUB	OTAL					
SUBC	ONTRACTOR FEE	TAL %					SUB						
SUBC	ONTRACTOR FEE	%	PRICE	Tr	OTAL	TOTAL	6% N	OTAL II TAX	2 OF	FICE II	SEC	ONI V	
SUBCO SUB C EQUIP	ONTRACTOR FEE ONTRACTOR TOTAL MENT/TOOLS	% HRS.	PRICE	T	OTAL	TOTAL	6% N	OTAL II TAX	AND DESCRIPTION	FICE U	Name and Address of the Owner, where	Name and Address of the Owner, where the Owner, which is the Owner, where the Owner, which is the Own	TOTAL
SUBCO SUB C EQUIP	ONTRACTOR FEE ONTRACTOR TOTAL MENT/TOOLS ON TRUCK	#RS.	PRICE	TO	OTAL	TOTAL SUMM	6% N	OTAL II TAX	AND DESCRIPTION	THE RESERVE OF THE PERSON NAMED IN	Name and Address of the Owner, where	DNLY	TOTAL
SUBCO SUB C EQUIP BO	ONTRACTOR FEE ONTRACTOR TOTAL MENT/TOOLS ON TRUCK N BASKET	HRS.	PRICE	_ To	OTAL	TOTAL SUMP LABOR FOREMAN	6% N	OTAL II TAX	AND DESCRIPTION	THE RESERVE OF THE PERSON NAMED IN	Name and Address of the Owner, where	Name and Address of the Owner, where the Owner, which is the Owner, where the Owner, which is the Own	TOTAL
SUBCO SUB C EQUIP Bo MA	ONTRACTOR FEE ONTRACTOR TOTAL MENT/TOOLS ON TRUCK N BASKET H GAS METERS	HRS.	PRICE	TO	OTAL	TOTAL SUMI LABOR FOREMAN PLUMBER	6% N	OTAL II TAX	AND DESCRIPTION	THE RESERVE OF THE PERSON NAMED IN	Name and Address of the Owner, where	Name and Address of the Owner, where the Owner, which is the Owner, where the Owner, which is the Own	TOTAL
SUBCO SUB C EQUIP MA (3)	ONTRACTOR FEE ONTRACTOR TOTAL MENTITOOLS ON TRUCK N BASKET H GAS METERS ON IN ESCAPE PACKS	HRS.	PRICE	: TO	OTAL	TOTAL SUMI LABOR FOREMAN PLUMBER PIPEFITTER	6% N	OTAL II TAX	AND DESCRIPTION	THE RESERVE OF THE PERSON NAMED IN	Name and Address of the Owner, where	Name and Address of the Owner, where the Owner, which is the Owner, where the Owner, which is the Own	TOTAL
SUBCO SUB C EQUIP MA (3)	ONTRACTOR FEE ONTRACTOR TOTAL MENT/TOOLS O'M TRUCK N BASKET H GAS METERS ONIN ESCAPE PACKS RADIOS	#RS. 3 3	PRICE	: TO	OTAL	TOTAL SUMM LABOR FOREMAN PLUMBER PIPEFITTER WELDER	6% N	OTAL II TAX	AND DESCRIPTION	THE RESERVE OF THE PERSON NAMED IN	Name and Address of the Owner, where	Name and Address of the Owner, where the Owner, which is the Owner, where the Owner, which is the Own	TOTAL
SUBCO SUB C EQUIP MA (3)	ONTRACTOR FEE ONTRACTOR TOTAL MENTITOOLS ON TRUCK N BASKET H GAS METERS ON IN ESCAPE PACKS	% HRS. 3 3 3	PRICE	: T(OTAL	TOTAL SUMI LABOR FOREMAN PLUMBER PIPEFITTER WELDER OPERATOR	6% N	OTAL II TAX	AND DESCRIPTION	THE RESERVE OF THE PERSON NAMED IN	Name and Address of the Owner, where	Name and Address of the Owner, where the Owner, which is the Owner, where the Owner, which is the Own	TOTAL
SUBCO SUB C EQUIP MA (3)	ONTRACTOR FEE ONTRACTOR TOTAL MENT/TOOLS O'M TRUCK N BASKET H GAS METERS ONIN ESCAPE PACKS RADIOS	% HRS. 3 3 3	PRICE	E T(OTAL	TOTAL SUMM LABOR FOREMAN PLUMBER PIPEFITTER WELDER	6% N	OTAL II TAX	AND DESCRIPTION	THE RESERVE OF THE PERSON NAMED IN	Name and Address of the Owner, where	Name and Address of the Owner, where the Owner, which is the Owner, where the Owner, which is the Own	TOTAL
SUBCO SUB C EQUIP MA (3)	ONTRACTOR FEE ONTRACTOR TOTAL MENT/TOOLS O'M TRUCK N BASKET H GAS METERS ONIN ESCAPE PACKS RADIOS	% HRS. 3 3 3	PRICE	E TO	OTAL	TOTAL SUMI LABOR FOREMAN PLUMBER PIPEFITTER WELDER OPERATOR	6% N	OTAL II TAX	AND DESCRIPTION	THE RESERVE OF THE PERSON NAMED IN	Name and Address of the Owner, where	Name and Address of the Owner, where the Owner, which is the Owner, where the Owner, which is the Own	TOTAL
SUBCO SUB C EQUIP MA (3) (3) (3) (3) (3) (3) (3) (3) (3) (3)	ONTRACTOR FEE ONTRACTOR TOTAL MENT/TOOLS O'M TRUCK N BASKET H GAS METERS ONIN ESCAPE PACKS RADIOS	% HRS. 3 3 3		E T(OTAL	TOTAL SUMI LABOR FOREMAN PLUMBER PIPEFITTER WELDER OPERATOR SUB CONTRACTOR	6% N	OTAL II TAX	AND DESCRIPTION	THE RESERVE OF THE PERSON NAMED IN	Name and Address of the Owner, where	Name and Address of the Owner, where the Owner, which is the Owner, where the Owner, which is the Own	TOTAL

Don't Estew

WORK AUTHORIZED BY



DE-CAL, INC. MECHANICAL CONTRACTORS

24659 Schoenherr, Warren, MI 48089 Phone: (586) 754-4370 • Fax: (586) 754-4371

LABOR AND MATERIAL VOUCHER

BILL TO: WALSH	LL TO: WALSH CONT.						DATE: 9/10/2/.						
CUSTOMER'S ORDER NO. DESCRIPTION OF WORK DO		ON	110	c59	51	DE-C							
TITLE NAME		s.T. O.	T. D.T.	MATERIAL			UNIT	S P	RICE	1	OTAL		
SUB CONTRACTORS (additional wo	De S	MOUNT	et in its			,							
			Aller of the second of the sec	N	IARK	-UP %							
SUB CONTRACTOR SUB TO		<u> </u>		<u> </u>		TOTAL							
SUBCONTRACTOR FEE	%				6% N	AI TAX							
SUB CONTRACTOR TOTAL EQUIPMENT/TOOLS	HRS.	PRICE	TOTAL	TOTAL	1 4 A D	, FO	205		05.6	N 11 N/			
EQUIPMENT/TOOLS	Inks.	PRICE	TOTAL	LABOR	THE PERSON NAMED IN	Y - FOI	desirated by the party lives	STATE STATE STATE	NAME OF TAXABLE PARTY.	RATE	TOTAL		
	<u> </u>			FOREMAN	3.1.	IVATE	0.1.	IVAIE	<i>U</i> . 1.	TOATE	TOTAL		
				PLUMBER									
,				PIPEFITTER									
				WELDER									
				OPERATOR									
				SUB CONTRACTOR									
				EQUIPMENT									
EQUIPMENT/TOOL FEE %		%		MATERIAL									
TOTAL		N		TOTAL									



Laramie Enterprises, Inc 48400 West Road Wixom, MI 48393 (248) 313-5800 Ph. (248) 313-5818 Fax

> De-cal Inc. 24659 Schoenherr Road Warren, MI 48089

Invoice

60066824

Invoice Date:

Monday, September 13, 2021

Customer:

DECA0001 M-6008979

Job No : Salesperson:

Al Livernois

Ordered By:

Ken Roots Jr

1

Job Site:

OMID Sanitary Line Gate Install

12601 10 Mile Road

Warren, MI

		Terms Net 30) Days								
Customer P.O. No: 120022 Work Performed: HT-40-01 / 30 Ton Boom Truck Hourly Rental											
Date	Description Unit No	Qty Unit Meas	Rate	3	Extension						
9/10/2021	Machine Travel to Job	0.75 Hours	\$224.00		\$168.00						
	30 Ton Hydraulic Boom HT-40-01 Truck Hourly Rental	5.75 Hours	\$224.00		\$1,288.00						
	Machine Travel from Job	0.75 Hours	\$224.00		\$168.00						
	Operator Time	0.75 Hours	\$101.00		\$75.75						

Total Invoice:

\$1,699.75



DE-CAL, INC

DE-CAL, INC. MECHANICAL CONTRACTORS

24659 Schoenherr, Warren, MI 48089 Phone: (586) 754-4370 • Fax: (586) 754-4371

LABOR AND MATERIAL VOUCHER

BILL TO: WALSH	DATE: 10-14-2021											
CUSTOMER'S ORDER NO. DESCRIPTION OF WORK DON	VE: IN	STA	<u>u</u>		HYD, CYLE	- N I			-		155	
WITH CONFINE.				ransenia)								
TITLE NAME		S.T.	.T. D	.T.	MATERIAL			UNIT	SP	RICE	T	OTAL
PL J KREMAELM	ž R	8	,5									
PLW S SUESSE		8						-				
SF ZSMITH		4							_			
									-			
		++	-+						+		+	
											+	
		† †									\neg	
	-											
SUB CONTRACTORS (additional wor	k orders atta	acred)	AMOU	NT								
		<u> </u>							-			
					N	IARK	-UP %					
SUB CONTRACTOR SUB TO	TAL	†					TOTAL					
SUBCONTRACTOR FEE	%	İ			 		AI TAX					
SUB CONTRACTOR TOTAL		İ			TOTAL							
EQUIPMENT/TOOLS	HRS.	PRICE	TOT	ΓAL	SUMI	MAR	Y – FOI	R OF	FICE U	SE C	NLY	
BOOM TRUCK WOPERATOR	9		1		LABOR	S.T.	RATE	O.T.	RATE	D.T.	RATE	TOTAL
BOOM TRUCK W/OPERATOR	210				FOREMAN							
4 RADIO'S	8				PLUMBER							
MAN BASKET	8				PIPEFITTER							
3 AIR MONITIR	8				WELDER							
2-25 RETRACTABLE	8		-		OPERATOR							
BARACADEING			+		SUB CONTRACTOR							
CAPITAL YOUL /WADERS			+		FOLUDIATIO							
2-1/2 TON COMBAING		L	6		EQUIPMENT							
TOTAL	JIPMENT/TOOL FEE %				MATERIAL							
I VIAL					1.0174							-



Laramie Enterprises, Inc 48400 West Road Wixom, MI 48393 (248) 313-5800 Ph. (248) 313-5818 Fax

De-cal Inc. 24659 Schoenherr Road Warren, MI 48089

Invoice 60066957

Invoice Date: Customer: Job No: Monday, October 18, 2021 DECA0001

Salesperson: M-6009084

Ordered By: Ken Roots Jr Al Livernois

Job Site:
OMID Sanitary Line Gate Install
12601 10 Mile Road Warren, MI

Terms: Net 30 Days

Customer P.O. No: 120022
Work Performed: HS-30-01/30 Ton Boom Truck Hourly Rental

					10/14/2021	Date
RADIOS	Misc	Operator Overtime	Machine Travel from Job	30 Ton Hydraulic Boom Truck Hourly Rental	Machine Travel to Job	Description
			0		HS-30-01	Unit No
	1.00 Total	1.00 Hours	1.00 Hours	7.00 Hours	1.00 Hours	Qty Unit Meas
	\$25.00	\$67.00	\$224.00	\$224.00	\$224.00	Rate
	\$25.00	\$67.00	\$224.00	\$1,568.00	\$224.00	Extension

Total Invoice:

\$2,108.00



ROSS STRUCTURAL STEEL, INC.

110 E. Robinwood Detroit, MI 48203

(313) 893-7877

September 03, 2021

Dave Pauline
Walsh Construction Co.
3031 West Grand Boulevard
Suite 640
Detroit, MI 48202

Ph: 313-456-6521 Fax: 313-873-6633

RE: Change Request 13

9445 OMID NE Sewage Pump Station

Dear Dave Pauline:

We are pleased to offer the following specifications and pricing to make the following changes:

CRX #13 - CS #9 Cap Plate

Provide detailing, material, fabrication and delivery of (1 Ea) 6'x8'x1/2" steel plate, fastening and rigging hardware for temporary installation by others at "CS #9" (10 Mile and Hoover), per Walsh request on 9/2 and delivery by 9/3.

Please refer to attached sheet for details. If you have any questions, please contact me at (313) 893-7877.

Sincerely,

Charles Buhagiar Ross Structural Steel Inc.



ROSS STRUCTURAL STEEL, INC.

110 E. Robinwood Detroit, MI 48203

(313) 893-7877

Change Request 13 Price Breakdown Continuation Sheet

Description: CRX #13 - CS #9 Cap Plate

We are pleased to offer the following specifications and pricing to make the following changes:

Provide detailing, material, fabrication and delivery of (1 Ea) 6'x8'x1/2" steel plate, fastening and rigging hardware for temporary installation by others at "CS #9" (10 Mile and Hoover), per Walsh request on 9/2 and delivery by 9/3.

Vork performed by us:				
Description	Quantity	Unit	Unit Price	Price
Ross Shop Labor	8.00	Hours	\$64.60	\$516.80
Ross Engineering Labor	2.00	Hours	\$60.00	\$120.00
Freight	2.00	Hours	\$102.27	\$204.54
Material "Steel"	1,071.00	Pounds	\$1.62	\$1,735.00
Manufacturing Supplies	0.50	tons	\$45.00	\$24.1
Misc Purchases				\$190.0
			Subtotal:	\$2,790.4
			Subtotal:	\$2,790.4
	Tax on Material & Supplies			\$116.9
	Overhead/Profit			\$434.6
			Total:	\$3,342.0

TIME and MATERIAL DAILY REPORT



OMID Emergency **JOB 220008** response to Lids Search for lids, road Anchoring road Description: falling in the plate delivered plate interceptor **Cost Code:** 8/30/2021 8/31/2021 9/1/2021 9/2/2021 9/3/2021 9/4/2021 Wednesday Monday Tuesday Thursday Friday Saturday **TOTALS** Emp# Craft RT ОТ RT ОТ RT ОТ RT ОТ RT ОТ RT ОТ RT ОТ Name 135582 Dave Pauline Project Manager 8 8 16 0 128120 Ankur Patel Superintendent 8 8 4 20 0 159161 8 Mike Graziano Project Engineer 8 16 0 159088 Christian Biolchini Project Engineer 2 6 8 4 10 10 19613 Michael Matyaszek Laborer FM 0 0 0 0 0 0 0 0 0 0 **TOTALS** Equipment 1 Single Man Cage 1 Generator 1 Supply Air Fan

TIME and MATERIAL DAILY REPORT



OMID JOB 220008																
Cost Code	9 :	Description:														
			9/6/	2021	9/7/	2021	9/8/	2021	9/9/	2021	9/10	/2021	9/11/	/2021		
-	-		Mo	nday	Tue	sday	Wedr	esday	Thur	rsday	Fri	day	Satu	ırday	TO1	TALS
Emp#	Name	Craft	RT	ОТ	RT	ОТ	RT	ОТ	RT	ОТ	RT	ОТ	RT	ОТ	RT	ОТ
135582	Dave Pauline	Project Manager									8				8	0
128120	Ankur Patel	Superintendent									8				8	0
159161	Mike Graziano	Project Engineer									8				8	0
159088	Christian Biolchini	Project Engineer									8				8	0
19613	Michael Matyaszek	Laborer FM									8				8	0
															0	0
															0	0
															0	0
															0	0
			_													
	Equipment														TOT	ΓALS
	1 Single Man Cage															
	1 Generator															
	1 Supply Air Fan															
	2 4-Gas Personal Gas Mon	nitor														

TIME and MATERIAL DAILY REPORT



OMID Inspection of the **JOB 220008** liner with OMID, Description: NTH, Hobas, Ins. Rep. Cost Code: 11/8/2021 11/9/2021 11/10/2021 11/11/2021 11/12/2021 11/13/2021 Monday Tuesday Wednesday Thursday Friday Saturday **TOTALS** RT ОТ RT ОТ RT ОТ RT ОТ RT ОТ RT ОТ RT ОТ Emp# Name Craft 135582 Dave Pauline Project Manager 0 128120 Ankur Patel Superintendent 8 8 0 159161 Mike Graziano Project Engineer 8 8 0 159088 Christian Biolchini Project Engineer 6 6 0 19613 Michael Matyaszek Laborer FM 8 8 0 0 0 0 0 0 0 0 0 **TOTALS** Equipment 1 Single Man Cage 1 Generator 1 Supply Air Fan 2 4-Gas Personal Gas Monitor

MALSH

TIME and MATERIAL DAILY REPORT

OMID JOB 220008 Cost Code	e.	Description:							the de scope an	nce call for fining of d planning imeframe.						
			11/29	9/2021	11/30	/2021	12/1	/2021	12/2	/2021	12/3	/2021	12/4	/2021		
			Мог	nday	Tue	sday	Wedr	nesday	Thu	rsday	Fri	day	Satu	ırday	TOT	TALS
Emp#	Name	Craft	RT	ОТ	RT	ОТ	RT	ОТ	RT	ОТ	RT	ОТ	RT	ОТ	RT	ОТ
135582	Dave Pauline	Project Manager							2						2	0
128120	Ankur Patel	Superintendent							2						2	0
159161	Mike Graziano	Project Engineer							3						3	0
159088	Christian Biolchini	Project Engineer							2						2	0
19613	Michael Matyaszek	Laborer FM													0	0
															0	0
															0	0
															0	0
															0	0
			•													
	Equipment														TOT	ΓALS
,	1 Single Man Cage															
1 Generator																
1 Supply Air Fan							•						•			

EQUIPMENT RENTAL

United Rentals

POWER & HVAC POWEH & HVAC BRANCH H86 4705 PRODUCT DR WIXOM MI 48393-2056 248-702-1881 248-676-2449 FAX

Si

WARREN PROJECT E 10 MILE RD AND CONSTITUTION WARREN MI 48089

Office: 313-456-6500 Cell: 313-456-6500

5.1,1665 1 MB 0.482 33256S21.p01 253326 1-2 0

արմիրիրիրիայներիայիներութինինիներիո

WALSH CONST GROUP-DETROIT MI 3031 W GRAND BLVD STE 640 DETROIT MI 48202-3031

RECEIVED Walsh Construction

OCT 12 2021

RENTAL RETURN INVOICE

197511959-002

Customer #

116328 10/04/21 08/30/21 09/30/21 Invoice Date 09:00 AM Rental Out 09:09 AM Rental In UR Job Loc UR Job # : E 10 MILE RD AND CON : 35

Customer Job ID:

: 220008 P.O. #

: NICK JANICKE : ERIC KAMEN : ERIC KAMEN Requested By Reserved By Salesperson

Invoice Amount: \$3,040.08

Terms: Net 30 Days
Payment options: Contact our credit office 704-916-4138

REMIT TO: UNITED RENTALS (NORTH AMERICA), INC.

PO BOX 840514 DALLAS TX 75284-0514

13370177.7	TORMO.		Detroit Office				
	ITEMS: Equipment	Description	Minimum	Day	Week	4 Week	Amount
1	DUCT TO PU	HEATER DRY 60 KW ELECTRIC Make: CHROMALOX Model: SDRA-60-4: Serial: C61064808001 Meter out: RAS BLOWER ILL AIR FROM SPACE Iters and misc equipment still back on rent in 2 weeks	3RG-UR .50 Meter in: .50				N/C
1	10322009 500KW HEAT INTO SEWER	HEATER DRY 150 KW ELECTRIC Make: CAPS Model: PHUH-ONN-ONN15 Serial: 14F-0509-015 ER AS VENTILATION TO MOVE AIR SPACE	0	600.00	1,200.00	3,600.00	1,200.00
4	VENTILATIO	A/C DUCTING 20" X 25' ON DUCT TO PUT FRESH AIR C AND PULL AIR FROM SPACE		11.00	22.00	66.00	88.00
2		CABLE BANDED 5 WIRE 50' OWER TO GENERATOR (X2)		35.00	70.00	210.00	140.00
1	20" ROUND	MISCELLANEOUS BULK INVENTORY EQUI X 10' SPIRAL DUCT AND HARD 90 DEGREE ELBOW	PMENT	25.00	50.00	150.00	50.00
4	241/5955 ATTACH TO GROUND	CABLE TAIL #2 FCAM BARE END LUGS ON GENERATOR / 3 HOTS +					N/C
1	10065329	GENERATOR 125-149 KVA Make: CUMMINS Model: C100D6RG Serial: F120348840 Meter out: 16 Substituted for: GENERATOR 45-49		306.00 6418.00	613,00	1,838.00	613.00
					Rental	Subtotal:	2,091.00
	MISCELLANEC / Item	DUS ITEMS:		Price	Unit of	Measure _	Extended Amt
64	DYED DIE	SEL	[DYEDDSL/MCI]	5.500	EACH		352.00
:	L PICKUP (CHARGE		425.000	EACH		425.00
					Sales/Misc	Subtotal:	777.00
					Agreement	Subtotal: Fuel: Tax: Total:	2,516.00 352.00 172.08 3,040.08
OMMEN'	rs/notes:						
	CONTACT: N CELL#: 313	NICK JANICKE 3-456-6500					CONTINUE

Effective January 1, 2021 and where permitted by law, United Rentals may impose a surcharge of 1.8% for credit card payments on charge accounts. This surcharge is not greater than our merchant discount rate for credit card transactions and is subject to sales tax in some jurisdictions.

NOTICE: This invoice is subject to the terms and conditions of the Rental and Service Agreement, which are available at https://www.unitedrentals.com/legal/rental-service-terms-US and which are incorporated herein by reference. A COPY OF THE RENTAL AND SERVICE AGREEMENT TERMS ARE AVAILABLE IN PAPER FORM UPON REQUEST.

Page:

1

OUnited Rentals

POWER & HVAC BRANCH H86 4705 PRODUCT DR WIXOM MI 48393-2056 248-702-1881 248-676-2449 FAX

WARREN PROJECT

E 10 MILE RD AND CONSTITUTION

WARREN MI 48089

Office: 313-456-6500 Cell: 313-456-6500

WALSH CONST GROUP-DETROIT MI STE 640 3031 W GRAND BLVD DETROIT MI 48202-3031

RENTAL **CREDIT MEMO**

197511959-003

Customer # Credit Date

: 116328 : 10/12/21

Credit Inv UR Job Loc UR Job #

: 197511959-001 : E 10 MILE RD AND CON : 35

Customer Job ID:

220008

P.O. # Requested By Reserved By Salesperson

: NICK JANICKE : ERIC KAMEN : ERIC KAMEN

Invoice Amount: \$1,431.00-

Terms: Net 30 Days
Payment options: Contact our credit office 704-916-4138

REMIT TO: UNITED RENTALS (NORTH AMERICA), INC.

PO BOX 840514 DALLAS TX 75284-0514

RENTAL Qty	ITEMS: Equipment	Description	Minimum	Day	Week	4 Week	Amount
1	10322009	HEATER DRY 150 KW ELECTRIC Make: CAPS Model: PHUH-ONN-ONN150 Serial: 14F-0509-015		600.00	1,200.00	3,600.00	1,350.00-
	_				Rental	Subtotal	1,350.00-
	Reason: IN	PUT ERROR CREDIT			Agreement	Subtotal: Tax: Total:	1,350.00- 81.00- 1,431.00-
COMMINI	me /Nomec.						

CONTACT: NICK JANICKE CELL#: 313-456-6500

CELL#: 313-450-0500
DLV/PKU LOC SELECTED BY MAP PIN OPTION
NORTH SIDE OF E 10 MILE RD BTW HOOVER &
SCHOENHER RD. AT HIGH POWER LINES
SITE CONTACTS:
MIKE GRAZIANO - 313.695.0696

CHRISTIAN BIOLCHINI - 313.706.7384

* CUSTOMER WILL BE CHARGED \$129/HOUR FOR WAIT TIME.*
CHARGES COMMENCE AFTER 20 MINUTES OF ARRIVAL. *

Patrolt Office/AP lacelved via email jah 1013-21

NOTICE: This credit memo is subject to the terms and conditions of the Rental and Service Agreement, which are available at https://www.unitedrentals.com/legal/rental-service-terms-US and which are incorporated herein by reference. A COPY OF THE RENTAL AND SERVICE AGREEMENT TERMS ARE AVAILABLE IN PAPER FORM UPON REQUEST.

You Can Now Access Invoice History and Update Purchase Orders Online To Sign Up, contact URControlSupport@ur.com

Page:

7

OUnited Rentals

BRANCH H86 4705 PRODUCT DR WIXOM MI 48393-2056 248-702-1881 248-676-2449 FAX

L

WARREN PROJECT E 10 MILE RD AND CONSTITUTION WARREN MI 48089

Office: 313-456-6500 Cell: 313-456-6500

WALSH CONST GROUP-DETROIT MI STE 640 3031 W GRAND BLVD DETROIT MI 48202-3031

RENTAL CREDIT MEMO

197511959-004

Customer # : 116328 : 10/12/21 Credit Date

: 197511959-002 Credit Inv UR Job Loc UR Job # E 10 MILE RD AND CON

: 35 Customer Job ID:

220008 P.O. #

Requested By : NICK JANICKE : ERIC KAMEN Reserved By : ERIC KAMEN Salesperson

Invoice Amount: \$477.00-

Terms: Net 30 Days

Payment options: Contact our credit office 704-916-4138

REMIT TO: UNITED RENTALS (NORTH AMERICA), INC.

PO BOX 840514 DALLAS TX 75284-0514

Qty	Equipment	Description	Minimum	Day	Week	4 Week	Amount
1	10322009	HEATER DRY 150 KW ELECTRIC Make: CAPS Model: PHUH-ONN-ONN150 Serial: 14F-0509-015		600.00	1,200.00	3,600.00	450.00-
					Rental	Subtotal:	450 . 00-
Reason: IN		PUT ERROR CREDIT			Agreement	Subtotal Tax: Total:	450.00- 27.00- 477.00-

COMMENTS/NOTES:

CONTACT: NICK JANICKE CELL#: 313-456-6500

DLV/PKU LOC SELECTED BY MAP PIN OPTION
NORTH SIDE OF E 10 MILE RD BTW HOOVER & SCHOENHER RD. AT HIGH POWER LINES SITE CONTACTS: MIKE GRAZIANO - 313.695.0696 CHRISTIAN BIOLCHINI - 313.706.7384

Detroit Office/AP **2008 ved via email** Jah 10-13-24

OUnited Rentals

BRANCH H86 4705 PRODUCT DR WIXOM MI 48393-2056 248-702-1881 248-676-2449 FAX

Site



OCT 26 2021

WARREN PROJECT

E 10 MILE RD AND CONSTITUTION WARREN MI 48089

Dehott Office

Office: 313-456-6500 Cell: 313-456-6500

6,1.2286 1 MB 0.482 39583S21.p01 304342 1-1 0

իովկանցակիլիարիկիլիիվորիրիրիգիկիլիյիլ

WALSH CONST GROUP-DETROIT MI 3031 W GRAND BLVD STE 640 DETROIT MI 48202-3031

PARTIAL RETURN INVOICE



199199392-001

: 116328 : 10/19/21 Customer #

Invoice Date Rental Out Rental In : 10/14/21 07:00 AM : 10/15/21 07:00 AM E 10 MILE RD AND CON UR Job Loc

: 35 .UR Job # Customer Job ID:

: 220008 P.O. #

: NICK JANICKE : MARC KOTENKO : ERIC KAMEN Requested By Reserved By Salesperson

Invoice Amount: \$1,275.18

Terms: Net 30 Days

Payment options: Contact our credit office 704-916-4138

REMIT TO: UNITED RENTALS (NORTH AMERICA), INC.

PO BOX 840514 DALLAS TX 75284-0514

	ITEMS: Equipment	Description	Minimum	Day	Week	4 Week	Amount
2	241/8010	CABLE BANDED 5 WIRE 50'	70.00	35.00	70.00	210.00	140.00
1	999/9999	MISCELLANEOUS BULK INVENTORY EQUIPMENT	50.00	25.00	50.00	150.00	50.00
4	241/5955	CABLE TAIL #2 FCAM BARE END					N/C
1	11246859	GENERATOR 70-84 KVA TIER 4	613.00	306.00	613.00	1,838.00	613.00
		Make: JCB Model: G70RS T4F Serial: 2656477 Meter out: 95.00 Meter	in: 100.60				
					Renta1	Subtotal:	803.00
	MISCELLANEO y Item	US ITEMS:		Price	Unit of	Measure	Extended Amt
	1 DELIVERY	CHARGE		200.000	EACH		200.00
	1 PICKUP C	HARGE		200.000	EACH		200.00
					Sales/Misc	Subtotal:	400.00

COMMENTS/NOTES:

CONTACT: NICK JANICKE CELL#: 313-456-6500 Dlv/Pku loc selected by Map Pin Option North side of E 10 Mile Rd btw Hoover & Schoenher Rd. at High Power Lines

* CUSTOMER WILL BE CHARGED \$129/HOUR FOR WAIT TIME.*

* CHARGES COMMENCE AFTER 20 MINUTES OF ARRIVAL. *

Effective January 1, 2021 and where permitted by law, United Rentals may impose a surcharge of 1.8% for credit card payments on charge accounts. This surcharge is not greater than our merchant discount rate for credit card transactions and is subject to sales tax in some jurisdictions.

NOTICE: This invoice is subject to the terms and conditions of the Rental and Service Agreement, which are available at https://www.unitedrentals.com/legal/rental-service-terms-US and which are incorporated herein by reference. A COPY OF THE RENTAL AND SERVICE AGREEMENT TERMS ARE AVAILABLE IN PAPER FORM UPON REQUEST. 1 Page:

O United Rentals

POWER & IIVAG BRANCH H86 4705 PRODUCT DR WIXOM MI 48393-2056 248-702-1881 248-676-2449 FAX

Si



NOV 2 2 2021

WARREN PROJECT

E 10 MILE RD AND CONSTITUTION WARREN MI 48089

Detroit Office

Office: 313-456-6500 Cell: 313-456-6500

5.1.1927 1 MB 0.482 50647S21.p01 388836 1-1 0

միլովեիլերկինիորիիներիկնորիներնենիրնիի

WALSH CONST GROUP-DETROIT MI 3031 W GRAND BLVD STE 640 DETROIT MI 48202-3031

RENTAL RETURN INVOICE



200080010-002

: 116328 : 11/12/21 Customer # Invoice Date

Rental Out : 11/05/21 02:30 PM 07:00 AM : 11/11/21 : E 10 MILE RD AND CON

Rental In UR Job Loc UR Job # : 35 Customer Job ID:

P.O. #

: MIKE GRAZIANO : MARC KOTENKO : ERIC KAMEN Requested By Reserved By Salesperson

Invoice Amount: \$1,673.21

Terms: Net 30 Days

Payment options: Contact our credit office 704-916-4138

REMIT TO: UNITED RENTALS (NORTH AMERICA), INC.

PO BOX 840514 DALLAS TX 75284-0514

	ITEMS:						
<u>Qty</u>	Equipment	Description	Minimum	Day	Week	4 Week	Amount
1	10420640	GENERATOR 70-84 KVA Make: MULTIQUIP Model: DCA70SSJU4I Serial: 7306691 Meter out: 11767.10		306.00 7.00	613.00	1,838.00	613.00
	400 7	Substituted for: GENERATOR 70-84 KVA	TIER 4				
	480v 3 phas	ge prior exchange is 5.000					
	Metel IIOM	prior exchange is 5.000					
4	241/5955	CABLE TAIL #2 FCAM BARE END					N/C
					Rental	Subtotal:	613.00
	MISCELLANEOU	JS ITEMS:		Price	Tinit of	f Measure	Extended Amt.
QE	/ _Item			PITCE		L Measure	Externed Ame.
23	DYED DIES	3EL	[DYEDDSL/MCI]	5.500	EACH		115.50
:	1 DELIVERY	CHARGE		425.000	EACH		425.00
1	L PICKUP CE	HARGE		425.000	EACH		425.00
					Sales/Misc	Subtotal:	965.50
					Agreement	Subtotal:	1,463.00
						Fuel:	115.50
						Tax:	94.71
						Total:	1,673.21
COMMENT	rs/notes:						

CONTACT: MIKE GRAZIANO CELL#: 313-695-0696 Dlv/Pku loc selected by Map Pin Option North side of E 10 Mile Rd btw Hoover & Schoenher Rd. at High Power Lines

* CUSTOMER WILL BE CHARGED \$129/HOUR FOR WAIT TIME.*
* CHARGES COMMENCE AFTER 20 MINUTES OF ARRIVAL. *

Effective January 1, 2021 and where permitted by law, United Rentals may impose a surcharge of 1.8% for credit card payments on charge accounts. This surcharge is not greater than our merchant discount rate for credit card transactions and is subject to sales tax in some jurisdictions.

NOTICE: This invoice is subject to the terms and conditions of the Rental and Service Agreement, which are available at https://www.unitedrentals.com/legal/rental-service-terms-US and which are incorporated herein by reference. A COPY OF THE RENTAL AND SERVICE AGREEMENT TERMS ARE AVAILABLE IN PAPER FORM UPON REQUEST. 1

Page:



9925 S. Industrial Dr. Bridgeview, IL 60455-2408

800-878-7305

AR@RentLGH.com

www.RentLGH.com

Invoice Date: 09/30/2021 Invoice Number: 6000194556

Order Number: 100095160 | Dispatch Number: 200100543 | Quote Number: 456792.1

Customer & Site Information

Customer Billing Information:
WALSH CONSTRUCTION
3031 W GRAND BLVD
Suite 640
DETROIT, MI 48202-3096

p: 313-363-8957 f: 313-873-6633 Customer Site Information
WALSH CONSTRUCTION
12601 E 10 Mile Rd
WARREN, MI 48089
Site Contact: Nick Janicke

REWILL INVOICE

Payment Terms: Payment Terms: NET 30 Email for Billing Questions: AR@rentlgh.com

Account Code: WAL15 Customer PO#: 220008 Internal Ref #: 013/ISA010 Rental Start Date: 08/30/2021 Shipping Date: 08/30/2021

Invoice Type: Continuation

p: 312-296-2279

Qty.	E-Code	Equipment Description	No. of Days	Rate/Price	Total Charge
1	OPH0007	300 lbs. Manbasket (30" Diameter) From: 08/30/2021 To: 09/26/2021	28	\$78.57/ Daily Rate \$550.00/ WEEK \$2,200.00/ MONTH	\$2,200.00
1	N/A	DELIVERY CHARGE		\$65.00 EA	\$65.00

Taxability Address: (based on where goods exchanged hands)

12601 E 10 Mile Rd WARREN, MI 48089 Goods Total: \$2,265.00 Tax: \$135.90 Invoice Total: \$2,400.90

7 DAY MINIMUM RENTAL MONTHLY RATES ARE FOR 28 DAYS

A service charge of 1 ½ % Per Month (18% Annum) will be applied to all accounts over 30 days.

Payment Options

If paying by check, mail to: Lifting Gear Hire Corporation P.O. Box 734381 Chicago, IL 60673-4381 Payment by EFT/ACH to: Lifting Gear Hire Corporation Routing# 071000013 Account: 936388651

Payment by credit card go to: https://www.rentlgh.com/payment

> Detroit Office/RP Peceived via email jah <u>1644</u>



9925 S. Industrial Dr. Bridgeview, IL 60455-2408

800- 878-7305

AR@RentLGH.com

(www.RentLGH.com

Invoice Date: 10/31/2021 Invoice Number: 6000197963

Order Number: 100095160 | Dispatch Number: 200100543 | Quote Number: 456792.1

Customer & Site Information

Customer Billing Information:
WALSH CONSTRUCTION
3031 W GRAND BLVD
Suite 640
DETROIT, MI 48202-3096
p: 313-363-8957

p: 313-363-8957 f: 313-873-6633 customer Site Information
WALSH CONSTRUCTION
12601 E 10 Mile Rd
WARREN, MI 48089
Site Contact: Nick Janicke

RENTAL INVOICE

Payment Terms: Payment Terms: NET 30 Email for Billing Questions: AR@rentlgh.com

Account Code: WAL15 Customer PO#: 220008 Internal Ref #: 013/ISA010 Rental Start Date: 08/30/2021 Shipping Date: 08/30/2021

Invoice Type: Continuation

p: 312-296-2279

Item Details							
Qty.	E-Code	Equipment Description	No. of Days	Rate/Price	Total Charge		
1	OPH0007	300 lbs. Manbasket (30" Diameter) From: 09/27/2021 To: 10/24/2021	28	\$78.57/ Daily Rate \$550.00/ WEEK \$2,200,00/ MONTH	\$2,200.00		

Taxability Address: (based on where goods exchanged hands)

12601 E 10 Mile Rd WARREN, MI 48089

Page: 1 of L

Tax: \$132.00 Invoice Total: \$2,332.00

7 DAY MINIMUM RENTAL MONTHLY RATES ARE FOR 28 DAYS

A service charge of 1 $\frac{1}{2}$ % Per Month (18% Annum) will be applied to all accounts over 30 days.

Payment Options

If paying by check, mail to: Lifting Gear Hire Corporation P.O. Box 734381 Chicago, IL 60673-4381 Payment by EFT/ACH to: Lifting Gear Hire Corporation Routing# 071000013 Account: 936388651

Payment by credit card go to: https://www.rentlgh.com/payment

Detroit Office/AP Received via email jah <u>1/-2-21</u>

Goods Total: \$2,200.00

9.0

65



9925 S. Industrial Dr. Bridgeview, IL 60455-2408

800- 878-7305

AR@RentLGH.com

www.RentLGH.com

Invoice Date: 12/07/2021 Invoice Number: 6000202681

Order Number: 100095160 | Dispatch Number: 200100543 | Quote Number: 456792.1

Customer & Site Information

Customer Billing Information: WALSH CONSTRUCTION 3031 W GRAND BLVD Suite 640 DETROIT, MI 48202-3096

p: 313-363-8957 f: 313-873-6633 **Customer Site Information** WALSH CONSTRUCTION 12601 E 10 Mile Rd **WARREN, MI 48089** Site Contact: Nick Janicke p: 312-296-2279

Account Code: WAL15 Customer PO#: 220008 Internal Ref #: 013/ISA010 Rental Start Date: 08/30/2021 Shipping Date: 08/30/2021

Invoice Type: RETURN INVOICE

Payment Terms: Payment Terms: NET 30 Email for Billing Questions: AR@rentlgh.com

RESTAL BEFORE

Item Details							
Qty.	E-Code	Equipment Description	No. of Days	Rate/Price	Total Charge		
1	OPH0007	300 lbs. Manbasket (30" Diameter) From: 11/22/2021 To: 12/03/2021	12	\$78.57/ Daily Rate \$550.00/ WEEK \$2,200.00/ MONTH	\$942.84		
1	N/A	RETURN CHARGE	9	\$65.00 EA	\$65.00		

Taxability Address: (based on where goods exchanged hands)

12601 E 10 Mile Rd

WARREN, MI 48089

Goods Total: \$1,007.84

\$60.47 Tax:

Invoice Total: \$1,068.31

7 DAY MINIMUM RENTAL MONTHLY RATES ARE FOR 28 DAYS

A service charge of 1 $\frac{1}{2}$ % Per Month (18% Annum) will be applied to all accounts over 30 days.

Payment Options

If paying by check, mail to: Lifting Gear Hire Corporation P.O. Box 734381 Chicago, IL 60673-4381

Payment by EFT/ACH to: Lifting Gear Hire Corporation Routing# 071000013

Account: 936388651

Payment by credit card go to: https://www.rentigh.com/payment

> Datroit Office/AP Received via email

STR:9010 US DEBIT **********7090 AID: A0000000980840 TUR: 8000048000 IAD: 06010A03A02000 ARC: 00 Chip Read INTERLINK CUST#: eligible for return.

\$89.99T Discounted Price: EMPLOYEE / COMPANY SPECIAL \$13.49T 002929685 GAME WADE CHEST PU Discounted Price: EMPLOYEE / COMPANY SPECIAL

TRX:06663

CSH: 82034

\$103.48 Subtotal 103.48 @ 6.000% Tax \$6.21 Total \$109.69

USD \$109.69

Card Type: DT Node: Issuer

TSI: 6800 Approved 002528

Verified by PlN

ITEMS SOLD 2

127

AAA - MICHIGAN

Save All Receipts. Items eligible for refund or exchange by 11/08/21 ID may be required. See back of receipt for Return Policy. Free with purchase items not

Now Hiring dunhamssports.com/careers.html Thank You for Shopping at Dunham's!



BOBS SANITATION SERVICE, INC

SCOTTY'S POTTIES P.O. BOX 530845 LIVONIA, MI 48153 Ph: (734) 421-1400 Fax: (734) 946-7382 Email: emailus@scottyspotties.net

Detroit Office





Invoice

Service Address

Billing Address	Service
WALSH CONSTRUCTION	WALSH CONSTRUCTION
SUITE #640	12601 10 MILE RD
3031 W. GRAND BLVD.	WARREN, MI 48089
DETROIT, MI 48202	

Phone: (313)

Site # 31392 ESCRIPTION 7 SANITIZER-5	Date Clerk Terms P.O.# Invoice# Page	11/23/2021 RR NET10 A-229903 Page 1 / 1	RATE QTY AMOUNT	SN#.CN1618 120.00 I 120.00	Paid Amt 0.00	Adjustment Anti
Cust #		WAL7870 31392	DESCRIPTION	SN# W/ SANTITZER-Service		

THANK YOU FOR DOING BUSINESS WITH US:

Statement as of 1123/2021 Future: 0.00 Current: 240.00 30 Day: 0.00 60 Day: 0.00 90 Day: 0.00 Total Due: 240.00

Please detach here and return the bottom portion with your payment. Div:A Cust #: WAL7870 Site #:31392 Invoice #: 229903

From WALSII CONSTRUCTION SUITE #640 3031 W. GRAND BLVD. DETROIT, MI 48202 T

BOBS SANITATION SERVICE, INC SCOTTY'S POTTHES P.O. BOX 530845 LIVONIA, MI 48153

Check Enclosed Invoice Balance 120,00 Previous Balance 240.00 ☐ Charge Monthly Amount Paid Total Due If paying by Credit Card, please fill out below ☐ 1 Time Charge CVC Code Choose One: Card Number Exp. Date

Do we have your correct email? jhaydon@walshgroup.com If not, please write your correct email here:

VISA_M/C_DISCOVER_AMEX

If credit card address different from billing address above, please write in below.

All invoices more than 30 days old are charged a late fee of 1.5% per month or 18% per year.

Field Meeting to Discuss CS-9 and NESPS Lakeshore Stop Log Issues

Field Meeting to Discuss CS-9 and NESPS Lakeshore Stop Log Issues

Meeting Minutes

Date: Wednesday September 8, 2021, 11:30 a.m., WRC Project # 1-3308 and 1-3309

Location: NESPS Walsh Field Trailer

Attendee Name	Representing
Joel Brown	OCWRC
John Michalski	ASI
Terry Moore	
Larry Gilbert	NTH
Dave Pauline	
Ankur Patel	Walsh
Nick Janicke	Walsh
Mike Mastracci Jr	De-Cal
Todd Cowper	De-Cal

Items

- 1. CS-9 Status (See Section g for schedule)
 - a. Accumulator leakage: Walsh is to work with HydroGate and Sun Systems to find and correct the accumulator leak (losing pressure). This is highest priority and critical for gate movements/operations. Flow control is not required for this operation.
 - b. Gate Leakage
 - i. Criteria/Status: The group agreed to an allowable leakage rate of 0.16 GPM/ft. With a 16 feet wet perimeter for each sluice gate and an approximately 49 foot wetted perimeter on the bulkhead, this equates to a total wetted perimeter of 81 feet and total allowable flow of approximately 13.0 GPM. The pass fail of this measurement will be on a visual basis (comparing to a 5 gallon bucket fill-up) per sluice gate (approximately 2.5 GPM) and then overall leaving the pipe (bulkhead assessment). The first leakage test did not pass this criterion.

c. Testing-Prep

- i. The day prior to testing will involve major cleaning of the gate. This can be done in conjunction with proximity switch work.
- ii. Walsh will work on cleaning the gate during the morning while flow control is being performed via CS-5 closure. When Walsh is complete with cleaning CS-9, the gates are to be closed/checked. The downstream standing water will then be pumped out via a sump to allow viewing of the bulkhead/sluice gate. CS-5 will then be slow-released as modified by ASI to control flow inbound to CS-9 to build up storage. Pass/Fail will then be established as indicated in Section b.

d. Instrumentation Issue

- i. CCI to confirm no hardware/software issues
- ii. CCI to confirm electrical interference

iii. Verify through testing of the gate (move gates up and down while monitoring). Move also without affecting depth.

e. Proximity Switch

i. Sun Systems is to correct the proximity Switch by sensor replacement and testing I/Os/general troubleshooting.

f. Hatch

i. Doetsch, NTH and possibly Walsh to make entry at CS-9 with wagon under full flow control from upstream gates CS-3, CS-5, CS-6, CS-7, CS-8. Walk downstream with recovery wagon. NTH to provide own PPE. If hatch is within a few hundred feet of CS-9, extraction will be at CS-9. Otherwise, search will continue downstream until hatches are found and loaded into wagon. Wagon and personnel will then be lifted out of NESPS. Ventilation to be provided at Toepher shaft.

g. Schedule

- i. Friday 9/10: CS-9 hatch recovery CS-3, CS-5, CS-6, CS-7, CS-8 Closed
- ii. Monday 9/13: OR Sewer walk. Closing CS-3, CS-6, CS-7, CS-8 Closed
- iii. Tuesday 9/14: Walsh accumulator work-investigate sensor issue— MID ADS Meter maintenance. CS-3, CS-6,CS-7, CS-8 Closed
- iv. Wednesday 9/15: CS-9 proximity switch, investigate sensor issue and major gate cleaning CS-3, CS-5, CS-6, CS-7, CS-8 Closed
- v. Thursday 9/16: Minor cleaning and leakage test CS-5 closure, modified release.

2. Lakeshore Stop Log

- a. De-Cal reviewed improvements that were made to the Lakeshore stop log. The side gaskets were replaced (60 durometer) and debris was removed from the threshold P-seal gasket (90 durometer reading). De-Cal utilized Welton for seal options. The P-Seal currently has a 25-week lead time. Tabs were welded on the corners to prevent the gasket from flexing in. The stop log was lowered yesterday Tuesday 9/7. Significant, unacceptable, leakage was observed on the south side of the gate at the corner and the north side of the gate along the side seal. Walsh believes the seat may be uneven, contributing to the leakage.
- b. There was discussion as to whether there is a metal threshold seat in the stop log channel. This will be confirmed on Friday 9/10.
- c. Walsh/De-Cal is exploring the use of rubber pieces to fill in gaps or otherwise supplementing large pieces of rubber onto the P-seal. If there is no metal threshold, a new one should be constructed and leveled (further discussion will be needed after confirmation).
- d. A general discussion was held on cinders. The group agreed this option is worth exploring, with possibly only 10 gallons needed. Larry and Ankur to contact suppliers. Joel to send link to company he found.

ACTION ITEMS:

- 1. John Michalski to develop revised release pattern for CS-5 when CS-9 is closed (for leakage testing).
- 2. Terry to work with GLWA to adjust NESPS pumping procedures prior to OMID dewatering to ensure wet well levels remain below EL 528.
- 3. Confirm Lakeshore threshold is made of metal (Friday 9/10).
- 4. Joel to send cinder company link to group.
- 5. Larry and Ankur to evaluate cinder supplier options.
- 6. Mike to confirm rubber seal options and lead times.

NTH REPORT



PROJECT NAME OMID NI-EA PCI-4 & CS-9 Gate CCA	PROJECT NO.	61-200186-02
PROJECT LOCATION OMID Control Structure 9 - Warren, MI	DATE	09/10/2021
CLIENT OMIDDD	WEATHER	Sunny
CLIENT'S REPRESENTATIVE(S) Joel Brown, P.E.	TEMP:	74 °F
CONTRACTOR Walsh Construction, Doetsch Environmental	PAGE 1 of	9
CONTRACTOR'S REPRESENTATIVE(S) Ankur Patel, Joe Schotthoefer	REPORT NO.	001
	TIME ON SITE	7:00 AM – 2:45 PM

TASK LOCATION					SATISFACTORY ? Check One Yes No	
EARTHWORK AND SUBGRADE PREPARA	TION					
Excavation/Fill						
Proofrolling						
UTILITY CONSTRUCTION						
Excavation/Backfill						
FOUNDATION CONSTRUCTION						
Excavation						
Backfill						
STRUCTURAL CONCRETE						
Reinforcing Steel						
Cast In-Place Concrete						
Pre-Cast Concrete						
STRUCTURAL STEEL ERECTION						
Framing						
Decking						
MASONRY CONSTRUCTION						
Erect						
Grout/Reinforcing Steel						
BITUMINOUS PAVEMENT						
Placement & Compaction						
OTHER						
Plate Recovery & Liner Inspection	OMID -	- CS-9 to PCI-5-108			X	
ATTACHMENTS						
ATTACHMENT	# OF ITEMS	ATTACHMENT	# OF ITEMS	ATTACHMENT		# OF ITEMS
Field Density Test Report(s)		Sketch(s)		Other:		
Daily Concrete Report(s)		Photo(s)		Other:		
Masonry Report(s)		Reinforcing Steel Inspection Report(s)		Other:		

itellis allu aleas (or construction reviewed during today	s site visit were illilited to those specifically discusses	u ili tilis Dally Fleid Report.
Report Prepared by:	Colton Morrow	Reviewed By:	A. Almadhoun
		_	



PROJECT NAME OMID NI-EA PCI-4 & CS-9 Gate CCA	PROJECT NO.	61-200186-02
PROJECT LOCATION OMID Control Structure 9 - Warren, MI	DATE	09/10/2021
CLIENT OMIDDD	WEATHER	Sunny
CLIENT'S REPRESENTATIVE(S) Joel Brown, P.E.	TEMP:	74 °F
CONTRACTOR Walsh Construction, Doetsch Environmental	PAGE 2 of	9
CONTRACTOR'S REPRESENTATIVE(S) Ankur Patel, Joe Schotthoefer	REPORT NO.	001
	TIME ON SITE	7:00 AM – 2:45 PM

Equipment on Site: Walsh: Crew Pickup (2). Doetsch: Crew Pickup (2), Box Truck. Laramie: Crane. FKE: Crew Pickup.

Visitors on Site: Walsh: 4-man crew. Doetsch: 5-man crew. FKE: J. Elsey. NTH: C. Morrow, A. Almadhoun, L. Gilbert.

MCPWC: K. Lumma. OCWRC: J. Brown. METCO: T. Moore

7:00 AM: NTH, FKE, Doetsch, and Walsh arrived on site at CS-8 to begin Lock Out/Tag Out (LOTO) operations. The crew would be locating and extracting two plate covers that had fallen into the interceptor at CS-9.

8:00 AM: LOTO operations were completed at control structures CS-8, CS-7, CS-6, CS-5, and CS-3, and the crew arrived at CS-9 which would remain open.

11:00 AM: After an on-site safety discussion, NTH, FKE, a 1-man crew from Walsh, and a 2-man crew from Doetsch entered the sewer via crane and man basket at CS-9. Doetsch was equipped with 2 wagons for extracting the cover plates.

NTH inspected the CS-9 shaft area and noted that two of the FRP handrails had been damaged by the cover plates. The handrails were located directly above the bulkhead in the northeast section of the shaft and on the west platform of the shaft. Spalled concrete was also observed on the channel walls immediately downstream of CS-9 at the 4 o'clock and 8 o'clock positions. NTH did not observe any defects on the sluice gates or rail system. See the attached defect list and photo log for additional information (note that additional site photos and videos outside of the attached photo log are also available for additional review).

Inspection of the HOBAS liner began. Notable defects included 1/4" deep gouges in the liner caused by the cover plates, damaged grout ports, and superficial scratches that ran from the start of the liner to the location of the farthest plate at 1400' downstream. See the attached defect list for exact locations of defects.

The two cover plates were located at 461 feet and 1400 feet downstream of the start of the HOBAS liner. Both cover plates were found upside down in the interceptor with no noticeable damage observed to either the plates or the liner underneath where they were found.

12:00 PM: The crew arrived back at CS-9 and FKE and NTH exited the sewer. Doetsch and Walsh prepared the two cover plates to be extracted via crane.

1:00 PM: Doetsch and Walsh exited the sewer after extracting the cover plates.

1:30 PM: NTH left CS-9 to complete the end of day LOTO operations.

2:45 PM: LOTO operations were completed and NTH left the site.

Non-conforming items observed or updated today: None

Items and	lareas of c	onstruction rev	iewed during too	av's site visit we	re limited to those	enecifically discus	sed in this Daily Field Repo
ILCIIIS AIIL	. ai cas vi c	JULISH UCHUH TEV	ieweu uui iiiu tot	av a alle viali we	:	SUCCINCAILY GISCUS	aseu III IIIIa Daliv I Ielu Nebu

Report Prepared by:	Colton Morrow	Reviewed By:	A. Almadhoun



PROJECT NAME OMID NI-EA PCI-4 & CS-9 Gate CCA	PROJECT NO.	61-200186-02
PROJECT LOCATION OMID Control Structure 9 - Warren, MI	DATE	09/10/2021
CLIENT OMIDDD	WEATHER	Sunny
CLIENT'S REPRESENTATIVE(S) Joel Brown, P.E.	TEMP:	74 °F
CONTRACTOR Walsh Construction, Doetsch Environmental	PAGE 3 of	9
CONTRACTOR'S REPRESENTATIVE(S) Ankur Patel, Joe Schotthoefer	REPORT NO.	001
	TIME ON SITE	7:00 AM – 2:45 PM

	HOBAS Liner Inspection				
Distance from Start of Liner (ft)	Observation	Clock Position			
0	Begin typical scratches in the liner, these scratches do not puncture the top layer of liner.	4:00 & 8:00			
5	Gouge in liner. Approx. 4" by 1" by 1/4"	4:00			
6	Gouge in liner. Approx. 4" by 1/2" by 1/4"	4:00			
24	Gouge in liner. Approx. 4" by 1/2" by 1/8"	8:00			
25	Gouge in liner. Approx. 2" by 1/2" by 1/8"	8:00			
40	Typical scratches move below the flow line.	5:00 & 7:00			
75	Gouge in liner. Approx. 2" by 1/2" by 1/8"	4:00			
200	Typical scratches above flow line.	4:00			
215	Scratch on liner deep enough to feel and approx. 3" by 0.05"	3:00			
245	Gouge in liner. Approx. 1" by 1" by 1/4"	5:00			
300	Typical scratches back below flow line.	5:00 & 7:00			
461	Found first missing plate. No defects observed under plate.	6:00			
510	Scratch on liner deep enough to feel and approx. 3.5" by 0.05"	5:00			
575	Gouges in liner. Approx. 3" by 1/2" by 1/4" each	5:00 & 7:00			
650	Scratch on liner deep enough to feel and approx. 3" by 0.05"	8:00			
684	Gouges under flow line.	7:00			
684	Damaged grout port. Flange and gasket damaged, PVC cap missing.	5:00			
737	Gouge in liner. Approx. 1" by 1" by 1/4"	4:00			
740	Gouge in liner. Approx. 1" by 1" by 1/4"	5:00			
755	Gouge in liner. Approx. 5" by 1" by 3/8"	7:00			
855	Defect in liner. Does not appear to be caused by plate.	5:00			
1125	Gouge in liner. Approx. 3" by 1/2" by 1/8"	4:00			
1126	Gouge in liner. Approx. 4" by 1/2" by 1/4"	4:00			
1177	Damaged grout port. Flange and gasket damaged, PVC cap missing.	7:00			
1400	Found second missing plate. No defects observed under plate.	6:00			

Report Prepared by:	Colton Morrow	Reviewed By:	A. Almadhoun



PROJECT NAME OMID NI-EA PCI-4 & CS-9 Gate CCA	PROJECT NO.	61-200186-02
PROJECT LOCATION OMID Control Structure 9 - Warren, MI	DATE	09/10/2021
CLIENT OMIDDD	WEATHER	Sunny
CLIENT'S REPRESENTATIVE(S) Joel Brown, P.E.	TEMP:	74 °F
CONTRACTOR Walsh Construction, Doetsch Environmental	PAGE 4 of	9
CONTRACTOR'S REPRESENTATIVE(S) Ankur Patel, Joe Schotthoefer	REPORT NO.	001
	TIME ON SITE	7:00 AM – 2:45 PM

Photo Log:



Photo 1: Damaged handrail directly above gate structure (facing upstream)



Photo 2: Damaged handrail to the west of the gate structure

Report Prepared by:	Colton Morrow	
---------------------	---------------	--



PROJECT NAME ON	MID NI-EA PC	I-4 & CS-9 Gate CCA	PROJECT NO	. 61-200186-02
PROJECT LOCATION	OMID Contro	l Structure 9 - Warren, MI	DATE	09/10/2021
CLIENT OMIDDD			WEATHER	Sunny
CLIENT'S REPRESENTAT	TIVE(S) Joel	Brown, P.E.	TEMP:	74 °F
CONTRACTOR Wals	sh Construction	, Doetsch Environmental	PAGE 5	of 9
CONTRACTOR'S REPRES	SENTATIVE(S)	Ankur Patel, Joe Schotthoefer	REPORT NO.	001
			TIME ON SITE	7:00 AM – 2:45 PM



Photo 3: Spalled concrete on the west side of the shaft



Photo 4: Spalled concrete on the east side of the shaft



PROJECT NAME OMID NI-EA PCI-4 & CS-9 Gate CCA	PROJECT NO. 61-200186-02
PROJECT LOCATION OMID Control Structure 9 - Warren, MI	DATE 09/10/2021
CLIENT OMIDDD	WEATHER Sunny
CLIENT'S REPRESENTATIVE(S) Joel Brown, P.E.	TEMP: 74 °F
CONTRACTOR Walsh Construction, Doetsch Environmental	PAGE 6 of 9
CONTRACTOR'S REPRESENTATIVE(S) Ankur Patel, Joe Schotthoefer	REPORT NO. 001
	TIME ON SITE 7:00 AM – 2:45 PM



Photo 5: Gouges in liner at 5' and 6' downstream



Photo 6: Typical light scratches in liner

Items and areas of construction reviewed during today's site visit were limited to those specifically discussed in this Daily Field Report.

Report Prepared by: Colton Morrow

Reviewed By:

A. Almadhoun



PROJECT NAME OMID NI-EA PCI-4 & CS-9 Gate CCA	PROJECT NO.	61-200186-02
PROJECT LOCATION OMID Control Structure 9 - Warren, MI	DATE	09/10/2021
CLIENT OMIDDD	WEATHER	Sunny
CLIENT'S REPRESENTATIVE(S) Joel Brown, P.E.	TEMP:	74 °F
CONTRACTOR Walsh Construction, Doetsch Environmental	PAGE 7 of	9
CONTRACTOR'S REPRESENTATIVE(S) Ankur Patel, Joe Schotthoefer	REPORT NO.	001
	TIME ON SITE	7:00 AM – 2:45 PM



Photo 7: Gouges in liner at 24' and 25' downstream



Photo 8: Typical 1" gouge in liner



PROJECT NAME OMID NI-EA PCI-4 & CS-9 Gate CCA	PROJECT NO.	61-200186-02
PROJECT LOCATION OMID Control Structure 9 - Warren, MI	DATE	09/10/2021
CLIENT OMIDDD	WEATHER	Sunny
CLIENT'S REPRESENTATIVE(S) Joel Brown, P.E.	TEMP:	74 °F
CONTRACTOR Walsh Construction, Doetsch Environmental	PAGE 8 of	9
CONTRACTOR'S REPRESENTATIVE(S) Ankur Patel, Joe Schotthoefer	REPORT NO.	001
	TIME ON SITE	7:00 AM – 2:45 PM



Photo 9: Damaged liner found at 855' downstream. Does not appear to be gouge from plate.



Photo 10: Gouges in liner at 1125' and 1126' downstream



PROJECT NAME OMID NI-EA PCI-4 & CS-9 Gate CCA	PROJECT NO.	61-200186-02
PROJECT LOCATION OMID Control Structure 9 - Warren, MI	DATE	09/10/2021
CLIENT OMIDDD	WEATHER	Sunny
CLIENT'S REPRESENTATIVE(S) Joel Brown, P.E.	TEMP:	74 °F
CONTRACTOR Walsh Construction, Doetsch Environmental	PAGE 9 of	9
CONTRACTOR'S REPRESENTATIVE(S) Ankur Patel, Joe Schotthoefer	REPORT NO.	001
	TIME ON SITE	7:00 AM – 2:45 PM



Photo 11: Damaged grout port at 684' downstream



Photo 12: Damaged grout port at 1177' downstream

TIME OF LOSS

SWORN STATEMENT

POLICY/CLAIM NUMBER

PROOF OF LOSS

I11175077 001 / KY21K2817628

07/01/20	_	TO THE	Southfield,	MI
ISSUED			AGENCY AT	
07/01/24	_	_	MEADOWBRO	OK INC
EXPIRES			AGENT	ž
		ACE American Insurance Company		
	of	Alpharetta, GA		
	At time of	floss, by the above indicated policy of insurance our insured		
	Oa ¹	kland-Macomb Interceptor Drain Drainage District		

to the property described under the above policy, according to the terms and against loss by All Risk conditions of the said policy and all forms, endorsements, transfers and assignments attached thereto.

TIME AND Property loss occurred on the 31st day of August, 2021 ORIGIN The cause and origin of the said loss were: Falling object into shaft / interceptor causing damage to platform railing and concrete. **OCCUPANCY** The building described, or containing the property described, was occupied at the time of loss as follows, and for no other purpose whatever: **Pumping Station** TITLE AND At the time of the loss the interest of your insured in the property described therein was: OWNER INTEREST No other person had any interest therein or encumbrance thereon, except: **CHANGES** Since the said policy was issued there has been no assignment thereof, or change of interest, use, occupancy, possession, location or exposure of the property described, except: None Known THE TOTAL AMOUNT OF INSURANCE upon the property described by this policy was, at the time of **TOTAL INSURANCE** \$98,226,400.00 as more particularly specified in the apportionment attached under the policy besides which there was no policy or other contract of insurance, written or oral, valid or invalid. VALUE THE ACTUAL CASH VALUE OF said property at the time of loss was VALUE LOSS THE WHOLE LOSS AND DAMAGE was 591,981.00 (25,000.00)**DEDUCTIBLE** Less the APPLICABLE DEDUCTIBLE AMOUNT 566,981.00 THE AMOUNT CLAIMED under the above numbered policy is CLAIMED

The said loss did not originate by any act, design or procurement on the part of your insured, or this affiant; nothing has been done or with the privity or consent of your insured or this affiant, to violate the conditions of the policy, or render it void; no articles are mentioned herein or in destroyed or damaged at the time of said loss; no property saved has in any manner been concealed, and no attempt to deceive the said company, as to the extent of said loss, has in any manner been made. Any other information that may be required will be furnished and considered a part of this proof.

Fraud Warning: It is a crime to provide false or misleading information to an insurer for the purpose of defrauding the insurer or any other person. Penalties include imprisonment and/or fines. In addition, an insurer may deny insurance benefits if false information materially related to a claim was provided by the applicant."

The furnishing of this blank or the preparation of proofs by a representative of the above insurance company is not a waiver of any of its rights.

State of County of

Insured

Subscribed and sworn to before me this 22 day of June

20 22 Notary Public

JEFFREY S. PARROTT NOTARY PUBLIC, STATE OF MI COUNTY OF OAKLAND MY COMMISSION EXPIRES Oct 31, 2022 ACTING IN COUNTY OF OAKLA

CHANGE ORDER NO. THREE

NIEA OMID Contract One, PCI-4 Rehabilitation

Oakland Macomb Interceptor Drain, Drainage District (OMIDDD)

For Lining of the PCI-4 Interceptor and Access Structure Construction
Located in the City of Detroit, Wayne County, Michigan

Authorization for: 1.) Reimbursement for the cost of Demolition and Removal of portions of the PCI-4 Geo-Polymer spray-on lining; 2.) Delay time costs due to emergency evacuation of Interceptor 3.) Additional cost for cement/ fly ash substitution. 4.) Adjustments to the Contract Time for Work performed under Items 3.1, 3.2, and 3.3 (above). 700 East 73 rd. Street Cleveland, OH 44103 Date: August 05, 2022

No.	Location-Description-Reason	Unit	Est. Quant.	Unit Price	Amount Increase	Amount Decrease
	LOCATION: This reach of the PCI-4 Interceptor Sewer is located beneath segments of the Northeast Sewage Pump Station campus, East State Fair Ave, Conner Ave., and East Outer Drive Ave. in the City of Detroit, MI					
3-1	DESCRIPTION: (Change/ Extra): Provide reimbursement to the Contractor for extra costs incurred during the installation of the Channeline Lining Segments in the initial 110 if of the PCI-4 Interceptor immediately downstream of the NESPS Discharge Chamber. (Note: Adjustments to the Contract Time resulting from this additional Work are described in the following Item 3-4.)	1	LS	\$206,603.13	\$206,603.13	-0-
	REASON: The initial 110 lf. approx. of the PCI-4 Interceptor was previously lined (limited to the upper 270 deg. interior					

Page 1 of 7

No.	Location-Description-Reason	Unit	Est. Quant.	Unit Price	Amount Increase	Amount Decrease
3-1	sector) with a "Geo-Polymer" spray-on lining following the complete of the NESPS Gatehouse Emergency Repair Project. Following a service period of approx. 5 years, this lining exhibited an inability to withstand the high H2S concentrations typical to that specific reach of the Interceptor. A decision was then made to extend the Channeline lining segment limits utilized by the current NIEA C-1 Contract, the additional distance necessary to provide a complete (360 degree) lining replacement. This addition now extends the lining further to the NESPS Discharge Chamber. This additional lining Work was authorized by prior Change Order No. One under this Contract following the established As-Bid unit prices. The initial efforts to install the additional Channeline lining segments, however, were adversely impacted due to the presence of the irregular (original) spray-on lining limiting the dimensional freedom necessary to physically install and "home" the lining segments (i.e., complete the joint connection). Consequently, a removal effort was undertaken to manually demolish and remove offending portions of the Geo-Polymer spray-on lining, thereby creating adequate annular working clearance for the new lining installation. In addition, the work was also complicated by the initial lining segments being custom fabricated to accommodate the irregular "truncated cone transition" shape of the Interceptor portal entrance. These various issues combined further to create over-stress conditions in several of the segmental joint locations that required specialized procedures using laminated fiberglass repair techniques to maintain the full integrity of the liner. Lastly, the work was performed under limiting, restrictive Flow Control Management work hours mandated by NESPS pumping requirements. Attachment: Marra Services Correspondence of 8-03-2022					
3-2	DESCRIPTION (Extra/Add) Provide compensation for idled equipment and crew due to an unexpected "ordered evacuation" of the PCI-4 Interceptor resulting from Flow Management Operations at the NESPS.	LS	Ea.	\$ 8,660.19	\$ 8,660.19	-0-
	REASON:					
	The Contractor commenced normal work operations on					

No.	Location-Description-Reason	Unit	Est. Quant.	Unit Price	Amount Increase	Amount Decrease
3-2	June 28, 2022 following routine LoTo Protocols and mobilization of equipment and crew in the Interceptor. During that time, routine (unrelated) operations within the NESPS inadvertently damaged a control valve on the Pump # 1 Knife gate operator that moved the knife gate to an pre-set automatic "Open" position. This condition resulted in the wet well storage levels being "communicated" to the Pump # 1 discharge system, and placed the crew working in the PCI-4 interceptor in a potentially dangerous engulfment condition. For reasons of obvious Worker Safety concerns, the Flow Control Manager requested all work to cease in the PCI-4 Interceptor with crews and equipment being evacuated topside to safety. The net impact of this necessary action resulted in the delay of one work day for the lining crew and accompanying support equipment. (Note: Schedule impacts are summarized in the following Item 3-x)					
3-3	DESCRIPTION: (Change/ Add): The design for the initial 50 lf of the Channeline segmental lining beginning at the NESPS Gatehouse portal called for the use of a structural grout that utilized "fly ash" (a waste product from coal fired power plants) as a major cementitious component. The fly ash component was eliminated, and was replaced with normal Portland cement that resulted in necessary adjustments to the segment buoyancy and the grout placing schedule.	LS	Еа	\$ 7,013.09	\$ 7,013.09	-0-
	REASON: The unanticipated current marketplace unavailability of fly ash used as a cementitious product in grout mixtures mandated a replacement using a heavier Portland cement substitution. Due in part to supply chain issues, supplier inventories, and environmental regulations, fly ash mix designs were declined by the major concrete producers in the local market. The use of Portland cement, while acceptable as a structural substitution, resulted in a significantly heavier "unit weight" of the grout material. This factor in turn resulted in an increased buoyancy condition for the liner segments (i.e increased their undesirable tendency to "float" during grout placement), that in turn required an extra grouting sequence to ensure the buoyancy forces were safely controlled. The result of this adjustment was a full crew day added to the work schedule for one additional grout placement.					

No.	Location-Description-Reason	Unit	Est. Quant.	Unit Price	Amount Increase	Amount Decrease
3.3	Ultimately, the work was completed safely and satisfactorily without incident, and future grouting operations will by plan utilize a different mix design th employs light weight cellular grout. (Note: Schedule impacts are summarized in the following Item 3-4)	at				
3-4	DESCRIPTION: (Time Adjustment/Add):					
	The Contract Time is adjusted for a duration of 31 Calendar days to reflect the additive time required to complete the additional Work described in Items # 3-1 3-2, and 3-3, above.	Day , (Cal.)	Еа.	31 Days	31 Days	-0-
	REASON:					
	The additional Work described in C.O. Items 3-1, 3-2 and 3-3 involved a sequenced delay period that directly and adversely affected the Project Critical Pat Schedule. Upon a review of the overall duration of the task, it was determined that the Contractor is entitled a Contract Time extension of 31 Calendar Days.	h s				
	The delay times are identified as follows:					
	Geo-Polymer Lining Removal and Lining (Fiberglass) Repairs 29 cal. days	5				
	Evacuation of Interceptor 1 cal. day					
	Additional "Buoyancy" Grouting 1 cal. day					
	Total: 31 cal. days	3				
	The current (previously adjusted) dates for Contract Completion are:					
	Substantial Completion: Dec. 07,2022					
	Final Completion: Jan. 06, 2023					
	The proposed revised dates for Contract Completion resulting from this Change Order are:					
	Substantial Completion: Jan. 08, 2023					
	Final Completion: Feb. 07, 2023					

No.	Location-Description-Reason	Unit	Est. Quant.	Unit Price	Amount Increase	Amount Decrease
	This Contract Time adjustment (Item 3-5) is limited to additional time only, and other direct and/or indirect costs resulting from this time extension are assumed to be incidental and non-compensable costs included in C.O. Items 3-1, 3-2, and 3.3.					

	END OF CHANGE ORDER NO. THREE LINE ITEMS					
					Amount Increase	Amount Decrease
			Т	otals	\$222,276.41	-0-
			Change (Ad		\$222,276.41	-0-
				e Time (Add)	31 Calendar Days	-0-

END OF CHANGE ORDER NO. THREE (NIEA OMID C-1), ITEMIZED DESCRIPTIONS

	NIEA OMID Contract One, PCI-4 Rehabilita	tion; C	C.O. #3
Prepared By: Lawrence T. Gilbert, P.E. NTH Consultants, Ltd.	Tauren, Libal	Date:	8-8-2022
Recommended By: Saju Sachidanandan, P.E Engineer of Design, NTH		Date:	8-8-2022
Approved By: Joel Brown, P.E. Project Manager, WRC		Date:	
Stephen Downing	tephen Downing ance Manager, Macomb County Public Works	Date: _	8/12/2022
Approved By: Sid Lockhart, P.E. Manager of Special Projec	cts, WRC	Date:	
Approved by: Steve Korth, P.E. Manager, WRC	Steven Korth	Date:	Aug. 17, 2022
All of Contractor's contract No adjustment to contract related, Change Order.	ctual obligations remain in place and are applicable to time or price shall be made for these issues except a	all work as set ou	and payments identified herein. t in this, or by a subsequent
The Contractor agrees to indicated.	do the work described above and agrees to accept C	ontract t	ime adjustments in full on the basis
Accepted by:	Nühoh Mara	Date	8/12/22
of:	MARRA SERVICES, INC		
The Contractor is hereby a Contract, as amended.	authorized and instructed to do the Work described a	bove in a	accordance with the terms of the
This Change Order No.	3 was approved by the Drainage Board on:	Date:	

Page 6 of 7

Attachment No. 1 to Change Order No. Three

The Engineer has reviewed the items included in this Change Order and confirms that these adjustments to the Contract are reasonable and in accordance with industry standards and the requirements of the Contract.

> Contract Status Summary Change Order No. Three

NIEA OMID CONTRACT ONE, PCI-4 REHABILITATION August 05, 2022

Contractor: Marra Services, Inc.

Project Award Date	January 21, 2021
Notice to Proceed Date	February 16, 2021
Contract Substantial Completion Date (Adjusted for C.O. 3)	January 08, 2023
Contract Final Completion Date (Adjusted for C.O. 3)	February 07, 2023
Original Contract Value	\$ 14,732,510.00
Previous Change Order Values (# 1 and #2)	\$ 808,198.88
Change Order Value, this C.O. # 3	\$ 222,276.41
Adjusted Contract Value, including C.O. #3:	\$ 15,762,985.29

Oakland-Macomb Interceptor Drain Drainage District

Regular Meeting – Wednesday, August 17, 2022

Agenda Item No. 7

Construction Estimates

OAKLAND MACOMB INTERCEPTOR DRAIN DRAINAGE BOARD Northeast Sewage Pumping Station- Pump and Electrical Upgrades Project Located in the City of Detroit, Wayne County, Michigan

	Estimate No. Twenty-Tw	10	July 01, 2022 throug	h July 31, 2022
Page One of Two	Department No.:	6010101	Account No.:	731472
	Fund No.:	84917	Program No.:	149015
	Project No.: 1-3309		Activity:	FAC
Construction Manager	at Risk:	Vendor # 23191	LI 43331; exp. 12/16/22	
Walsh Construction Co.			Date of Contract:	Dec. 16, 2019
3031 West Grand Boule	vard, Suite 640	(Adjusted)	Final Completion Date:	July 28, 2023
Detroit, MI 48202		Contract No. 5977		
Orig. GMP amount for P	ump & Elec. Upgrades Pr	roject, not including CS-9	and Pre-Const. Balance	\$44,107,745.18
Expended Pre-Construct	tion Phase Amount			(\$1,174,363.30)
Unused Pre-Construction	n Phase Budget			(\$70,196.70)
CS-9 Budget from GMP				(\$3,251,117.72)
NESPS Pump & Elec. U	pgrades Original Contrac	t Budget		\$39,612,067.46
Change Orders, This Est	timate: C.O. No. 24			\$570,665.08
Previous C.O.s: (C.O.# 7	7, 8, 9, 10, 11,12, 13, 14,	15, 16, 17, 18, 19, 29, 21,	22, and 23)	\$3,191,514.76
Unused Pre-Construction	n Phase Budget			\$70,196.70
Adjusted Construction C	ontract Amount: (N/I CS-	9)		\$43,444,444.00
Sub-Total To Date: (CS	-9 Costs are Not included	on this Estimate)		\$27,917,150.55
Less Deductions:				None
Gross Estimate: (Work i	n Place) V	/alue Complete = 64.26 %		\$27,917,150.55
Less Amount Reserved ((S/V Retain. @ \$2,337,93	33.10 - CS-9 @122,530.96	3 = \$2,215,402.14)	\$2,215,402.14
Total Amount Allowed To	Date:			\$25,701,748.41
Less Previous Estimates	:			\$24,992,722.91
Current Payment Due				\$709,025.50
Reserve Pay to Contract	or:			\$0.00
Balance to Finish: \$15,5	27,293.45	,	Accounting Auditor:	
Amount To Be Reserved	(10% of 1/2 S.V., less C	S-9 retention)		\$2,215,402.14
Less Previous Transfers	To Reserve (N/i CS-9 C	Contract Retention)		\$2,186,868.89

Amount of Current Transfer

\$28,533.25

OAKLAND MACOMB INTERCEPTOR DRAIN DRAINAGE BOARD

Northeast Sewage Pumping Station- Pump and Electrical Upgrades Project Located in the City of Detroit, Wayne County, Michigan Walsh Construction Co. II; Construction Manager at Risk

Regular Construction Estimate No. Twenty-Two Page Two of Two

7/01/ 2022 through 7/31/ 2022

Prepared by: Selling Street St	Date:_	68-63-2022
Recommended by: John Michalski, P.E., ASI	Date: _	8/10/2022
Recommended by: Joel Brown, P.E. Oakland County WRC	Date: _	
Recommended by: Stephen Downing Stephen Downing; Macomb County OPWC	Date:	8/12/2022
Approved for Payment by:	Date: _	
Regular Construction Estimate No. 22 (July, 2022)	Approved By Board On:	

OAKLAND MACOMB INTERCEPTOR DRAIN DRAINAGE BOARD

For Construction of the NI-EA OMID Contract 1 - PCI 4 Rehabilitation Located in the City of Detroit, Wayne, Michigan Project ID 1-00000003308

Regular Construction Estimate No. 17			Period: 7/01/22 through 7/31/22		
	Department No.: Fund No.: Project No.:	84917	Account No.: Program No.: Activity:	731472 149015 FAC	
Contractor: Marra Services, Inc. 700 E. 73 rd. Street Cleveland, OH 44103		Vendor # 29656 Contrac LI # 44838 exp. 1/20/23	t # 6323 Date of Contract: Final Completion Date:	January 21, 2021 September 9, 2022	
Original Construction Contra	ct Amount			\$14,732,510.00	
Previous Change Orders: No	o. One and Two			\$808,198.88	
Change Orders This Estimat	e: None			\$0.00	
Total Net Change Orders:				\$808,198.88	
Adjusted Contract Amount:				\$15,540,708.88	
Sub-Total To Date				\$9,594,154.78	
Less Deductions: None				\$0.00	
Gross Estimate, Work in Pla	ce	(61.7% Complete)		\$9,594,154.78	
Less Amount Reserved (Ma	x. at 10% of 50% C	C.V.)		\$777,035.44	
Total Amount Allowed To Da	te:			\$8,817,119.34	
Less Previous Estimates				\$8,513,557.12	
Net Payment Request To Be	Paid To Contracto	or:		\$303,562.22	
Reserve Payment to Contract	tor:			\$0.00	
Balance to Finish: \$5,946,55 Amount to be Reserved from Less Previous Transfers To Amount of Current Transfer	Above		Accounting Auditor:	\$777,035.44 \$777,035.44 \$0.00	
Prepared by: Lawrence T. Gilbert, P.E., N. Recommended by: Saju Sachidanandan, P. E.;	TH Consultants Ltd		Date: Date:	8-8-2022	
Recommended by: Joel Brown, P.E. Oakland Co					
Recommended by: Stephen Downing; Macomb	then Down County OPWC	ring	Date:	8/12/2022	
Approved for Payment by: Sid Lockhart, P.E.; Special F	rojects Manager, C	 Dakland County WRC	Date:		
Regular Pay Estimate No. 17	' - July, 2022		Approved By Board On:		

Oakland-Macomb Interceptor Drain Drainage District

Regular Meeting – Wednesday, August 17, 2022

Agenda Item No. 8

Report/Update – Status of OMID Project, Segments 1 through 4, NESPS, NI-EA

Oakland Macomb Interceptor Drain (OMID) Repairs Project Progress Update

Prepared by:

F. Klingler, P.E., N. Kacynski, P.E., FK Engineering Assoc.

S. Sachidanandan, P.E., L. Gilbert, P.E., NTH Consultants, Ltd.

J. Michalski, P.E., Applied Science, Inc.; T. Moore, Metco Services, Inc.

J. Matteo, P.E., Jacobs Engineering, Inc.

August 17, 2022 OMIDDD Board Meeting

The following provides a status update as of the writing of this report (August 8, 2022) for the work completed for the Oakland-Macomb Interceptor Drain Repair Program (SRF Segments 1-4; Contract 7 PCI-4 repairs; Maintenance Repairs in PCI-5 through PCI-11A; Control Structure Modifications; NIEA Repairs; NESPS Upgrades; Odor/ Corrosion Control System, and other related work):

SRF Segment 1 Status:

Contracts 1&2: Complete

System-wide Odor/Corrosion Study

Project Budget Summary (including EWOs):

Adjusted Project Budget (including EWOs and Fan Testing Allowance): \$567,447.00
 Total Spent (through May 2021): \$566,441.58
 Additional Data Gathering Budget (under NTH): \$84,926.00
 Additional Data Gathering Expenditure to date: \$1,282.00

Status of Major Project Tasks:

• System-wide Odor/Corrosion Study and additional requested data gathering under Jacobs Engineering is substantially complete. Final Report, including updated analysis based on additionally gathered data, will be updated within the next several weeks.

SRF Segment 2 Status:

Contract 3 (Base Contract & C.O. 2E-2J): Complete

SRF Segment 3 Status:

Contract 4: Complete

August 17, 2022 OMIDDD Board Meeting

SRF Segment 4 Status:

Contract 5A/5B: Complete

• City of Utica Use Agreement for access paths is pending; awaiting final authorization.

Contract 6: Complete

Contract 7 (NIEA 110 feet of Emergency Rehab): Complete

NESPS Odor/Corrosion Control System (No Segment or Contract No.):

Construction Complete

NESPS & OMID Maintenance, Operations & Upgrades Status:

Status of Emergency Contingency Plan for pumping during total power loss or other catastrophic system failure:

- Mersino Dewatering is under contract for standby emergency bypass pumping.
- The OMIDDD Project Team has finalized an approach for keeping the 15 Mile Road bypass
 pumping arrangement (initially constructed in summer 2021) intact. Plans are now in place for
 the existing bypass piping remaining on site as a proposed below grade installation pending final
 agreement with ITC.
- Remaining items in the final emergency plan include punch-list and optimization steps for
 electrification, the modification of one manhole, modifications at the 15-Mile Road Site, and
 overall optimization of the Emergency Plan per above.

Additional work being performed under Metco Maintenance Contract for NESPS:

- Flow control operations related to OMID/MID/NIEA sewer repair and upgrade projects are ongoing.
- Mechanical and Electrical corrective/preventative maintenance schedules continue.
- Coordination between GLWA, MID, NESPS, and Pump/Electrical Upgrade Project has not affected station operations nor hindered performance or abilities to meet demands.
- Wet well sediment inspection and bar screen cleaning are now quarterly tasks. The
 Dry well (Main Elevator) final inspection is tentatively scheduled for August 11, 2022.
 All requirements have been addressed.
- Existing disabled Wet Well Elevator cleaning as part of its restoration has begun. (see photo).
- Wet well sediment inspection and bar screen cleaning are now quarterly tasks. The next sediment inspection will be performed in September, 2022.

August 17, 2022 OMIDDD Board Meeting

- The OMIDDD Project Team continues to review past wet well/bar screen data. This effort will be used in developing best practices maintaining overall de-ragging and sediment removal efforts. Options for future automated and/or optimized cleaning are being researched and considered.
- A NESPS Controls Workshop with the OMID team and GLWA is an ongoing process, designed around new operational parameters and control strategies.
- NESPS Health and Safety Plan finalized.

Overall NESPS Station Performance Report:

- Sanitary Pumps #2 #4, #5, and #6 ready for duty. Total pump capacity equals 500-cfs
- Specific data logging software has been installed within the Sanitary Pump #2 VFD drive PLC. Siemens maintains the ability to monitor VFD performance and fault/trip conditions. P2 VFD Pump and Motor has performed well since 2021 power cell restoration.
- Rotor integrated the existing Eaton Power Expert (Quality Power Monitoring Meter) located on the VFD Sanitary Pump #4 switchgear into the OMID SCADA system. No faults, voltage sags or spikes reported.
- Sanitary Pump #1 remains out of service as part of the upgrade project. The Pump #1 knife gate valve has been refurbished and installed. Field testing on the hydraulic actuation system in progress
- New transformer (T3) remains de-energized for permanent re-configuration. This outage is scheduled for 4-6 weeks.
 Utility transformer #4 will remain under load. Station is considered "single-ended."
 No issues to report.
- NEXGEN asset management in use. Monthly status meetings are being held with OMID. Contractors are fulfilling their requirements and no outstanding issues to report.
- Gas detection in use. Rounds are conducted daily. Unit filters restocked and changed as required. Last filter change 8-2-22. No issues to report.
- Bio Filter performance normal with no odor complaints or issues to report. Unit has
 performed well during the hot summer. Parameters checked daily and shared with
 Bio Aire on a weekly basis.
- No-Load test performed on Stand-by generators as part of the preventative maintenance schedules. No issues to report.
- Above ground storage tank Annual Inspection completed. (SP001) Inspection form to be turned over to GLWA as required. Inspection form on file (Nexgen)
- Overall General Housekeeping tasks in order. Minor maintenance activities addressed in a timely manner.



Wet well elevator

Control Structures Performance Report (CS-5, CS-6, CS-7, CS-8):

- Daily flow control operations now support MID/OMID/NIEA repair and improvement projects.
- All LOTO protocols are in-place with no major issues to report.
- System-wide communications are good.
- CS-6 gate remains out of service (not necessary for current flow control operations). As far as repair, Hesco reports that gate parts are in. Cylinder delivery scheduled for Aug 19th. Gate disc sandblasted and painted. Overall repair expected to take place by end of August.
- Preventative maintenance tasks are ongoing.
- CS-7 in stand-by mode ready for service; Bi-Annual Preventative Maintenance scheduled for Aug 12th.
- CS-8 in stand-by mode ready for service, Bi-Annual Preventative Maintenance scheduled for Aug 6th.
- CS-5 in stand-by mode ready for service; lower limit switch scheduled for installation Aug 19th.
- CS-9 in stand-by mode ready for service; minor oil leaks inside control cabinet has been reported and under investigation.
- Routine daily rounds and inspection made with no major maintenance issues to report.

Other System Operation Issues

- O&M Manual currently being revised to include new structures, recently modified structures, new monitoring equipment, and recent inspection and repair status.
- EGLE has informally agreed to consent to use of all flow control structures for long term flow control. Request for formal consent is promised but not yet received.

OMID Control Structure Upgrades Status:

 ASI is now contracted for design of major upgrades to control structures that considers longterm operability. Initial planning in process.

OMID System 3-Year Spot Repairs Status:

 Remaining 3-year spot repair work consists of step removal at one manhole in PCI-8, delayed due to access issues and timing of other work.

OMID System 6-Year Inspection Status:

- The 6-Year inspection began July 8, 2021. Flow Control delays have hampered inspections. Inspections of portions of PCI-7 were performed on June 21, 2022 and additional inspections are planned for the end of this month.
- Some damage noted to the CIPP Liner installed in 42" section of PCI-11A. Current plan is for Doetsch to remove the damaged section, grind the edges, and assess if anything more is necessary. Work has been delayed due to permit and access issues, as well as availability of work crews.

NIEA Repairs (Design/Construction)

Contract 1 (PCI-4 Rehabilitation): In Construction

Amt Invoiced: Construction cost to date is \$9,594,154.78 representing 61.7 % of the Contract

value.

Schedule Status: Current adjusted Substantial Completion date is December 2, 2022. Currently, the

Contractor is operating approximately 6 weeks behind the adjusted schedule, but anticipates this shortfall can be partially made up with productive lining and

grouting work now in the stages of regular production.

Contract 1 (PCI-4 Rehabilitation) Construction Status:

- Currently, 100% of the Channeline segments are now on site and being assembled, and 100% of the Rockhard SCP segments have been manufactured and also delivered to the jobsite. Progress continues on the QuakeWrap lining pipe at the Hastings, MI manufacturing facility.
- Initial adjustments to pipe carrier are complete and carrier is functioning properly.
- Initial transition section of Channeline lining segment is installed; bulkhead complete, and first few pipe sections have been installed, homed, and grouted in place. As of 8-5-22, 152.6 If of Channeline has been installed out of a total planned of 1,327 feet.
- Geotechnical monitoring of construction activities at the access shaft location indicates continuing stable conditions.



Channeline pipe being lowered into the Interceptor



Work on Discharge Chamber taper transition







Channeline pipe placement from behind pipe carrier

Contract 2 (PCI-18/19 Rehabilitation): Design Complete

Amt Invoiced: \$2,400,570 out of currently projected study/design budget of \$2,400,570;

Schedule Status: Contract 2: 100% design work complete; expected to bid in 2022 Q4 pending permit

and easement acquisition resolution and coordination with GLWA projects that

impact flow control requirements.

Contract 2 (PCI -18/19 Rehabilitation) Design Status:

- NI-EA OMID Contract No. 2 PCI-18 & 19 Rehabilitation 100% drawing set has been workshopped with OMIDDD and is ready for advertisement, pending GLWA agreement.
- Flow control measures necessary to complete Contract 2 work may impact a downstream GLWA
 project (DB-226). Contract 2 is being structured such that potential interference between the two
 contracts can be mitigated, and major interference is not expected at this time.
- Current City of Detroit permitting and easement issues are nearly resolved; certain follow-up issues remaining.
- Working with GLWA to develop cost sharing agreement; Draft agreement is currently being negotiated.

The draft line item schedule and budgets for OMID NIEA Contracts 1 and 2 are summarized:

Work Item/ Milestone	Estimated Budget	Estimated	Estimated Delivery Date
	Expenditure	Budget	
	(Engineering)	Expenditure	
		(Contractor)	
Lining Study Final Report	\$126,744		10/30/2019
90%, 100% Design Package			3/20/2020 and 4/28/2020 (Contract 1)
			4/16/2021* and TBD* (Contract 2)
MDEQ Submittal (Part 41)			4/28/2020 (Contract 1)
			Pending* (Contract 2)
Issued for Bid			6/10/2020 (Contract 1)
			TBD* (Contract 2)
Bid Opening			9/30/2020 (Contract 1)
			TBD* (Contract 2)
Contract Award and NTP			12/16/2020 and 1/04/2021 (Contract 1)
			TBD* (Contract 2)
Subtotal - Design	\$2,400,570		
Final Completion of Construction	\$3,500,000	\$35,000,000	12/2/2022 (Contract 1)
			8/30/2024 (Contract 2, estimated)

NESPS Pump and Electrical Upgrades Project

Budget Status:

\$1,280,139 billed out of current Design Budget of \$1,382,430; \$968,018 out of the current CCA Budget of \$2,443,262. Total construction budget currently established as \$46,187,996.94, including contingencies, through proposed C.O. #23. The total construction amount invoiced to date as of June 30, 2022, is \$31,175,442.80 (including the now completed and operational Control Structure 9 Bulkhead Gate facility, and adjusted for stored material inclusion in major work activities), representing 66.7% of the combined project (Pump & Electrical Upgrades and CS-9 Gate Installation).

Schedule Status:


Currently work is approximately 5 months late, resulting from a combination of supply chain issues and other issues. Contractor is working on an enhanced schedule to make up time but will likely be unable to meet the scheduled completion date. Discussions for additional time and/or schedule adjustments are pending. The Contractor is also working an adjusted time shift schedule to cooperate with the NIIEA C-1 Project for mutual Flow Control needs.


The following Design Team and Construction Services Effort is active:


- The new Sewage Pump # 3 and Motor has now been delivered to the NESPS and is substantially installed. Factory performance tests have been conducted with each separate component, and the pump and motor assembly are being re-tested in place at the NESPS. Pump 3 began start up "wet" testing in mid-July. While the pump and motor performed satisfactorily, special componentry of the motor "exciters" was determined to require replacement; parts are expected to arrive by 2nd. Week of August, 2022.
- Sewage Pump and Motor No. 1 is following closely behind Pump 3 and near substantially installed. Factory performance tests were conducted with each separate component, and the pump and motor assembly will be re-tested at the NESPS. Pump 1 startup "wet" testing was

- planned for mid-august, although, special componentry of the motor "exciters" was determined to require replacement; parts are expected to arrive by 2nd. Week of August 2022.
- Electrical work on the primary cable installation from the transformers to the new metal clad switchgear is complete.
- A review of alternative energy saving methods and pump sequence remains ongoing, incorporating GLWA SCC comments.
- Construction Phase services (RFIs, Submittals) are ongoing, and the engineering team is reviewing and responding.
- Discharge piping work is complete on Pumps # 1 and # 3, including pressure testing.
- Chemical injection to seal groundwater infiltration at the existing discharge pipe wall
 penetrations is substantially complete, with final efforts on hold to observe the initial stages of
 grouting and determine if further measures may be required for final leak control.
- Small diameter conduit runs are being installed in the existing NESPS building with favorable progress, now approaching substantial completion for this activity.
- Knife Gate 1 is refurbished and has been reinstalled on site and available for service.
- Steel discharge piping for Pumps 5 and 6 is now at the Toledo, OHG facility for sand blast preparation and painting.
- The **draft** line item schedule and budget are summarized:

Wo	rk Item/ Milestone	Design/CCA Budget	Const Budget	Estimated Delivery Date
2	Final Basis of Design			5/31/2019
7	MDEQ Submittal (Part 41 Permit)			4/8/2020 (initial pkg)
8	90% Design Submittal			6/30/20
9	Final Package Development			8/14/2020
	Subtotal	\$3,826,000	\$44,100,000	
10	Substantial Completion	\$2,500,000 (est.)	\$44,100,000 (est.)	9/22/2023 (late)
11	Final Completion			12/21/2023 (late)







NESPS Interior

CS-9 Gate Installation

Budget Status: Total construction budget currently established as approximately

\$3,314,218.01

Schedule Status: Construction complete;

Repairs pending

The following work is active:

• All major work is complete and the Hydrogate gate is in regular use for flow control management.

- Site restoration is substantially complete and will be fully completed following Hobas Repairs.
- Doetsch Environmental is engaged to provide Hobas Lining repair and platform repair services. Repairs are now being scheduled with insurance carrier approval




CS-9 Project location


Summary of OMID Design and Construction Status:

		Work In Construc	ction Since 2	2009			
Seg. No	Contract No. (Description)	Contractor	Const.	As-Builts Final?	Balancing Change Order?	Contractor Closed Out?	Easements Settled?
1	Contract 1 (CS-9, 5, 3)	Ric-Man	Υ	Υ	Υ	Υ	Υ
1	Contract 2 (CS-6, 7, 8)	Ric-Man	Υ	Υ	Υ	Υ	Υ
2	Contract 3-2E (Gatehouse)	IWPC (Weiss)	Υ	Υ	Υ	Υ	N/A
2	Contract 3 (Grouting PCI-5 thru 8)	IWPC	Υ	Υ	Υ	Υ	Υ
3	Contract 4 (Lining PCI-5 thru 8)	Jay Dee Cont.	Υ	Υ	Υ	Υ	Υ
4	Contract 5 (Lining PCI-9, 10A/B)	Lanzo	Υ	Υ	Υ	Υ	N
4	Contract 6 (Lining PCI-11A)	Lanzo	Υ	Υ	Υ	Υ	Υ
N/A	Contract 7 (Lining 110' of NIEA)	IWPC	Υ	Υ	Υ	Υ	N/A
N/A	Odor/Corrosion Control System	CSM	Υ	Υ	Υ	Υ	N/A
N/A	Control Structure Modifications	CSM/Hesco/MCE	Y/Y/Y	Y/Y/N	Y/Y/N	Y/Y/N	N/A
N/A	OMID Maintenance Repairs	Doetsch	Υ	N	N	N	N/A
N/A	CS-9 Gate Modifications	Walsh as CMR	Υ	N	N	N	Υ
N/A	NESPS Pump & Electrical Upgrade	ASI;Walsh as CMAR	N	N	N	N	Υ
N/A	NIEA-OMIDDD Contract 1 (PCI-4)	Marra	N	N	N	N	N

	Work Currently in Design/Stud	y/Engineering
Description	Design Consultant	Status
System-wide Odor/Corrosion Study	Jacobs	Study Complete, final report pending
NESPS & OMID Maintenance & Repairs	Metco	Engineering/Maintenance Ongoing
NIEA-OMIDDD Contract 2 (PCI-18/19)	NTH	Design Complete; pursuing cost sharing w/ GLWA
Emergency Pumping Plan	ASI/FKE	Draft Plan to be modified following ITC bypass pumping modifications



Overview of OMID System in Oakland, Macomb, and Wayne County



MID/OMID Construction Schedule

		_			Π	2022		Т			-	2023				Т	MID/	ОМІС	Cont	rol De	evices	Requ	ired to	o Stor	e Flo	w	
Project	Work Location	Owner	Lead Engineer	Contractor	A S	О	N D	L	FN	ИΑ	м.	J	Α	s o	N C	CS-2	CS-S	3 CS-	-5 CS		S-6 PS	CS-7	CS-8	CS-9	CS-12	CPS	Concurrent Work Notes
MID Grouting Garfield Interceptor	Lakeshore Interceptor (LSI)	MID	AEW	Doetsch	/			П								-		-					-		n/a	N	Work is Random - If other work requires CS-3 closure, then LSI work will be concurrent. CPS can not be used for storage. Schedule duration is TBD based on grout takes. Present work in in the Garfield.
MID Inspection	Routine Inspection of MID Manholes & Interceptors	MID	Fishbeck	Doetsch												-		-	-		-	-	-		n/a		Work may require breief flow control to inspect certain reaches. Work will be coordinated around active construction.
Segment 6 Lining	15 Mile upstream of Garfield (15 Mile Interceptor)	MID	FKE	Ric-Man	$/\!/$	$^{\prime\prime}$	//	$^{\prime\prime}$	//	//						-	-		-		-	-	-			Y	Flow control on pause but upcoming. May work concurrent with Segment 5 or NIEA rehabilitation. Schedule is preliminary.
Segment o Dining	15 Mile upstream of Garfield & between CS-2/CS-3 (Romeo Arm)	MID	FKE	Ric-Man	//	//	//	$^{\prime}/$	//	//						Y	Y	N			-	-	-		Y	Y	May work concurrent with Segment 5 or NIEA rehabilitation. Flow control conditions at the CS gates i similar with the exception of utilizing CS-2. Schedule is preliminary.
Segment 5 Lining*	15 Mile between ITC Corridor & Eberlein	MID	FKE	OR	//	//	//	//		//	//					-	Y	N	Y		-	Y	Y	-	Y	Н	If work is concurrent with NIEA rehabilitation; CS-9 is required. Flow control dates may change depending on sediment removal means and methods. Current projected finish is 2 months late.
NIEA Rehabilitation	PCI-4 Shaft & Lining	OMID	NTH	MARRA	$/\!/$	$\langle \rangle$	//									-	Y	N	Y		-	Y	Y	*		Н	If work is concurrent with Segments 5 & 6 Lining; CS-9 is required.
(Downstream of NESPS)	PCI-18/19 Spot Repairs, Lining, and Flow Controls	OMID	NTH	TBD												-	-		-		-	-	-				Shaft construction. MID/OMID flow control may be required depending on 7-Mile Relief Inter- Connection and PC-663 Gate status. Coordination with GLWA and downstream system when flow is
OMID CCTV Inspection	Throughout System	OMID	NTH	Doetsch												-	Y	Y	Y		-	Y	Y		n/a	н	Present work is in upstream manholes so limited flow control necessary. Flow control will be required within certain reaches to facilitate.
CS-9 Gate Installation & Hobas Repair	CS-9	OMID	NTH	Walsh		//										-	Y	Y	Y		-	Y	Y	Y	n/a	Н	Hobas Repair Moved to Spring.
NESPS Improvements	NESPS Pump Replacement	OMID	ASI	Walsh												-	Y	-	Y		-	Y	Y	Υ		Н	Will require brief flow control for pump installation, gate installation, and electrical work.
DB-226 DRI Repairs	GLWA - DRI	GLWA	FKE	Jay Dee												-	-	-	-		-	-	-				Can be effected by flows rerouted from the NIEA to the DRI.
CS-6 Gate Repairs	CS-6 CS	OMID	NTH	HESCO		//										-	Y	Y	Y		-	Y	Y	Y	n/a	Н	Schedule to be confirmed.
Rigid Seal Study	NESPS Discharge Chamber	OMID	NTH	TBD		//										-	Y	Y	Y		-	Y	Y	Υ	n/a	Н	Schedule to be confirmed. Reuires 2-3 Days
Inspection and Repair of Discharge Chamber Riser	NESPS Discharge Chamber	OMID	NTH	TBD		//										-	Y	Y	Y		-	Y	Y	Y	n/a	н	Schedule to be confirmed.
PSPS / COSDS Work (PSPS Shutdown)	PSPS	WRC	n/a	n/a												-	-	-				-	-		-		Diversion to PSPS is 5MGD (May increase to 10MGD this Fall). Scheduled shut down of PSPS in September; no flow diversion to Pontiac WWTP (CRWRRF). Will significantly impact storage capabilities on the Oakland Arm CS gates.

Table updated on 8/1/2022. Estimates to be updated as necessary.

Y = Required to store

* Flow control will be required for sewer lining (Schedule TBD). Flow control CS requirements are defined in the "Control Devices Required to Store Flow" section. PSPS and ELPS operations can significantly impact storage times upstream of CS-6, 7 & 8 and subsequently downstream control structures. Coordination & alerting for ELPS, PSPS, WRC Meters 1222/1223 & 1000 required.

| Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required | Flow Control May Be Required |

Note CS-6 is currently out of service

Summary of OMID Flow Control Requirements for Ongoing and Future Projects

H = Helpful to extend work times. If available when not required for concurrent work.

^{*} Flow control will be required for sewer deaning, currently estimated in 2022. Flow control requirements are TBD based on contractor means & methods, not reflected in "Control Devices Required to Store Flow" sectio: -= Irrelevant

Oakland-Macomb Interceptor Drain Drainage District

Regular Meeting – Wednesday, August 17, 2022

Agenda Item No. 9

Financial Reports – General Financial Report and Status of State Revolving Fund Financing and Other Financing **OCM Project Work In Progress**

Company Oakland County

Projects and Project Hierarchies PRJ-13308 OMID NI-EA CONSTRUCTION

Budget Structure Project Task

Budget Name

Period FY2022 - Jul

Project	Start Date	Final Budget	Actuals MTD	Obligations	Actuals YTD	Total Spend	Actuals LTD	Variance
Project Expenses	11/1/2020	28,395,600.00	643,353.77	162,370.72	19,839,802.44	20,002,173.16	19,839,802.44	8,555,797.56
1 > Administration		584,000.00	0.00	0.00	0.00	0.00	0.00	584,000.00
1 > Contingency		2,581,000.00	0.00	0.00	0.00	0.00	0.00	2,581,000.00
1 > Engineering		478,000.00	3,260.89	0.00	143,306.84	143,306.84	143,306.84	334,693.16
1 > Engineering Consultants		4,913,000.00	253,954.96	(13,393.61)	3,694,208.54	3,680,814.93	3,694,208.54	1,218,791.46
1 > Facility Acquisition		17,983,600.00	331,260.10	0.00	15,528,310.29	15,528,310.29	15,528,310.29	2,455,289.71
1 > Inspection		260,000.00	0.00	0.00	0.00	0.00	0.00	260,000.00
1 > Legal and Financial		1,259,000.00	1,269.00	918.00	156,269.90	157,187.90	156,269.90	1,102,730.10
1 > Right of Way		265,000.00	0.00	0.00	91,765.02	91,765.02	91,765.02	173,234.98
1 > Standard		40,000.00	53,608.82	174,846.33	225,941.85	400,788.18	225,941.85	(185,941.85)
1 > Survey		32,000.00	0.00	0.00	0.00	0.00	0.00	32,000.00
Project Revenues	11/1/2020	0.00	0.00	0.00	24,171,142.65	(24,171,142.65)	24,171,142.65	
RC605572 - Special		0.00	0.00	0.00	2,206,043.00	(2,206,043.00)	2,206,043.00	
RC697551 - Issuance of Bonds		0.00	0.00	0.00	21,965,099.65	(21,965,099.65)	21,965,099.65	
Revenue Over/ (Under) Expenses							4,331,340.21	

OCM Project Work In Progress

Company Oakland County

Projects and Project Hierarchies PRJ-13309 NESPS MECH-ELEC CONSTRUCTION

Budget Structure Project Task

Budget Name

Period FY2022 - Jul

Project	Start Date	Final Budget	Actuals MTD	Actuals YTD	Total Spend	Actuals LTD	Variance
Project Expenses	11/1/2020	54,086,000.00	4,062,123.20	36,322,077.32	36,322,077.32	36,322,077.32	17,763,922.68
1 > Administration		620,000.00	0.00	44,200.00	44,200.00	44,200.00	575,800.00
1 > Contingency		4,917,000.00	0.00	0.00	0.00	0.00	4,917,000.00
1 > Engineering		446,000.00	8,859.15	234,966.85	234,966.85	234,966.85	211,033.15
1 > Engineering Consultants		3,987,000.00	88,460.52	1,937,441.65	1,937,441.65	1,937,441.65	2,049,558.35
1 > Facility Acquisition		40,857,000.00	3,600,132.78	32,779,180.10	32,779,180.10	32,779,180.10	8,077,819.90
1 > Inspection		285,000.00	5,623.85	449,915.35	449,915.35	449,915.35	(164,915.35)
1 > Legal and Financial		2,417,000.00	0.00	179,800.00	179,800.00	179,800.00	2,237,200.00
1 > Right of Way		393,000.00	0.00	0.00	0.00	0.00	393,000.00
1 > Standard		130,000.00	359,046.90	696,573.37	696,573.37	696,573.37	(566,573.37)
1 > Survey		34,000.00	0.00	0.00	0.00	0.00	34,000.00
Project Revenues	11/1/2020	0.00	0.00	46,039,857.01	(46,039,857.01)	46,039,857.01	
Revenue		0.00	0.00	4,202,235.00	(4,202,235.00)	4,202,235.00	
RC697551 - Issuance of Bonds		0.00	0.00	41,837,622.01	(41,837,622.01)	41,837,622.01	
Revenue Over/ (Under) Expenses					_	9,717,779.69	

OCM Project Work In Progress

Company Oakland County

Projects and Project Hierarchies PRJ-13252 OMID Segment 5

Budget Structure Project Task

Budget Name

Period FY2022 - Jul

Project	Start Date	Actuals MTD	Actuals YTD	Total Spend YTD	Actuals LTD
Project Expenses	8/1/2020	0.00	749,670.65	749,670.65	749,670.65
1 > Administration		0.00	242,201.57	242,201.57	242,201.57
1 > Legal and Financial		0.00	514,935.00	514,935.00	514,935.00
1 > Standard		0.00	(7,465.92)	(7,465.92)	(7,465.92)
Project Revenues	8/1/2020	0.00	1,846,608.41	(1,846,608.41)	1,846,608.41
Revenue		0.00	108,835.74	(108,835.74)	108,835.74
Adjustments		0.00	(161,449.04)	161,449.04	(161,449.04)
Investments		0.00	814,218.62	(814,218.62)	814,218.62
Sold		0.00	7,672,724.75	(7,672,724.75)	7,672,724.75
RC697551 - Issuance of Bonds		0.00	(6,587,721.66)	6,587,721.66	(6,587,721.66)
Revenue Over/ (Under) Expenses				<u> </u>	1,096,937.76

OAKLAND MACOMB INTERCEPTOR DRAINAGE BOARD - APPROVAL OF INVOICES/REIMBURSEMENTS

OMI DD Meeting Date 8/17/2022

		84917	84917	82912	
		1-3308	1-3309		
Payable To	Invoice #	Segment 5 NIEA Construction	Segment 5 NESPS Mech / Electric Construction	Opperations & Maintanence	<u>Total</u>
Oakland County *	WRC Labor/Fringes/Non-direct Labor	9,168.34	56,255.90		\$65,424.24
Oakland County *	WRC Equipment	188.72	407.14		\$595.86
Applied Science, Inc	Invoice # 42 (ASI Inv. #8199) Services 06/26/22 to 07/30/22		113,280.89		\$113,280.89
Clark Hill PLC	Invoice # 1220403 Matter 424741 Services Through 06/30/2022			13,608.00	\$13,608.00
Clark Hill PLC	Invoice # 1220405 Matter 404547 Services Through 06/30/2022	135.00			\$135.00
Dickinson Wright PLLC	Invoice # 1715594 Matter 012840-00436 Service through 06/30/2022			1,619.50	\$1,619.50
HESCO	Invoice # 2213786 Preventative Maintenance 07/07/2022			4,016.75	\$4,016.75
Jaobs Consultants, Inc.	Invoice # C6A19900-02 OMIDD Odor & Corrosion Faciloities 5/28/22 - 6/24/22			70,618.37	\$70,618.37
Kenedy Industries	Invoice # 630978 - 1 NESPS Field Service 04/29/22			1,518.00	\$1,518.00
Kenedy Industries	Invoice # 631969 NESPS Field Service 06/28/22			1,040.95	\$1,040.95
METCO	Invoice # 1811-43 Through 07/31/22			80,733.91	\$80,733.91
Motor City Electric Technologies	Invoice # 94500 NESP SCADA Cut Over Service Date 05/19/22			351.00	\$351.00
Motor City Electric Technologies	Invoice # 94596 NESP SCADA Cut Over Service Date 07/18/22			252.00	\$252.00
NTH Consultants	Invoice # 630201 Enigineering Design NI-EA PCI-4 Through 07/22/2022	1,663.50			\$1,663.50
NTH Consultants	Invoice # 6302024 (D-425) Engineering Srvices Through 07/22/2022	68,698.49			\$68,698.49
NTH Consultants	Invoice # 630204 (D-421) Engineering Design NESPS Through 07/22/2022		1,029.71		\$1,029.71
NTH Consultants	Invoice # 630205 2021 OMIDD System Inspection Through 07/22/2022			1,328.50	\$1,328.50
NTH Consultants	Invoice # 630206 NESPS Close-Out & Maintenance Tasks Through 07/22/2022			603.73	\$603.73
NTH Consultants	Invoice # 630207 Engineering Work D 439 & NESPS Maintenance Through 07/22/2022			929.69	\$929.69
Rotor Electric Company	Invoice # 12530 P4 Loto For Pumo Inpectiom 07/13/22			1,569.00	\$1,569.00
Rotor Electric Company	Invoice # 12531 P2 VFD Fan Motors 07/01/22			7,082.93	\$7,082.93
Rotor Electric Company	Invoice # 12532 P5Brush Holders 07/01/22			2,357.42	\$2,357.42
	Total Invoices/Reimbursements for Approval	\$79,854.05	\$170,973.64	\$187,629.75	\$438,457.44
	* Less WRC Charges already paid from OMI Fund	(9,357.06)	(56,663.04)	0.00	(66,020.10)
Total Invoices/Reimbursements th	at will impact Cash Balance listed on Current Trial Balance submitted to OMI Drain Board	\$70,496.99	\$114,310.60	\$187,629.75	\$372,437.34

Oakland-Macomb Interceptor Drain Drainage District

Regular Meeting – Wednesday, August 17, 2022

Agenda Item No. 10

Invoices

OMI Segi	ment 5 NESP M	lech - Elect Co	nstruction Project - WRC Labor	/Fringes/Non-D	irect Labor Facto	or for Trans Date	s - 04/23/2022 - 07/1	5/2022	
WOID	Date Entered	Date Worked	Name/Description	Hours/Units	Cost	Cost Category	Assign Equipment	Project	Activity
1094849	05/11/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	05/11/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	05/11/22		BROWN, JOEL	4.00		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	05/11/22		BROWN, JOEL	2.50		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849 1094849	05/11/22 05/11/22		BROWN, JOEL BROWN, JOEL	1.00 4.00		REGULAR REGULAR	WRCCON WRCCON	PRJ-13309 PRJ-13309	ENGINEERING ENGINEERING
1094849	05/26/22		BROWN, JOEL	1.50		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	05/26/22		BROWN, JOEL	1.50		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	05/26/22		BROWN, JOEL	3.50		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	05/26/22		BROWN, JOEL	2.00		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	05/26/22		BROWN, JOEL	1.00	125.45	REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	05/26/22	05/18/22	BROWN, JOEL	2.00		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	05/26/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	05/26/22		BROWN, JOEL	2.00		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	06/20/22		BROWN, JOEL	1.50		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849 1094849	06/20/22 06/20/22		BROWN, JOEL BROWN, JOEL	0.50 1.00		REGULAR REGULAR	WRCCON WRCCON	PRJ-13309 PRJ-13309	ENGINEERING ENGINEERING
1094849	06/20/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	06/20/22		BROWN, JOEL	0.50		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	06/20/22		BROWN, JOEL	0.50		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	06/20/22		BROWN, JOEL	2.00		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	06/20/22	06/02/22	BROWN, JOEL	5.00	627.25	REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	06/20/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	06/20/22		BROWN, JOEL	4.00		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	06/20/22		BROWN, JOEL	2.50		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	06/20/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849 1094849	06/20/22 06/20/22		BROWN, JOEL BROWN, JOEL	2.00 4.00		REGULAR REGULAR	WRCCON WRCCON	PRJ-13309 PRJ-13309	ENGINEERING ENGINEERING
1094849	06/20/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13309 PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	1.50		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	3.00		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	07/12/22	06/24/22	BROWN, JOEL	1.50		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	07/12/22	06/27/22	BROWN, JOEL	3.00	376.35	REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	2.00		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	7.50		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094849	07/12/22	07/01/22	BROWN, JOEL	1.50		REGULAR	WRCCON	PRJ-13309	ENGINEERING
1094845	07/01/22	06/30/22	BROWN, JOEL Total CARLEY, JOSEPH	0.50	9,596.99	OVERTIME	WRCCDM	PRJ-13309	INSPECTION
1094845	04/27/22		CARLEY, JOSEPH	1.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	04/27/22		CARLEY, JOSEPH	1.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	04/29/22		CARLEY, JOSEPH	1.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	04/29/22		CARLEY, JOSEPH	1.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	05/03/22		CARLEY, JOSEPH	4.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	05/05/22		CARLEY, JOSEPH	1.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	05/13/22		CARLEY, JOSEPH	2.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845 1094845	05/18/22 05/26/22		CARLEY, JOSEPH CARLEY, JOSEPH	1.50		REGULAR REGULAR	WRCCDM WRCCDM	PRJ-13309 PRJ-13309	INSPECTION INSPECTION
1094845	06/03/22		CARLEY, JOSEPH	5.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	06/07/22		CARLEY, JOSEPH	1.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	06/14/22	06/13/22	CARLEY, JOSEPH	1.00	81.65	REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	06/21/22		CARLEY, JOSEPH	1.50		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	06/24/22		CARLEY, JOSEPH	1.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	06/27/22		CARLEY, JOSEPH	4.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	07/01/22	06/30/22	CARLEY, JOSEPH Total	1.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	06/28/22	06/27/22	IGNASH, MICHAEL	3.00	2,333.67	OVERTIME	WRCCDM	PRJ-13309	INSPECTION
1094845	06/29/22		IGNASH, MICHAEL	3.00		OVERTIME	WRCCDM	PRJ-13309	INSPECTION
1094845	06/29/22		IGNASH, MICHAEL	3.00		OVERTIME	WRCCDM	PRJ-13309	INSPECTION
1094845	06/30/22	06/30/22	IGNASH, MICHAEL	3.00	271.20	OVERTIME	WRCCDM	PRJ-13309	INSPECTION
1094845	07/01/22		IGNASH, MICHAEL	1.50		OVERTIME	WRCCDM	PRJ-13309	INSPECTION
1094845	07/05/22		IGNASH, MICHAEL	3.00		OVERTIME	WRCCDM	PRJ-13309	INSPECTION
1094845	07/06/22		IGNASH, MICHAEL	3.00		OVERTIME	WRCCDM	PRJ-13309	INSPECTION
1094845	07/07/22		IGNASH, MICHAEL	1.50		OVERTIME	WRCCDM	PRJ-13309	INSPECTION
1094845 1094845	07/08/22 06/27/22		IGNASH, MICHAEL IGNASH, MICHAEL	2.00 8.00		OVERTIME REGULAR	WRCCDM WRCCDM	PRJ-13309 PRJ-13309	INSPECTION INSPECTION
1094845	06/27/22		IGNASH, MICHAEL	8.00		REGULAR	WRCCDM	PRJ-13309 PRJ-13309	INSPECTION
1094845	06/29/22		IGNASH, MICHAEL	8.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	06/30/22		IGNASH, MICHAEL	8.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	07/01/22		IGNASH, MICHAEL	8.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	07/05/22	07/05/22	IGNASH, MICHAEL	8.00	622.08	REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	07/06/22		IGNASH, MICHAEL	8.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	07/07/22		IGNASH, MICHAEL	8.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	07/08/22	07/08/22	IGNASH, MICHAEL	8.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1004040	05/00/00	04/05/00	IGNASH, MICHAEL Total	4.00	7,677.92	DECLUAD	W/DCADM	DD I 42200	ENCINEEDING
1094849 1094849	05/06/22 05/06/22		LOCKHART, SIDNEY LOCKHART, SIDNEY	1.00 2.00		REGULAR REGULAR	WRCADM WRCADM	PRJ-13309 PRJ-13309	ENGINEERING ENGINEERING
1094849	05/06/22		LOCKHART, SIDNEY	2.00		REGULAR	WRCADM	PRJ-13309 PRJ-13309	ENGINEERING
100-10-13	00/00/22	UT/21/22	LOCKI II II CI , OIDINE I	2.00	212.14	I L COLAIN	**************************************	1 10 10000	LINGHALLINING

1001010	05/00/00	0.4/00/00	LOOKUART OIRNEY	0.00	070 74 DEOLU	D JAKDOADA	DD 1 40000	TENIONIEEDINIO
1094849	05/06/22		LOCKHART, SIDNEY	2.00	272.74 REGULA		PRJ-13309	ENGINEERING
1094849	05/06/22	05/02/22	LOCKHART, SIDNEY	1.00	136.37 REGULA	AR WRCADM	PRJ-13309	ENGINEERING
1094849	05/06/22	05/03/22	LOCKHART, SIDNEY	2.00	272.74 REGULA	AR WRCADM	PRJ-13309	ENGINEERING
1094849	05/06/22		LOCKHART, SIDNEY	2.00	272.74 REGULA		PRJ-13309	ENGINEERING
1094849	05/06/22		LOCKHART, SIDNEY	1.00	136.37 REGULA		PRJ-13309	ENGINEERING
1094849	05/06/22	05/06/22	LOCKHART, SIDNEY	2.00	272.74 REGULA	AR WRCADM	PRJ-13309	ENGINEERING
1094849	05/23/22	05/09/22	LOCKHART, SIDNEY	2.00	272.74 REGULA	AR WRCADM	PRJ-13309	ENGINEERING
1094849	05/23/22		LOCKHART, SIDNEY	2.00	272.74 REGULA		PRJ-13309	ENGINEERING
1094849	05/23/22		LOCKHART, SIDNEY	2.00	272.74 REGULA		PRJ-13309	ENGINEERING
1094849	06/06/22		LOCKHART, SIDNEY	2.00	272.74 REGULA	AR WRCADM	PRJ-13309	ENGINEERING
1094849	06/06/22	05/27/22	LOCKHART, SIDNEY	2.00	272.74 REGULA	AR WRCADM	PRJ-13309	ENGINEERING
1094849	06/17/22	06/07/22	LOCKHART, SIDNEY	2.00	272.74 REGULA		PRJ-13309	ENGINEERING
		00/01/22	LOCKHART, SIDNEY		136.37 REGULA		PRJ-13309	
1094849	06/17/22	06/08/22	LOCKHART, SIDNEY	1.00				ENGINEERING
1094849	06/17/22	06/13/22	LOCKHART, SIDNEY	2.00	272.74 REGULA		PRJ-13309	ENGINEERING
1094849	06/17/22	06/14/22	LOCKHART, SIDNEY	2.00	272.74 REGULA	AR WRCADM	PRJ-13309	ENGINEERING
1094849	07/01/22	06/21/22	LOCKHART, SIDNEY	1.00	136.37 REGULA		PRJ-13309	ENGINEERING
1094849	07/01/22		LOCKHART, SIDNEY	1.00	136.37 REGULA		PRJ-13309	ENGINEERING
		06/22/22	LOCKHART, SIDNET					
1094849	07/01/22		LOCKHART, SIDNEY	1.00	136.37 REGULA		PRJ-13309	ENGINEERING
1094849	07/01/22	06/28/22	LOCKHART, SIDNEY	1.00	136.37 REGULA	AR WRCADM	PRJ-13309	ENGINEERING
1094849	07/01/22	06/29/22	LOCKHART, SIDNEY	2.00	272.74 REGULA		PRJ-13309	ENGINEERING
1094849	07/01/22	06/20/22	LOCKHART, SIDNEY	1.00	136.37 REGULA		PRJ-13309	ENGINEERING
1094849	07/15/22		LOCKHART, SIDNEY	2.00	272.74 REGULA		PRJ-13309	ENGINEERING
1094849	07/15/22	07/07/22	LOCKHART, SIDNEY	2.00	272.74 REGULA	AR WRCADM	PRJ-13309	ENGINEERING
1094849	07/15/22	07/11/22	LOCKHART, SIDNEY	2.00	272.74 REGULA		PRJ-13309	ENGINEERING
1094849	07/15/22	07/12/22	LOCKHART, SIDNEY	2.00	272.74 REGULA		PRJ-13309	ENGINEERING
		07/12/22	LOOKHART CIRVEY					
1094849	07/15/22		LOCKHART, SIDNEY	2.00	272.74 REGULA		PRJ-13309	ENGINEERING
1094849	07/15/22	07/14/22	LOCKHART, SIDNEY	1.00	136.37 REGULA	AR WRCADM	PRJ-13309	ENGINEERING
			LOCKHART, SIDNEY Total		6,818.50			
1004045	07/15/22	07/05/22	POUSHO. ROBERT	9.00		ND WDCCON	DD I 12200	INSPECTION
1094845			, -	8.00	437.28 REGULA		PRJ-13309	
1094845	07/15/22		POUSHO, ROBERT	8.00	437.28 REGULA		PRJ-13309	INSPECTION
1094845	07/15/22		POUSHO, ROBERT	8.00	437.28 REGULA	AR WRCCON	PRJ-13309	INSPECTION
1094845	07/15/22	07/14/22	POUSHO, ROBERT	8.00	437.28 REGULA	AR WRCCON	PRJ-13309	INSPECTION
100.0.0	017.0722	0.7.1.722	POUSHO, ROBERT Total	0.00	1,749.12	missen		
1001015	0.4/0.0/0.0	0.4/05/00		4.00		145	DD 1 40000	INCORPORTION
1094845	04/26/22		ROBERTS, PATRICK	1.00	82.00 OVERTI		PRJ-13309	INSPECTION
1094845	04/27/22		ROBERTS, PATRICK	1.00	82.00 OVERTI	ME WRCCDM	PRJ-13309	INSPECTION
1094845	04/27/22	04/27/22	ROBERTS, PATRICK	1.00	82.00 OVERTI	ME WRCCDM	PRJ-13309	INSPECTION
1094845	04/28/22	04/28/22	ROBERTS, PATRICK	2.00	164.00 OVERTI		PRJ-13309	INSPECTION
		04/20/22	ROBERTO, PATRICK					
1094845	04/29/22		ROBERTS, PATRICK	1.00	82.00 OVERTI		PRJ-13309	INSPECTION
1094845	05/02/22		ROBERTS, PATRICK	1.00	82.00 OVERTI	ME WRCCDM	PRJ-13309	INSPECTION
1094845	05/04/22	05/04/22	ROBERTS, PATRICK	1.00	82.00 OVERTI	ME WRCCDM	PRJ-13309	INSPECTION
1094845	05/05/22	05/05/22	ROBERTS, PATRICK	2.00	164.00 OVERTI		PRJ-13309	INSPECTION
1094845	05/06/22		ROBERTS, PATRICK	1.00	82.00 OVERTI		PRJ-13309	INSPECTION
1094845	05/09/22	05/09/22	ROBERTS, PATRICK	1.00	82.00 OVERTI	ME WRCCDM	PRJ-13309	INSPECTION
1094845	05/10/22	05/10/22	ROBERTS, PATRICK	1.00	82.00 OVERTI	ME WRCCDM	PRJ-13309	INSPECTION
1094845	05/11/22	05/11/22	ROBERTS, PATRICK	2.00	164.00 OVERTI		PRJ-13309	INSPECTION
1094845	05/12/22		ROBERTS, PATRICK	2.00	164.00 OVERTI		PRJ-13309	INSPECTION
1094845	05/13/22	05/13/22	ROBERTS, PATRICK	2.00	164.00 OVERTI		PRJ-13309	INSPECTION
1094845	05/14/22	05/14/22	ROBERTS, PATRICK	10.00	820.00 OVERTI	ME WRCCDM	PRJ-13309	INSPECTION
1094845	05/15/22		ROBERTS, PATRICK	9.00	738.00 OVERTI		PRJ-13309	INSPECTION
1094845	05/16/22		ROBERTS, PATRICK	1.00	82.00 OVERTI		PRJ-13309	INSPECTION
1094845	05/18/22		ROBERTS, PATRICK	1.00	82.00 OVERTI		PRJ-13309	INSPECTION
1094845	05/19/22	05/19/22	ROBERTS, PATRICK	2.00	164.00 OVERTI	ME WRCCDM	PRJ-13309	INSPECTION
1094845	05/20/22		ROBERTS, PATRICK	1.00	82.00 OVERTI		PRJ-13309	INSPECTION
1094845	05/23/22		ROBERTS, PATRICK		82.00 OVERTI		PRJ-13309	INSPECTION
				1.00				
1094845	05/25/22		ROBERTS, PATRICK	1.00	82.00 OVERTI		PRJ-13309	INSPECTION
1094845	05/26/22	05/26/22	ROBERTS, PATRICK	2.00	164.00 OVERTI	ME WRCCDM	PRJ-13309	INSPECTION
1094845	05/31/22		ROBERTS, PATRICK	2.00	164.00 OVERTI		PRJ-13309	INSPECTION
1094845	06/01/22		ROBERTS, PATRICK		246.00 OVERTI		PRJ-13309	INSPECTION
				3.00				
1094845	06/02/22		ROBERTS, PATRICK	2.00	164.00 OVERTI		PRJ-13309	INSPECTION
1094845	06/06/22	06/06/22	ROBERTS, PATRICK	1.00	82.00 OVERTI	ME WRCCDM	PRJ-13309	INSPECTION
1094845	06/08/22	06/08/22	ROBERTS, PATRICK	1.00	82.00 OVERTI	ME WRCCDM	PRJ-13309	INSPECTION
1094845	06/09/22		ROBERTS, PATRICK	1.00	82.00 OVERTI		PRJ-13309	INSPECTION
1094845	06/10/22		ROBERTS, PATRICK	2.00	164.00 OVERTI		PRJ-13309	INSPECTION
1094845	06/13/22		ROBERTS, PATRICK	2.00	164.00 OVERTI		PRJ-13309	INSPECTION
1094845	06/15/22	06/15/22	ROBERTS, PATRICK	2.00	164.00 OVERTI	ME WRCCDM	PRJ-13309	INSPECTION
1094845	06/16/22		ROBERTS, PATRICK	2.00	164.00 OVERTI		PRJ-13309	INSPECTION
1094845	06/17/22		ROBERTS, PATRICK	2.00	164.00 OVERTI		PRJ-13309	INSPECTION
1094845	06/18/22		ROBERTS, PATRICK	8.00	656.00 OVERTI		PRJ-13309	INSPECTION
1094845	06/20/22	06/20/22	ROBERTS, PATRICK	9.00	738.00 OVERTI	ME WRCCDM	PRJ-13309	INSPECTION
1094845	06/23/22		ROBERTS, PATRICK	7.00	574.00 OVERTI		PRJ-13309	INSPECTION
1094845	06/23/22		ROBERTS, PATRICK	1.00	82.00 OVERTI		PRJ-13309	INSPECTION
1094845	06/24/22		ROBERTS, PATRICK	1.00	82.00 OVERTI		PRJ-13309	INSPECTION
1094845	04/26/22	04/25/22	ROBERTS, PATRICK	8.00	564.24 REGULA	AR WRCCDM	PRJ-13309	INSPECTION
1094845	04/27/22		ROBERTS, PATRICK	8.00	564.24 REGULA		PRJ-13309	INSPECTION
1094845			ROBERTS, PATRICK	8.00	564.24 REGULA		PRJ-13309	INSPECTION
	04/27/22							
1094845	04/28/22		ROBERTS, PATRICK	8.00	564.24 REGULA		PRJ-13309	INSPECTION
1094845	04/29/22		ROBERTS, PATRICK	8.00	564.24 REGULA	AR WRCCDM	PRJ-13309	INSPECTION
1094845	05/02/22		ROBERTS, PATRICK	8.00	564.24 REGULA		PRJ-13309	INSPECTION
1094845	05/04/22		ROBERTS, PATRICK	8.00	564.24 REGULA		PRJ-13309	INSPECTION
1094845	05/05/22		ROBERTS, PATRICK	8.00	564.24 REGULA		PRJ-13309	INSPECTION
						D WDOODM	55 1 10000	1
1094845	05/06/22	05/06/22	ROBERTS, PATRICK	8.00	564.24 REGULA	AR WRCCDM	PRJ-13309	INSPECTION

			Grand Total		56.255.90				
			ROBERTS, PATRICK Total		28,079.70				
094845	06/30/22	06/30/22	ROBERTS, PATRICK	2.00	141.06	REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	06/24/22		ROBERTS, PATRICK	8.00	564.24	REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	06/23/22		ROBERTS, PATRICK	8.00	564.24	REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	06/23/22		ROBERTS, PATRICK	8.00	564.24	REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	06/17/22		ROBERTS, PATRICK	8.00	564.24	REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	06/16/22		ROBERTS, PATRICK	8.00	564.24	REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	06/15/22		ROBERTS, PATRICK	8.00	564.24	REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	06/13/22		ROBERTS, PATRICK	8.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	06/10/22		ROBERTS, PATRICK	8.00	564.24	REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	06/09/22		ROBERTS, PATRICK	8.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	06/08/22		ROBERTS, PATRICK	8.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	06/06/22		ROBERTS, PATRICK	8.00	564.24	REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	06/02/22		ROBERTS, PATRICK	8.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	06/01/22		ROBERTS, PATRICK	8.00	564.24	REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	05/31/22		ROBERTS, PATRICK	8.00	564.24	REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	05/27/22		ROBERTS, PATRICK	8.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	05/26/22		ROBERTS, PATRICK	8.00			WRCCDM	PRJ-13309	INSPECTION
094845	05/25/22		ROBERTS, PATRICK	8.00	564.24	REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	05/23/22		ROBERTS, PATRICK	8.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	05/20/22		ROBERTS, PATRICK	8.00			WRCCDM	PRJ-13309	INSPECTION
094845	05/19/22		ROBERTS, PATRICK	8.00	564.24	REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	05/18/22		ROBERTS, PATRICK	8.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	05/16/22		ROBERTS, PATRICK	8.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	05/13/22		ROBERTS, PATRICK	8.00	564.24	REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	05/12/22		ROBERTS, PATRICK	8.00		REGULAR	WRCCDM	PRJ-13309	INSPECTION
094845	05/11/22		ROBERTS, PATRICK	8.00			WRCCDM	PRJ-13309	INSPECTION
094845	05/10/22		ROBERTS, PATRICK	8.00	564.24	REGULAR	WRCCDM	PRJ-13309	INSPECTION
1094845	05/09/22	05/09/22	ROBERTS, PATRICK	8.00	564.24	REGULAR	WRCCDM	PRJ-13309	INSPEC

1994849	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING
1994849 05/11/22 04/25/22 BROWN, JOEL 1 0.40 ASSIGNED PC/Computer PRJ-13 1994849 05/11/22 04/25/22 BROWN, JOEL 1 0.45 ASSIGNED Tablet/Pad PRJ-13 1994849 05/11/22 04/25/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/Pad PRJ-13 1994849 05/11/22 04/26/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/Pad PRJ-13 1994849 05/11/22 04/26/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/Pad PRJ-13 1994849 05/11/22 04/26/22 BROWN, JOEL 1 2.34 ASSIGNED Tablet/Pad PRJ-13 1994849 05/11/22 04/26/22 BROWN, JOEL 4 1.60 ASSIGNED Cell Phone PRJ-13 1994849 05/11/22 04/26/22 BROWN, JOEL 4 1.60 ASSIGNED Cell Phone PRJ-13 1994849 05/11/22 04/26/22 BROWN, JOEL 4 1.60 ASSIGNED PC/Computer PRJ-13 1994849 05/11/22 05/02/22 BROWN, JOEL 2.5 0.63 ASSIGNED PC/Computer PRJ-13 1994849 05/11/22 05/02/22 BROWN, JOEL 2.5 1.00 ASSIGNED Tablet/Pad PRJ-13 1994849 05/11/22 05/02/22 BROWN, JOEL 2.5 1.00 ASSIGNED Tablet/Pad PRJ-13 1994849 05/11/22 05/02/22 BROWN, JOEL 2.5 5.86 ASSIGNED Tablet/Pad PRJ-13 1994849 05/11/22 05/02/22 BROWN, JOEL 2.5 5.86 ASSIGNED Tablet/Pad PRJ-13 1994849 05/11/22 05/02/22 BROWN, JOEL 1 0.25 ASSIGNED PC/Computer PRJ-13 1994849 05/11/22 05/04/22 BROWN, JOEL 1 0.25 ASSIGNED PC/Computer PRJ-13 1994849 05/11/22 05/04/22 BROWN, JOEL 1 0.40 ASSIGNED PC/Computer PRJ-13 1994849 05/11/22 05/04/22 BROWN, JOEL 1 0.40 ASSIGNED PC/Computer PRJ-13 1994849 05/11/22 05/05/22 BROWN, JOEL 1 0.40 ASSIGNED PC/Computer PRJ-13 1994849 05/11/22 05/05/22 BROWN, JOEL 1 0.40 ASSIGNED PC/Computer PRJ-13 1994849 05/11/22 05/05/22 BROWN, JOEL 1 0.40 ASSIGNED PC/Computer PRJ-13 1994849 05/11/22 05/05/22 BROWN, JOEL 1 0.40 ASSIGNED PC/Computer PRJ-13 1994849 05/26/22 05/05/22 BROWN, JOEL 1 0.40	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING
1994849	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING
1998489	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING
1994849	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING
1994849	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING
1998489	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING
1994849	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING
1994849	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING
1094849	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING
1094849	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING
1994849	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING
1094849	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING
1094849	ENGINEERING BOS ENGINEERING BOS ENGINEERING BOS ENGINEERING BOS ENGINEERING
1094849	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING
1094849	809 ENGINEERING 809 ENGINEERING
1094849	309 ENGINEERING
1094849	
1094849	
1094849	
1094849	309 ENGINEERING
1094849	
1094849	
1094849	
1094849	
1094849	
1094849	
1094849	
1094849	
1094849 05/26/22 05/16/22 BROWN, JOEL 2 0.50 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/17/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/17/22 BROWN, JOEL 1 2.34 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/17/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13 1094849 05/26/22 05/18/22 BROWN, JOEL 2 0.80 ASSIGNED Cell Phone PRJ-13 1094849 05/26/22 05/18/22 BROWN, JOEL 2 0.50 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/18/22 BROWN, JOEL 2 4.68 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/19/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13 1094849 05/26/22 05/19/22	
1094849	
1094849 05/26/22 05/17/22 BROWN, JOEL 1 2.34 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/17/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13 1094849 05/26/22 05/18/22 BROWN, JOEL 2 0.80 ASSIGNED Cell Phone PRJ-13 1094849 05/26/22 05/18/22 BROWN, JOEL 2 0.50 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/18/22 BROWN, JOEL 2 4.68 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/19/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13 1094849 05/26/22 05/19/22 BROWN, JOEL 1 2.34 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/19/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/20/22	
1094849	
1094849 05/26/22 05/18/22 BROWN, JOEL 2 0.80 ASSIGNED Cell Phone PRJ-13 1094849 05/26/22 05/18/22 BROWN, JOEL 2 0.50 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/18/22 BROWN, JOEL 2 4.68 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/19/22 BROWN, JOEL 1 0.40 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/19/22 BROWN, JOEL 1 2.34 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/19/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 0.50 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 0.50 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/23/22	
1094849 05/26/22 05/18/22 BROWN, JOEL 2 0.50 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/18/22 BROWN, JOEL 2 4.68 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/19/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13 1094849 05/26/22 05/19/22 BROWN, JOEL 1 2.34 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/19/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 4.68 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 0.50 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 0.60 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/23/22	
1094849 05/26/22 05/18/22 BROWN, JOEL 2 4.68 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/19/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13 1094849 05/26/22 05/19/22 BROWN, JOEL 1 2.34 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/19/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 4.68 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 0.50 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 0.80 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 0.60 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/23/22	
1094849 05/26/22 05/19/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13 1094849 05/26/22 05/19/22 BROWN, JOEL 1 2.34 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/19/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 4.68 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 0.50 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 0.80 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 0.60 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 3.51 ASSIGNED PC/Computer PRJ-13 1094849 06/20/22 05/24/22 <td></td>	
1094849 05/26/22 05/19/22 BROWN, JOEL 1 2.34 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/19/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 4.68 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 0.50 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 0.80 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 0.60 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 3.51 ASSIGNED PC/Computer PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 0.38 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/24/22	309 ENGINEERING
1094849 05/26/22 05/19/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 4.68 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 0.50 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 0.80 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 0.60 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 3.51 ASSIGNED PC/Computer PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 0.38 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 1.17 ASSIGNED PC/Computer PRJ-13 1094849 06/20/22 05/24/	
1094849 05/26/22 05/20/22 BROWN, JOEL 2 4.68 ASSIGNED PC/Computer PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 0.50 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 0.80 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 0.60 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 3.51 ASSIGNED PC/Computer PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 0.38 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 1.17 ASSIGNED PC/Computer PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 0.20 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/24	
1094849 05/26/22 05/20/22 BROWN, JOEL 2 0.50 ASSIGNED Tablet/iPad PRJ-13 1094849 05/26/22 05/20/22 BROWN, JOEL 2 0.80 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 0.60 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 3.51 ASSIGNED PC/Computer PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 0.38 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 1.17 ASSIGNED PC/Computer PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 0.20 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 0.13 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/	
1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 0.60 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 3.51 ASSIGNED PC/Computer PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 0.38 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 1.17 ASSIGNED PC/Computer PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 0.20 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 0.13 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.25 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/	
1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 3.51 ASSIGNED PC/Computer PRJ-13 1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 0.38 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 1.17 ASSIGNED PC/Computer PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 0.20 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 0.13 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13	309 ENGINEERING
1094849 06/20/22 05/23/22 BROWN, JOEL 1.5 0.38 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 1.17 ASSIGNED PC/Computer PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 0.20 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 0.13 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13	
1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 1.17 ASSIGNED PC/Computer PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 0.20 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 0.13 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13	
1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 0.20 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 0.13 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13	
1094849 06/20/22 05/24/22 BROWN, JOEL 0.5 0.13 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13	
1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13	
1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13	
1094849 06/20/22 05/25/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13	
	BOO ENGINEERING
1094849 06/20/22 05/25/22 BROWN, JOEL 1 2.34 ASSIGNED PC/Computer PRJ-13	
1094849 06/20/22 05/26/22 BROWN, JOEL 1 0.40 ASSIGNED Cell Phone PRJ-13	
1094849 06/20/22 05/26/22 BROWN, JOEL 1 2.34 ASSIGNED PC/Computer PRJ-13	
1094849 06/20/22 05/26/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13	
1094849 06/20/22 05/27/22 BROWN, JOEL 0.5 0.13 ASSIGNED Tablet/iPad PRJ-13 1094849 06/20/22 05/27/22 BROWN, JOEL 0.5 0.20 ASSIGNED Cell Phone PRJ-13	
1094849 06/20/22 05/27/22 BROWN, JOEL 0.5 0.20 ASSIGNED Cell Phone PRJ-13 1094849 06/20/22 05/27/22 BROWN, JOEL 0.5 1.17 ASSIGNED PC/Computer PRJ-13	
1094849 06/20/22 05/31/22 BROWN, JOEL 0.5 1.17 ASSIGNED PC/Computer PRJ-13	
1094849 06/20/22 05/31/22 BROWN, JOEL 0.5 0.20 ASSIGNED Cell Flidite PRJ-13 1094849 06/20/22 05/31/22 BROWN, JOEL 0.5 1.17 ASSIGNED PC/Computer PRJ-13	
1094849 06/20/22 05/31/22 BROWN, JOEL 0.5 0.13 ASSIGNED Tablet/iPad PRJ-13	
1094849 06/20/22 06/01/22 BROWN, JOEL 2 0.80 ASSIGNED Cell Phone PRJ-13	
1094849 06/20/22 06/01/22 BROWN, JOEL 2 4.68 ASSIGNED PC/Computer PRJ-13	
1094849 06/20/22 06/01/22 BROWN, JOEL 2 0.50 ASSIGNED Tablet/iPad PRJ-13	
1094849 06/20/22 06/02/22 BROWN, JOEL 5 1.25 ASSIGNED Tablet/iPad PRJ-13	
1094849 06/20/22 06/02/22 BROWN, JOEL 5 2.00 ASSIGNED Cell Phone PRJ-13	
1094849 06/20/22 06/02/22 BROWN, JOEL 5 11.70 ASSIGNED PC/Computer PRJ-13	
1094849	
1094849 06/20/22 06/06/22 BROWN, JOEL 1 2.34 ASSIGNED PC/Computer PRJ-13	
1094849 06/20/22 06/06/22 BROWN, JOEL 1 0.25 ASSIGNED Tablet/iPad PRJ-13	309 ENGINEERING
1094849 06/20/22 06/09/22 BROWN, JOEL 4 9.36 ASSIGNED PC/Computer PRJ-13	309 ENGINEERING
1094849 06/20/22 06/09/22 BROWN, JOEL 4 1.00 ASSIGNED Tablet/iPad PRJ-13	309 ENGINEERING
1094849 06/20/22 06/09/22 BROWN, JOEL 4 1.60 ASSIGNED Cell Phone PRJ-13	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING
1094849 06/20/22 06/10/22 BROWN, JOEL 2.5 0.63 ASSIGNED Tablet/iPad PRJ-13	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING
1094849 06/20/22 06/10/22 BROWN, JOEL 2.5 1.00 ASSIGNED Cell Phone PRJ-13	809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING 809 ENGINEERING

1094849	06/20/22	06/10/22	BROWN, JOEL	2.5	5.85	ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1094849	06/20/22		BROWN, JOEL	1		ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1094849	06/20/22		BROWN, JOEL	1		ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
1094849	06/20/22		BROWN, JOEL	1		ASSIGNED	Cell Phone	PRJ-13309	ENGINEERING
1094849	06/20/22		BROWN, JOEL	2		ASSIGNED	Cell Phone	PRJ-13309	ENGINEERING
1094849	06/20/22		BROWN, JOEL	2		ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1094849	06/20/22		BROWN, JOEL	2		ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
1094849	06/20/22		BROWN, JOEL	4		ASSIGNED	Cell Phone	PRJ-13309	ENGINEERING
1094849	06/20/22		BROWN, JOEL	4		ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1094849	06/20/22	06/16/22	BROWN, JOEL	4	1.00	ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
1094849	07/12/22	06/21/22	BROWN, JOEL	1	0.25	ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
1094849	07/12/22	06/21/22	BROWN, JOEL	1	0.40	ASSIGNED	Cell Phone	PRJ-13309	ENGINEERING
1094849	07/12/22	06/21/22	BROWN, JOEL	1		ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	1.5		ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	1.5		ASSIGNED	Cell Phone	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	1.5		ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	3		ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	3		ASSIGNED	Cell Phone	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	3		ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	1.5		ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	1.5		ASSIGNED	Cell Phone	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	1.5		ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	3		ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	3		ASSIGNED	Cell Phone	PRJ-13309	ENGINEERING
1094849	07/12/22	06/27/22	BROWN, JOEL	3	7.02	ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1094849	07/12/22	06/28/22	BROWN, JOEL	1	0.40	ASSIGNED	Cell Phone	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	1		ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	1		ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	2		ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	2		ASSIGNED	Cell Phone	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	2		ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	7.5		ASSIGNED	Cell Phone	PRJ-13309	ENGINEERING
			, , , , , , , , , , , , , , , , , , ,						
1094849	07/12/22		BROWN, JOEL	7.5		ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	7.5		ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	1.5		ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1094849	07/12/22		BROWN, JOEL	1.5		ASSIGNED	Cell Phone	PRJ-13309	ENGINEERING
1094849	07/12/22	07/01/22	BROWN, JOEL	1.5		ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
			BROWN, JOEL Total		228.80				
1094845	04/27/22	04/26/22	CARLEY, JOSEPH	1		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	04/27/22	04/26/22	CARLEY, JOSEPH	1	0.40	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	04/27/22	04/26/22	CARLEY, JOSEPH	1	5.69	ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	04/27/22	04/27/22	CARLEY, JOSEPH	1	0.40	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	04/27/22	04/27/22	CARLEY, JOSEPH	1	5.69	ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	04/27/22		CARLEY, JOSEPH	1		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	04/29/22		CARLEY, JOSEPH	1		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	04/29/22		CARLEY, JOSEPH	1		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	04/29/22		CARLEY, JOSEPH	1		ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	04/29/22	04/20/22	CARLEY, JOSEPH	1		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	04/29/22		CARLEY, JOSEPH	1			PC/Computer	PRJ-13309	
			CARLEY, JOSEPH						INCRECTION
1094845	04/29/22	04/29/22				ASSIGNED	2/4 Ton Diale		INSPECTION
1094845	05/03/22			1	5.69	ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/00/00	05/03/22	CARLEY, JOSEPH	1 4	5.69 9.36	ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer	PRJ-13309 PRJ-13309	INSPECTION INSPECTION
1094845	05/03/22	05/03/22 05/03/22	CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4	5.69 9.36 22.76	ASSIGNED ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up	PRJ-13309 PRJ-13309 PRJ-13309	INSPECTION INSPECTION
	05/03/22	05/03/22 05/03/22 05/03/22	CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4	5.69 9.36 22.76 1.60	ASSIGNED ASSIGNED ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone	PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309	INSPECTION INSPECTION INSPECTION INSPECTION
1094845	05/03/22 05/05/22	05/03/22 05/03/22 05/03/22 05/05/22	CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1	5.69 9.36 22.76 1.60 2.34	ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer	PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309	INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION
1094845	05/03/22 05/05/22 05/05/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22	CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1	5.69 9.36 22.76 1.60 2.34 0.40	ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone	PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309	INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION
1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22	CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1	5.69 9.36 22.76 1.60 2.34 0.40 5.69	ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up	PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309	INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION
1094845 1094845 1094845	05/03/22 05/05/22 05/05/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22	CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38	ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone	PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309	INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION
1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22	CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38	ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up	PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309	INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION
1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22	CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38	ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up	PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309	INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION
1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22	CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2 2 2	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68	ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer	PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309	INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION
1094845 1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22	CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2 2 2 2 1.5	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68	ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone PC/Computer Cell Phone	PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309	INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION
1094845 1094845 1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/16/22	CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2 2 2 2 1.5	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54	ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up	PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309	INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION
1094845 1094845 1094845 1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22 05/18/22 05/18/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/16/22	CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 1 1 1 2 2 2 2 1.5 1.5	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54	ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up PC/Computer	PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309	INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION
1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22 05/18/22 05/18/22 05/26/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/16/22 05/16/22	CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2 2 2 2 1.5 1.5	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54 3.51	ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up PC/Computer Cell Phone	PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309	INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION
1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22 05/18/22 05/18/22 05/26/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/16/22 05/16/22 05/16/22 05/16/22 05/26/22	CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2 2 2 2 1.5 1.5 1.5	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54 3.51 0.40 5.69	ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone	PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309 PRJ-13309	INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION
1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22 05/18/22 05/18/22 05/26/22 05/26/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/16/22 05/16/22 05/16/22 05/26/22 05/26/22	CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2 2 2 2 1.5 1.5 1.5	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54 3.51 0.40 5.69 2.34	ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer	PRJ-13309 PRJ-13309	INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION
1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22 05/18/22 05/18/22 05/26/22 05/26/22 05/26/22 06/03/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/16/22 05/16/22 05/16/22 05/26/22 05/26/22 05/26/22 06/03/22	CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2 2 2 2 1.5 1.5 1.5 1.5	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54 3.51 0.40 5.69 2.34 2.00	ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone	PRJ-13309 PRJ-13309	INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION INSPECTION
1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22 05/18/22 05/18/22 05/26/22 05/26/22 06/03/22 06/03/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/16/22 05/16/22 05/16/22 05/26/22 05/26/22 06/03/22 06/03/22	CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2 2 2 2 1.5 1.5 1.5 1.5	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54 3.51 0.40 5.69 2.34 2.00 11.70	ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone PC/Computer Cell Phone	PRJ-13309 PRJ-13309	INSPECTION INSPECTION
1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22 05/18/22 05/18/22 05/26/22 05/26/22 06/03/22 06/03/22 06/03/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/16/22 05/16/22 05/26/22 05/26/22 06/03/22 06/03/22	CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2 2 2 2 1.5 1.5 1.5 1.5 1.5	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54 3.51 0.40 5.69 2.34 2.00 11.70 28.45	ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone PC/Computer Cell Phone PC/Computer T/2 Ton Pick-up	PRJ-13309 PRJ-13309	INSPECTION INSPECTION
1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/18/22 05/18/22 05/18/22 05/26/22 05/26/22 06/03/22 06/03/22 06/03/22 06/07/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/16/22 05/16/22 05/26/22 05/26/22 06/03/22 06/03/22 06/06/22	CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 1 2 2 2 2 1.5 1.5 1.5 1.5 1.5 5 5	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54 3.51 0.40 5.69 2.34 2.00 11.70 28.45 0.40	ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone PC/Computer Cell Phone PC/Computer Cell Phone PC/Computer Cell Phone PC/Computer Cell Phone	PRJ-13309 PRJ-13309	INSPECTION INSPECTION
1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22 05/18/22 05/18/22 05/26/22 05/26/22 06/03/22 06/03/22 06/03/22 06/07/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/16/22 05/16/22 05/26/22 05/26/22 06/03/22 06/03/22 06/06/22 06/06/22	CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2 2 2 2 1.5 1.5 1.5 1.5 5 5 5	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54 3.51 0.40 5.69 2.34 2.00 11.70 28.45 0.40 2.34	ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone PC/Computer Cell Phone PC/Computer Cell Phone PC/Computer Cell Phone PC/Computer 1/2 Ton Pick-up Cell Phone PC/Computer	PRJ-13309 PRJ-13309	INSPECTION INSPECTION
1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22 05/18/22 05/26/22 05/26/22 06/03/22 06/03/22 06/07/22 06/07/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/16/22 05/16/22 05/26/22 05/26/22 06/03/22 06/03/22 06/06/22 06/06/22	CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 4 1 1 1 1 2 2 2 2 1.5 1.5 1.5 1.5 1.5 1.5 1.5 1.5 1.5 1.5	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54 3.51 0.40 5.69 2.34 2.00 11.70 28.45 0.40 2.34 5.69	ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone PC/Computer Cell Phone PC/Computer 1/2 Ton Pick-up PC/Computer 1/2 Ton Pick-up PC/Computer	PRJ-13309 PRJ-13309	INSPECTION INSPECTION
1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22 05/18/22 05/18/22 05/26/22 05/26/22 06/03/22 06/03/22 06/03/22 06/07/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/16/22 05/16/22 05/26/22 05/26/22 06/03/22 06/03/22 06/06/22 06/06/22	CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2 2 2 2 1.5 1.5 1.5 1.5 5 5 5	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54 3.51 0.40 5.69 2.34 2.00 11.70 28.45 0.40 2.34 5.69	ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone PC/Computer Cell Phone PC/Computer 1/2 Ton Pick-up PC/Computer 1/2 Ton Pick-up PC/Computer	PRJ-13309 PRJ-13309	INSPECTION INSPECTION
1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22 05/18/22 05/18/22 05/26/22 05/26/22 06/03/22 06/03/22 06/07/22 06/07/22 06/07/22 06/07/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/16/22 05/16/22 05/26/22 06/03/22 06/03/22 06/06/22 06/06/22 06/06/22	CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 4 1 1 1 1 2 2 2 2 1.5 1.5 1.5 1.5 1.5 1.5 1.5 1.5 1.5 1.5	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54 3.51 0.40 5.69 2.34 2.00 11.74 0.40 2.34 2.00 2.34	ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone PC/Computer Cell Phone PC/Computer Cell Phone PC/Computer Cell Phone PC/Computer 1/2 Ton Pick-up Cell Phone PC/Computer	PRJ-13309 PRJ-13309	INSPECTION INSPECTION
1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22 05/18/22 05/18/22 05/26/22 05/26/22 06/03/22 06/03/22 06/07/22 06/07/22 06/07/22 06/07/22 06/07/22 06/07/22 06/07/22 06/07/22 06/14/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/16/22 05/16/22 05/26/22 06/03/22 06/06/22 06/06/22 06/06/22 06/06/22 06/06/22	CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2 2 2 2 1.5 1.5 1.5 1.5 5 5 5 1 1	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54 3.51 0.40 5.69 2.34 2.00 11.70 28.45 0.40 2.34 5.69 0.40 2.34	ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone PC/Computer Cell Phone PC/Computer 1/2 Ton Pick-up PC/Computer 1/2 Ton Pick-up Cell Phone PC/Computer 1/2 Ton Pick-up Cell Phone PC/Computer	PRJ-13309 PRJ-13309	INSPECTION INSPECTION
1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22 05/18/22 05/18/22 05/26/22 05/26/22 06/03/22 06/03/22 06/03/22 06/07/22 06/07/22 06/07/22 06/14/22 06/14/22 06/14/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/16/22 05/16/22 05/16/22 05/26/22 06/03/22 06/06/22 06/06/22 06/06/22 06/13/22 06/13/22	CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2 2 2 2 1.5 1.5 1.5 1.5 1.5 5 5 5 1 1 1 1 1 1 1	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54 3.51 0.40 5.69 2.34 2.00 11.70 28.45 0.40 2.34 5.69 0.40 2.34 5.69	ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone PC/Computer Cell Phone PC/Computer 1/2 Ton Pick-up PC/Computer 1/2 Ton Pick-up Cell Phone PC/Computer 1/2 Ton Pick-up Cell Phone PC/Computer 1/2 Ton Pick-up Cell Phone PC/Computer 1/2 Ton Pick-up Cell Phone PC/Computer 1/2 Ton Pick-up Cell Phone	PRJ-13309 PRJ-13309	INSPECTION INSPECTION
1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22 05/18/22 05/18/22 05/26/22 05/26/22 06/03/22 06/03/22 06/03/22 06/07/22 06/07/22 06/07/22 06/14/22 06/14/22 06/14/22 06/14/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/16/22 05/16/22 05/16/22 05/26/22 06/03/22 06/03/22 06/06/22 06/06/22 06/06/22 06/13/22 06/13/22	CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2 2 2 2 1.5 1.5 1.5 1.5 1.5 5 5 5 1 1 1 1 1 1 1	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54 3.51 0.40 5.69 2.34 2.00 11.70 28.45 0.40 2.34 5.69 0.40 2.34 5.69 3.51	ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone PC/Computer Cell Phone PC/Computer 1/2 Ton Pick-up PC/Computer 1/2 Ton Pick-up Cell Phone PC/Computer 1/2 Ton Pick-up Cell Phone PC/Computer 1/2 Ton Pick-up Cell Phone PC/Computer 1/2 Ton Pick-up Cell Phone PC/Computer 1/2 Ton Pick-up Cell Phone	PRJ-13309 PRJ-13309	INSPECTION INSPECTION
1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845 1094845	05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/18/22 05/18/22 05/18/22 05/26/22 05/26/22 06/03/22 06/03/22 06/03/22 06/07/22 06/07/22 06/07/22 06/14/22 06/14/22 06/14/22	05/03/22 05/03/22 05/03/22 05/05/22 05/05/22 05/05/22 05/13/22 05/13/22 05/13/22 05/16/22 05/16/22 05/26/22 05/26/22 06/03/22 06/03/22 06/06/22 06/06/22 06/13/22 06/13/22 06/13/22 06/13/22 06/13/22 06/13/22 06/13/22	CARLEY, JOSEPH CARLEY, JOSEPH	1 4 4 4 1 1 1 2 2 2 2 1.5 1.5 1.5 1.5 1.5 5 5 5 1 1 1 1 1 1 1	5.69 9.36 22.76 1.60 2.34 0.40 5.69 11.38 0.80 4.68 0.60 8.54 3.51 0.40 5.69 2.34 2.00 11.70 28.45 0.40 2.34 5.69 0.40 2.34 5.69 3.51 0.60	ASSIGNED ASSIGNED	3/4 Ton Pick-up PC/Computer 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up 3/4 Ton Pick-up 3/4 Ton Pick-up Cell Phone PC/Computer Cell Phone 3/4 Ton Pick-up PC/Computer Cell Phone 1/2 Ton Pick-up PC/Computer Cell Phone PC/Computer Cell Phone PC/Computer 1/2 Ton Pick-up PC/Computer 1/2 Ton Pick-up Cell Phone PC/Computer 1/2 Ton Pick-up Cell Phone PC/Computer 1/2 Ton Pick-up Cell Phone PC/Computer 1/2 Ton Pick-up Cell Phone PC/Computer 1/2 Ton Pick-up Cell Phone	PRJ-13309 PRJ-13309	INSPECTION INSPECTION

1094845	06/24/22	06/23/22	CARLEY, JOSEPH	1	5.60	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/24/22		CARLEY, JOSEPH	1		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
-									
1094845	06/24/22		CARLEY, JOSEPH	1		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/27/22		CARLEY, JOSEPH	4		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/27/22		CARLEY, JOSEPH	4	-	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/27/22		CARLEY, JOSEPH	4		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	07/01/22	06/30/22	CARLEY, JOSEPH	1	0.40	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	07/01/22	06/30/22	CARLEY, JOSEPH	1	2.34	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	07/01/22	06/30/22	CARLEY, JOSEPH	1	5.69	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	07/01/22	06/30/22	CARLEY, JOSEPH	0.5	0.20	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	07/01/22		CARLEY, JOSEPH	0.5		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	07/01/22		CARLEY, JOSEPH	0.5		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1034043	01/01/22	00/30/22	·	0.5		AGGIGINED	1/2 TOTT TICK-up	110-13303	INSI LCTION
1004045	06/00/00	00/07/00	CARLEY, JOSEPH Total		240.27	ACCIONED	Cell Phone	DD 142200	INCRECTION
1094845	06/28/22		IGNASH, MICHAEL	3		ASSIGNED		PRJ-13309	INSPECTION
1094845	06/28/22		IGNASH, MICHAEL	3		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/28/22		IGNASH, MICHAEL	3		ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/27/22	06/27/22	IGNASH, MICHAEL	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/27/22	06/27/22	IGNASH, MICHAEL	8	45.52	ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/27/22	06/27/22	IGNASH, MICHAEL	8	3.20	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/28/22	06/28/22	IGNASH, MICHAEL	8	3.20	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/28/22		IGNASH, MICHAEL	8	18.72	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/28/22		IGNASH, MICHAEL	8		ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/29/22		IGNASH, MICHAEL	3		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/29/22		IGNASH, MICHAEL	3		ASSIGNED	PC/Computer	PRJ-13309 PRJ-13309	INSPECTION
							•		
1094845	06/29/22		IGNASH, MICHAEL	3		ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/29/22		IGNASH, MICHAEL	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/29/22		IGNASH, MICHAEL	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/29/22		IGNASH, MICHAEL	8		ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/29/22	06/29/22	IGNASH, MICHAEL	3	1.20	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/29/22		IGNASH, MICHAEL	3		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/29/22	06/29/22	IGNASH, MICHAEL	3		ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/30/22		IGNASH, MICHAEL	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/30/22		IGNASH, MICHAEL	8		ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/30/22		IGNASH, MICHAEL	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/30/22		IGNASH, MICHAEL	3		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/30/22		IGNASH, MICHAEL	3		ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/30/22		IGNASH, MICHAEL	3		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	07/01/22		IGNASH, MICHAEL	1.5		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	07/01/22	07/01/22	IGNASH, MICHAEL	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	07/01/22	07/01/22	IGNASH, MICHAEL	8	18.72	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	07/01/22	07/01/22	IGNASH, MICHAEL	8	45.52	ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	07/01/22	07/01/22	IGNASH, MICHAEL	1.5	3.51	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	07/01/22		IGNASH, MICHAEL	1.5		ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	07/05/22		IGNASH, MICHAEL	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	07/05/22		IGNASH, MICHAEL	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
	07/05/22		·	8		ASSIGNED			
1094845			IGNASH, MICHAEL				3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	07/05/22		IGNASH, MICHAEL	3		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	07/05/22		IGNASH, MICHAEL	3		ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	07/05/22		IGNASH, MICHAEL	3		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	07/06/22		IGNASH, MICHAEL	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	07/06/22		IGNASH, MICHAEL	8	18.72	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	07/06/22	07/06/22	IGNASH, MICHAEL	3		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	07/06/22		IGNASH, MICHAEL	3		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	07/06/22		IGNASH, MICHAEL	3		ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	07/06/22		IGNASH, MICHAEL	8		ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	07/07/22		IGNASH, MICHAEL	1.5		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
			IGNASH, MICHAEL				PC/Computer		
1094845	07/07/22		· · · · · · · · · · · · · · · · · · ·	1.5		ASSIGNED		PRJ-13309	INSPECTION
1094845	07/07/22		IGNASH, MICHAEL	1.5		ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	07/07/22		IGNASH, MICHAEL	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	07/07/22		IGNASH, MICHAEL	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	07/07/22		IGNASH, MICHAEL	8		ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	07/08/22		IGNASH, MICHAEL	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	07/08/22	07/08/22	IGNASH, MICHAEL	8		ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1094845	07/08/22		IGNASH, MICHAEL	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	07/08/22		IGNASH, MICHAEL	2		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	07/08/22		IGNASH, MICHAEL	2		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	07/08/22		IGNASH, MICHAEL	2		ASSIGNED	3/4 Ton Pick-up	PRJ-13309	INSPECTION
1034043	01/00/22	01/00/22				AGGIGINED	JA TOH FICK-UP	110-10008	INOFECTION
1004040	05/00/00	04/05/00	IGNASH, MICHAEL Total		800.86	ACCIONED	Call Discret	DD 140000	ENGINEEDING
1094849	05/06/22		LOCKHART, SIDNEY	1		ASSIGNED	Cell Phone	PRJ-13309	ENGINEERING
1094849	05/06/22		LOCKHART, SIDNEY	1		ASSIGNED	Blazer/Suburbans	PRJ-13309	ENGINEERING
1094849	05/06/22		LOCKHART, SIDNEY	1		ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
1094849	05/06/22		LOCKHART, SIDNEY	1		ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1094849	05/06/22		LOCKHART, SIDNEY	2		ASSIGNED	Blazer/Suburbans	PRJ-13309	ENGINEERING
1094849	05/06/22		LOCKHART, SIDNEY	2		ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
1094849	05/06/22		LOCKHART, SIDNEY	2		ASSIGNED	Cell Phone	PRJ-13309	ENGINEERING
1094849	05/06/22		LOCKHART, SIDNEY	2	4 68	ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1094849	05/06/22		LOCKHART, SIDNEY	2		ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
1034043	03/00/22	U 4 /21/22	LOUISIANT, SIDNET		0.50	, COIGINED	i avievir au	1110-10003	LINGHALEKHAG

1994849	ENGINEERING ENGINEERING
1994849	ENGINEERING ENGINEERING
1094849	NGINEERING NGINEERING
1094849	ENGINEERING ENGINEERING
1094849	ENGINEERING ENGINEERING
1094849	ENGINEERING ENGINEERING
1094849	ENGINEERING ENGINEERING
1094849	ENGINEERING ENGINEERING
1094849	ENGINEERING ENGINEERING
1994B49	NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING
1094849	ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING
1094849	ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING
1994849	ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING
1094849	ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING
1094849	NGINEERING ENGINEERING
1094849	ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING
1094849	ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING
1094849	ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING
1094849	ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING
1094849	ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING
1094849	ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING
1094849	ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING
1094849	NGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING
1094849	ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING
1094849	NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING
1094849	NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING
1094849	NGINEERING NGINEERING NGINEERING NGINEERING NGINEERING
1094849	ENGINEERING ENGINEERING ENGINEERING ENGINEERING
1094849 05/06/22 05/06/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 E1 1094849 05/23/22 05/09/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 E1 1094849 05/23/22 05/09/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 E1 1094849 05/23/22 05/09/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 E1 1094849 05/23/22 05/09/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 E1 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED PC/Computer PRJ-13309 E1 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Blazer/Suburbans PRJ-13309 E1 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY	NGINEERING NGINEERING NGINEERING
1094849 05/23/22 05/09/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 Ef 1094849 05/23/22 05/09/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Ef 1094849 05/23/22 05/09/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 Ef 1094849 05/23/22 05/09/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 Ef 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 Ef 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Blazer/Suburbans PRJ-13309 Ef 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Tablet/iPad PRJ-13309 Ef 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Ef 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2	NGINEERING NGINEERING
1094849 05/23/22 05/09/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 EI 1094849 05/23/22 05/09/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 EI 1094849 05/23/22 05/09/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED Blazer/Suburbans PRJ-13309 EI 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 EI 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 EI 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 EI 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 EI 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY	NGINEERING
1094849 05/23/22 05/09/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 EI 1094849 05/23/22 05/09/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 EI 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 EI 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 EI 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 EI 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 EI 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Tablet/iPad PRJ-13309 EI 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY	
1094849 05/23/22 05/09/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 EI 1094849 05/23/22 05/09/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 EI 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 EI 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 1.38 ASSIGNED Blazer/Suburbans PRJ-13309 EI 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 EI 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 EI 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 EI 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY	NGINEERING
1094849 05/23/22 05/09/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 ER 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 ER 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Blazer/Suburbans PRJ-13309 ER 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 ER 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 ER 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 ER 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 ER 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY	
1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 E1 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 E1 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 E1 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 E1 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 E1 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 E1 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 E1 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY <	NGINEERING
1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 EI 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 EI 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 EI 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Cell Phone PRJ-13309 EI 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 EI 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 EI 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 EI 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY <	NGINEERING
1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 Et 1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Et 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Et 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 Et 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 Et 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Blazer/Suburbans PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY <t< td=""><td></td></t<>	
1094849 05/23/22 05/12/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Et 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Et 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 Et 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 Et 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED PC/Computer PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY <t< td=""><td>NGINEERING</td></t<>	NGINEERING
1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 EI 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 EI 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 EI 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 EI 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 EI 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 EI 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 EI 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY <	NGINEERING
1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 EI 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 EI 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 EI 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 EI 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 EI 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 EI 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 EI 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY	ENGINEERING
1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 Et 1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 Et 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Et 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY	ENGINEERING
1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 Et 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Et 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Et 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY	ENGINEERING
1094849 05/23/22 05/16/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 Et 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Et 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Et 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY	NGINEERING
1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.50 ASSIGNED Tablet/iPad PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 Et 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 Et 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Et 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 Et	NGINEERING
1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 E1 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 E1 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 E1 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 E1 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 E1	NGINEERING
1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 E1 1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 E1 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 E1 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 E1	NGINEERING
1094849 06/06/22 05/23/22 LOCKHART, SIDNEY 2 11.38 ASSIGNED Blazer/Suburbans PRJ-13309 E1 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 E1 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 E1	
1094849 06/06/22 05/27/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 E1 1094849 06/06/22 05/27/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 E1	NGINEERING
1094849 06/06/22 05/27/22 LOCKHART, SIDNEY 2 4.68 ASSIGNED PC/Computer PRJ-13309 EI	ENGINEERING
	ENGINEERING
1094849 06/06/22 05/27/22 LOCKHART SIDNEY 2 0.50 ASSIGNED Tablet/Dad DD L12200 Et	ENGINEERING
FINATOTO TO ANNOTATE VALENCE CONTINUE OF THE PROPERTY OF THE P	NGINEERING
	NGINEERING
	NGINEERING
	NGINEERING
	NGINEERING
	NGINEERING
	ENGINEERING
	NGINEERING
	NGINEERING
	NGINEERING
1094849 06/17/22 06/14/22 LOCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PRJ-13309 Et	ENGINEERING
	ENGINEERING
	NGINEERING
	NGINEERING
	NGINEERING
	NGINEERING
	NGINEERING
	NGINEERING
	ENGINEERING
	ENGINEERING
	NGINEERING
1094849 07/01/22 06/27/22 LOCKHART, SIDNEY 1 0.25 ASSIGNED Tablet/iPad PRJ-13309 Ef	NGINEERING
	NGINEERING NGINEERING
	NGINEERING NGINEERING NGINEERING
1094849 07/01/22 06/27/22 LOCKHART, SIDNEY 1 2.34 ASSIGNED PC/Computer PRJ-13309 E1	ENGINEERING ENGINEERING ENGINEERING ENGINEERING
	ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING
	ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING
1094849 07/01/22 06/28/22 LOCKHART, SIDNEY 1 2.34 ASSIGNED PC/Computer PRJ-13309 EI	ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING

1994849	1094849	07/01/22	06/28/22	LOCKHART, SIDNEY	1	5.60	ASSIGNED	Blazer/Suburbans	PRJ-13309	ENGINEERING
1964848 0701/22 0028/22 005HNRT SIDNEY 2	-									
1998499				,						
1994949				· ·						
1904949 070122 0002922 COCHART, SIDNEY 2 0.00 ASSIGNED TablesPad PR-1/3309 ENGINEERING 1004449 070122 0000022 COCHART, SIDNEY 1 0.40 ASSIGNED CoCHART, SIDNEY 1 0.40 ASSIG										
1904949 0770122 0909022 COCHART, SIDNEY 1										
1984896				,						
19094949					1			Cell Phone		
19094949 0770122 0093022 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TableRPad PR-J13309 ENGINEERING 1908494 077522 077622 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TableRPAD PR-J13309 ENGINEERING 1908494 077522 0776722 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TableRPAD PR-J13309 ENGINEERING 1908494 077522 0776722 LOCHAPAT, SIDNEY 2 11.38 ASSIGNED TableRPAD PR-J13309 ENGINEERING 1908494 077522 0776722 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TableRPAD PR-J13309 ENGINEERING 1908494 077522 0776722 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TableRPAD PR-J13309 ENGINEERING 1908494 077522 0776722 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TableRPAD PR-J13309 ENGINEERING 1908494 077522 0776722 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TableRPAD PR-J13309 ENGINEERING 1908494 077522 0776722 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TableRPAD PR-J13309 ENGINEERING 1908494 077522 0771022 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TABLER PAD PR-J13309 ENGINEERING 1908494 077522 0771022 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TABLER PAD PR-J13309 ENGINEERING 1908494 077522 0771022 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TABLER PAD PR-J13309 ENGINEERING 1908494 077522 0771022 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TABLER PAD PR-J13309 ENGINEERING 1908494 077522 0771022 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TABLER PAD PR-J13309 ENGINEERING 1908494 077522 0771022 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TABLER PAD PR-J13309 ENGINEERING 1908494 077522 0771022 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TABLER PAD PR-J13309 ENGINEERING 1908494 077522 0771022 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TABLER PAD PR-J13309 ENGINEERING 1908494 077522 0771022 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TABLER PAD PR-J13309 ENGINEERING 1908494 077522 0771022 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TABLER PAD PR-J13309 ENGINEERING 1908494 077522 0771022 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TABLER PAD PR-J13309 ENGINEERING 1908494 077522 0771022 LOCHAPAT, SIDNEY 2 0.50 ASSIGNED TABLER PAD	1094849	07/01/22	06/30/22	LOCKHART, SIDNEY	1	2.34	ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
19094949	1094849	07/01/22	06/30/22	LOCKHART, SIDNEY	1	5.69	ASSIGNED	Blazer/Suburbans	PRJ-13309	ENGINEERING
19094949	1094849	07/01/22	06/30/22	LOCKHART, SIDNEY	1	0.25	ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
1904949				· ·						
Inches										
1908499		07/15/22								
1908489 07/15/22 07/07/22 LOCKHART, SIDNEY 2								-		
1904849 07/15/22 07/07/22 DOCKHART, SIDNEY 2 0.80 ASSIGNED TelePhone PRJ.13309 ENGINEERING 1904840 07/15/22 07/07/22 DOCKHART, SIDNEY 2 0.80 ASSIGNED PC.Computer PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 2 4.88 ASSIGNED PC.Computer PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 2 4.88 ASSIGNED Cell Phone PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 2 4.80 ASSIGNED Cell Phone PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 2 0.50 ASSIGNED Cell Phone PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 2 0.50 ASSIGNED Cell Phone PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 2 4.60 ASSIGNED Cell Phone PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 2 4.60 ASSIGNED Cell Phone PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 2 1.00 ASSIGNED Cell Phone PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 2 1.00 ASSIGNED Cell Phone PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 2 1.00 ASSIGNED Cell Phone PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 2 1.00 ASSIGNED Cell Phone PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 2 1.00 ASSIGNED Cell Phone PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 2 1.00 ASSIGNED Cell Phone PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 2 1.00 ASSIGNED Cell Phone PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 2 1.00 ASSIGNED Cell Phone PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 1 0.40 ASSIGNED Cell Phone PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22 DOCKHART, SIDNEY 1 0.40 ASSIGNED Cell Phone PRJ.13309 ENGINEERING 1904840 07/15/22 07/16/22				,						
19084499										
1004449 07/1522 07/15										
199449 07/15/22 07/11/22 OCCHART, SIDNEY 2 4.88 ASSIGNED PCComputer PR.11399 ENGINEERING 199449 07/15/22 07/11/22 OCCHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PR.11399 ENGINEERING 199449 07/15/22 07/12/22 OCCHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PR.11399 ENGINEERING 199449 07/15/22 07/12/22 OCCHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PR.11399 ENGINEERING 199449 07/15/22 07/12/22 OCCHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PR.11399 ENGINEERING 199449 07/15/22 OCCHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PR.11399 ENGINEERING 199449 07/15/22 OCCHART, SIDNEY 2 0.80 ASSIGNED Telestriand PR.11399 ENGINEERING 199449 07/15/22 OCCHART, SIDNEY 2 0.80 ASSIGNED Telestriand PR.11399 ENGINEERING 199449 07/15/22 OCCHART, SIDNEY 2 0.80 ASSIGNED Telestriand PR.11399 ENGINEERING 199449 07/15/22 OCCHART, SIDNEY 2 0.80 ASSIGNED Telestriand PR.11399 ENGINEERING 199449 07/15/22 OCCHART, SIDNEY 2 0.80 ASSIGNED Telestriand PR.11399 ENGINEERING 199449 07/15/22 OCCHART, SIDNEY 2 0.80 ASSIGNED Telestriand PR.11399 ENGINEERING 199449 07/15/22 OCCHART, SIDNEY 2 0.80 ASSIGNED PR.11399 ENGINEERING 199449 07/15/22 OCCHART, SIDNEY 2 0.50 ASSIGNED PR.11399 ENGINEERING 199449 07/15/22 OCCHART, SIDNEY 2 0.50 ASSIGNED PR.11399 ENGINEERING 199449 07/15/22 OCCHART, SIDNEY 2 0.50 ASSIGNED Telestriand PR.11399 ENGINEERING 199449 07/15/22 OCCHART, SIDNEY 2 0.50 ASSIGNED Telestriand PR.11399 ENGINEERING 199449 07/15/22 OCCHART, SIDNEY 2 0.50 ASSIGNED Telestriand PR.11399 ENGINEERING 199449 07/15/22 OCCHART, SIDNEY 2 0.50 ASSIGNED Telestriand PR.11399 ENGINEERING 199449 07/15/22 OCCHART, SIDNEY 2 0.50 ASSIGNED Telestriand PR.11399 ENGINEERING 199449 07/15/22 OCCHART, SIDNEY 199449 07/15/22 OCCHART, SIDNEY 199449 07/15/22 OCCH										
1994499	1094849	07/15/22	07/07/22	LOCKHART, SIDNEY	2	4.68	ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1994949	1094849	07/15/22	07/11/22	LOCKHART, SIDNEY	2	4.68	ASSIGNED	PC/Computer	PRJ-13309	ENGINEERING
1994949	1094849	07/15/22	07/11/22	LOCKHART, SIDNEY	2	11.38	ASSIGNED	Blazer/Suburbans	PRJ-13309	ENGINEERING
1994949	1094849	07/15/22	07/11/22	LOCKHART, SIDNEY	2	0.80	ASSIGNED	Cell Phone		ENGINEERING
1994490				,						
198449 07/15/22 07/15/23 07/15/23 07/15/23 07/15/23 07/15/23 07/15/23 07/15/23 07/15/23 07/15/23 07/15/23 07/15/23 07/15/23 0										
199489 077/522 077/422 COCKHART, SIDNEY 2 1.38 ASSIGNED Bilazer/Suburbans PR-I-13309 ENGINEERING 1994849 077/522 077/4322 COCKHART, SIDNEY 2 0.80 ASSIGNED Cell Phone PR-I-13309 ENGINEERING 1994849 077/522 077/4322 COCKHART, SIDNEY 2 4.88 ASSIGNED Cell Phone PR-I-13309 ENGINEERING 1994849 077/522 077/4322 COCKHART, SIDNEY 2 4.88 ASSIGNED Cell Phone PR-I-13309 ENGINEERING 1994849 077/522 077/4322 COCKHART, SIDNEY 2 1.38 ASSIGNED Cell Phone PR-I-13309 ENGINEERING 1994849 077/522 077/422 COCKHART, SIDNEY 1 0.40 ASSIGNED Cell Phone PR-I-13309 ENGINEERING 1994849 077/522 077/422 COCKHART, SIDNEY 1 0.40 ASSIGNED Cell Phone PR-I-13309 ENGINEERING 1994849 077/522 077/422 COCKHART, SIDNEY 1 0.25 ASSIGNED Cell Phone PR-I-13309 ENGINEERING 1994849 077/522 077/422 COCKHART, SIDNEY 1 0.25 ASSIGNED Cell Phone PR-I-13309 ENGINEERING 1994849 077/522 077/422 COCKHART, SIDNEY 1 0.25 ASSIGNED Cell Phone PR-I-13309 ENGINEERING 1994849 077/522 077/422 COCKHART, SIDNEY 1 0.25 ASSIGNED Cell Phone PR-I-13309 ENGINEERING 1994849 077/522 077/422 COCKHART, SIDNEY 1 0.25 ASSIGNED Cell Phone PR-I-13309 INSPECTION 1994845 077/522 077/422 COUSHO, ROBERT 8 3.20 ASSIGNED Cell Phone PR-I-13309 INSPECTION 1994845 077/522 077/422 POUSHO, ROBERT 8 3.20 ASSIGNED Cell Phone PR-I-13309 INSPECTION 1994845 077/522 077/422 POUSHO, ROBERT 8 3.20 ASSIGNED Cell Phone PR-I-13309 INSPECTION 1994845 077/522 077/422 POUSHO, ROBERT 8 3.20 ASSIGNED Cell Phone PR-I-13309 INSPECTION 1994845 077/522 077/422 POUSHO, ROBERT 8 3.20 ASSIGNED Cell Phone PR-I-13309 INSPECTION 1994845 077/522 077/422 POUSHO, ROBERT 8 3.20 ASSIGNED Cell Phone PR-I-13309 INSPECTION 1994845 077/522 077/422 POUSHO, ROBERT 8 3.20 ASSIGNED Cell Phone PR-I-13309				,						
1094494 0771522 07714222 1074722 107										
1094489				, -						
1094849										
10944949										
1094849										
1094949				,						
1994849	1094849	07/15/22	07/13/22	LOCKHART, SIDNEY	2	0.50	ASSIGNED	Tablet/iPad	PRJ-13309	ENGINEERING
1994849	1094849				1			Cell Phone	PRJ-13309	ENGINEERING
1994849	1094849	07/15/22	07/14/22	LOCKHART, SIDNEY	1	5.69	ASSIGNED	Blazer/Suburbans	PRJ-13309	ENGINEERING
1994849 07/15/22 07/14/22 LOCKHART, SIDNEY total 1904845 07/15/22 07/05/22 POLSHO, ROBERT 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 07/15/22 07/05/22 POLSHO, ROBERT 8 8.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/07/22 POLSHO, ROBERT 8 8.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/07/22 POLSHO, ROBERT 8 8.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/07/22 POLSHO, ROBERT 8 8.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/12/22 POLSHO, ROBERT 8 8.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/12/22 POLSHO, ROBERT 8 8.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POLSHO, ROBERT 8 8.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POLSHO, ROBERT 8 8.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POLSHO, ROBERT 8 8.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/28/22 04/25/22 ROBERTS, PATRICK 8 8.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/28/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/28/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/28/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/28/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/28/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/28/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSP										
1994845 07/15/22 07/05/22 POUSHO, ROBERT 8 18.72 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 07/15/22 07/07/22 POUSHO, ROBERT 8 18.72 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 07/15/22 07/07/22 POUSHO, ROBERT 8 18.72 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 07/15/22 07/12/22 POUSHO, ROBERT 8 18.72 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 07/15/22 07/12/22 POUSHO, ROBERT 8 18.72 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 18.72 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 18.72 ASSIGNED PC-Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 18.72 ASSIGNED PC-Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 76/14/22 POUSHO, ROBERT 76/14/24 POUSHO, RO	1004040	01/10/22	01/14/22				ACCICIALD	Tablevii aa	110 10000	LITOINELITING
1994845 07/15/22 07/05/22 POUSHO, ROBERT 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/07/22 POUSHO, ROBERT 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/12/22 POUSHO, ROBERT 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 07/15/22 07/12/22 POUSHO, ROBERT 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED 04/26/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED 04/26/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED 04/26/24 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED 04/26/24 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED 04/26/24 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED 04/26/24 04/25/24 ROBERTS, PATRICK 8 3.20 ASSIGNED 04/26/24 04/26/24 ROBERTS, PATRICK 8 3.20 ASSIGNED 04/26/24 04/26/24 ROBERTS, PATRICK 8 3.20 ASSIGNED 04/26/24 04/26/24 ROBERTS, PATRICK 8 3.20 ASSIGNED 04/26/24 ROBERTS, PATRICK 8 3.20 ASSIGN	1004045	07/45/00	07/05/00				ACCIONED	Call Dhana	DD 1 42200	INCRECTION
1994845 07/15/22 07/07/22 POUSHO, ROBERT 8 3.20 ASSIGNED Cell Phone PR.1-13309 INSPECTION 1994845 07/15/22 07/15/22 POUSHO, ROBERT 8 3.20 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 3.20 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 18.72 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 18.72 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 18.72 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PR.1-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PR.1-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PR.1-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PR.1-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 04/26/22 04/26/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 04/27/22										
1994845 07/15/22 07/16/22 POUSHO, ROBERT 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED CEIPhone PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED CEIPhone PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED CEIPhone PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED CEIPhone PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 48.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS,										
1994845 07/15/22 07/12/22 POUSHO, ROBERT 8 3.20 ASSIGNED P.C. Cell Phone PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 3.20 ASSIGNED P.C. Cell Phone PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 18.72 ASSIGNED P.C. Cell Phone PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 18.72 ASSIGNED P.C. Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 18.72 ASSIGNED P.C. Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED P.C. Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 5.69 ASSIGNED P.C. Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 45.52 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 45.52 ASSIGNED P.C. Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 18.72 ASSIGNED P.C. Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 18.72 ASSIGNED P.C. Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 3.20 ASSIGNED P.C. Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 3.20 ASSIGNED P.C. Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 3.20 ASSIGNED P.C. Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 3.20 ASSIGNED P.C. Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 3.20 ASSIGNED P.C. Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 18.72 ASSIGNED P.C. Computer PRJ-13309 INSPE				-						
1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 2.34 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 4.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845				,						
1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION POUSHO, ROBERT 7 POUSHO, ROBERT 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION POUSHO, ROBERT Total 87.68 SIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/26/22 04/25/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/26/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/26/22 04/25/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/26/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/26/22 04/25/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/26/22 04/25/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASS										
1994845 07/15/22 07/14/22 POUSHO, ROBERT 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION POUSHO, ROBERT Total 8 87.68	1094845		07/12/22	POUSHO, ROBERT	8			PC/Computer		
POUSHO, ROBERT Total 87.68	1094845	07/15/22	07/14/22	POUSHO, ROBERT	8	3.20	ASSIGNED		PRJ-13309	INSPECTION
POUSHO, ROBERT Total 87.68	1094845	07/15/22	07/14/22	POUSHO, ROBERT	8	18.72	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845										
1094845 04/26/22 04/25/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/26/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/26/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/26/22 04/25/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/26/22 04/25/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22	1094845	04/26/22					ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/26/22 04/26/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 04/27/22 04/27/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845										
1994845 04/25/22 04/25/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 2.34 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 04/26/22 04/25/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/122 04/26/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/122 04/26/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/122 04/26/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/122 04/26/22 ROBERTS, PATRICK 8 45.52 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 04/27/122 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED DEL PRDI PRJ-13309 INSPECTION 1994845 04/27/122 04/26/22 ROBERTS, PATRICK 1 5.69 ASSIGNED DEL PRDI PRJ-13309 INSPECTION 1994845 04/27/122 04/26/22 ROBERTS, PATRICK 1 5.69 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/122 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/122 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/122 04/27/122 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/122 04/27/122 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/122 04/27/122 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/27/122 04/27/122 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/28/122 04/28/122 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04/28/122 04/28/122 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 04										
1094845										
1094845										
1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 5.69 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 8 3.20 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845										
1094845										
1094845 04/27/22 04/26/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 8 3.20 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 0.80 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 0.80 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845										
1094845 04/27/22 04/26/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 O4/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 O4/27/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 0.80 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/										
1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 5.69 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 5.69 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 8 3.20 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 <	1094845									
1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 5.69 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 5.69 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04	1094845				8				PRJ-13309	INSPECTION
1094845 04/27/22 04/26/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/27/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 ROBERTS, PATRICK 1 5.69 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/27/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/27/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 ROBERTS, PATRICK 8 18.72 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22 ROBERTS, PATRICK 2 11.38 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/29/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSP			04/26/22	ROBERTS, PATRICK		0.40				
1094845 04/27/22 04/27/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/27/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22	1094845		04/26/22	ROBERTS, PATRICK	1			1/2 Ton Pick-up		
1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22				·				PC/Computer		
1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/27/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22									PRJ-13309	
1094845 04/27/22 04/27/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22										
1094845 04/27/22 04/27/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/27/22 04/27/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 <										
1094845 04/27/22 04/27/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/29/22										
1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 1.38 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/29/22 04										
1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/29/22			04/27/22	ROBERTS, PATRICK						
1094845 04/28/22 04/28/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>										
1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>										
1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22	1094845									
1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22	1094845	04/28/22	04/28/22	ROBERTS, PATRICK			ASSIGNED	Cell Phone	PRJ-13309	
1094845 04/28/22 04/28/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 5.69 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 05/02/22		04/28/22								
1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 05/02/22		04/28/22								
1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 05/02/22										
1094845 04/29/22 04/29/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 05/02/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION										
1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION										
1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION										
1094845 04/29/22 04/29/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION										
1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION										
1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION										
1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION										
1094845 05/02/22 05/02/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION						3.20	ASSIGNED			
	1004045	05/02/22	05/02/22	ROBERTS, PATRICK	8	45.52	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION

1094845	05/02/22	05/02/22	ROBERTS, PATRICK	1	0.40	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/02/22		ROBERTS, PATRICK	1		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/02/22		ROBERTS, PATRICK	1		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/04/22		ROBERTS, PATRICK	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/04/22		ROBERTS, PATRICK	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/04/22		ROBERTS, PATRICK	8		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/04/22	05/04/22	ROBERTS, PATRICK	1	2.34	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/04/22	05/04/22	ROBERTS, PATRICK	1	0.40	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/04/22	05/04/22	ROBERTS, PATRICK	1	5.69	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/05/22		ROBERTS, PATRICK	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/05/22		ROBERTS, PATRICK	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/05/22		ROBERTS, PATRICK	8		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/05/22		ROBERTS, PATRICK	2		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/05/22		ROBERTS, PATRICK	2		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/05/22		ROBERTS, PATRICK	2		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/06/22		ROBERTS, PATRICK	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/06/22	05/06/22	ROBERTS, PATRICK	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/06/22	05/06/22	ROBERTS, PATRICK	8	45.52	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/06/22	05/06/22	ROBERTS, PATRICK	1	2.34	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/06/22	05/06/22	ROBERTS, PATRICK	1	0.40	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/06/22		ROBERTS, PATRICK	1	5.69	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/09/22		ROBERTS, PATRICK	1		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/09/22		ROBERTS, PATRICK	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/09/22		ROBERTS, PATRICK	8		ASSIGNED	PC/Computer	PRJ-13309 PRJ-13309	INSPECTION
			·						
1094845	05/09/22		ROBERTS, PATRICK	8		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/09/22		ROBERTS, PATRICK	1	-	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/09/22		ROBERTS, PATRICK	1		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/10/22		ROBERTS, PATRICK	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/10/22	05/10/22	ROBERTS, PATRICK	8	18.72	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/10/22	05/10/22	ROBERTS, PATRICK	8		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/10/22	05/10/22	ROBERTS, PATRICK	1	0.40	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/10/22		ROBERTS, PATRICK	1		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/10/22		ROBERTS, PATRICK	1		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/11/22		ROBERTS, PATRICK	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/11/22		ROBERTS, PATRICK	8		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
							•		
1094845	05/11/22		ROBERTS, PATRICK	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/11/22		ROBERTS, PATRICK	2		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/11/22		ROBERTS, PATRICK	2		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/11/22	05/11/22	ROBERTS, PATRICK	2		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/12/22	05/12/22	ROBERTS, PATRICK	8	3.20	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/12/22	05/12/22	ROBERTS, PATRICK	8	45.52	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/12/22	05/12/22	ROBERTS, PATRICK	8	18.72	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/12/22		ROBERTS, PATRICK	2		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/12/22		ROBERTS, PATRICK	2		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/12/22		ROBERTS, PATRICK	2		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
				8		ASSIGNED	· · · · · · · · · · · · · · · · · · ·	PRJ-13309	INSPECTION
1094845	05/13/22		ROBERTS, PATRICK				Cell Phone		
1094845	05/13/22		ROBERTS, PATRICK	8		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/13/22		ROBERTS, PATRICK	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/13/22		ROBERTS, PATRICK	2		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/13/22	05/13/22	ROBERTS, PATRICK	2		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/13/22	05/13/22	ROBERTS, PATRICK	2	0.80	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/14/22	05/14/22	ROBERTS, PATRICK	10	4.00	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/14/22		ROBERTS, PATRICK	10		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/14/22		ROBERTS, PATRICK	10		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/15/22		ROBERTS, PATRICK	9		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/15/22		ROBERTS, PATRICK	9		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
	05/15/22		· · · · · · · · · · · · · · · · · · ·				•		
1094845			ROBERTS, PATRICK	9		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/16/22		ROBERTS, PATRICK	1		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/16/22		ROBERTS, PATRICK	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/16/22		ROBERTS, PATRICK	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/16/22		ROBERTS, PATRICK	8		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/16/22	05/16/22	ROBERTS, PATRICK	1		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/16/22		ROBERTS, PATRICK	1		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/18/22		ROBERTS, PATRICK	1		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/18/22		ROBERTS, PATRICK	1		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/18/22		ROBERTS, PATRICK	1		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/18/22		ROBERTS, PATRICK	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845									
	05/18/22		ROBERTS, PATRICK	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/18/22		ROBERTS, PATRICK	8		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/19/22		ROBERTS, PATRICK	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/19/22		ROBERTS, PATRICK	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/19/22		ROBERTS, PATRICK	8		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/19/22	05/19/22	ROBERTS, PATRICK	2	0.80	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	05/19/22		ROBERTS, PATRICK	2		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	05/19/22		ROBERTS, PATRICK	2		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/20/22		ROBERTS, PATRICK	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	05/20/22		ROBERTS, PATRICK	1		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1034040	03/20/22	03/20/22	INODENTO, I ATRICK		0.40	, COIGINED	CONTRIBUTE	1110-10008	LINOI LOTION

1994845	1094845	05/20/22	05/20/22	ROBERTS, PATRICK	1	5.69	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1969465 0-520/022 05620/22 05620/22 05620/22 05620/23										
1994866										
1994946 0622/22 0622/22 0628/27 PATRICK 8 3.0 ASSIGNED Call Phone PAL-1309 INSPECTION Call Phone										
199445										
1998986 092322 ROBERTS, PATRICK S										
1998946										
1984845 052322 052522		05/23/22								
1988481 0952322 ROBERTS, PATRICK 1 5.88 ASSIGNED 1/2 Ton Pockup PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 8 13.20 ASSIGNED Computer PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 8 13.20 ASSIGNED Computer PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 1 2.41 ASSIGNED PCC-omputer PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 1 2.41 ASSIGNED PCC-omputer PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 1 2.41 ASSIGNED PCC-omputer PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 2 4.68 ASSIGNED PCC-omputer PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 2 4.68 ASSIGNED PCC-omputer PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 2 4.68 ASSIGNED PCC-omputer PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 2 4.68 ASSIGNED PCC-omputer PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 2 4.68 ASSIGNED PCC-omputer PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 2 4.68 ASSIGNED PCC-omputer PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 2 4.68 ASSIGNED PCC-omputer PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 2 4.68 ASSIGNED PCC-omputer PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 2 4.68 ASSIGNED PCC-omputer PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 2 4.68 ASSIGNED PCC-omputer PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 2 4.68 ASSIGNED PCC-omputer PRJ-13309 INSPECTION 1098481 052522 055252 ROBERTS, PATRICK 3 4.68 ASSIGNED PCC-omputer PRJ-13309 INSPECTION 1098481 052522 055222 ROBERTS, PATRICK 3 4.68 ASSIGNED PCC-omputer PRJ-13309 INSPECTION 1										_
1998485										
1904945 952522 9052522 ROBERTS, PATRICK 8 16.72 ASSIGNED PC/Computer PR-L13390 INSPECTION 1904945 952522 9052622 ROBERTS, PATRICK 1 0.40 ASSIGNED Call Phone PR-L13390 INSPECTION 1904945 952522 9052622 ROBERTS, PATRICK 1 0.40 ASSIGNED Call Phone PR-L13390 INSPECTION 1904945 952522 9052622 ROBERTS, PATRICK 1 5.89 ASSIGNED PC/Computer PR-L13398 INSPECTION 1904945 952622 9052622 ROBERTS, PATRICK 2 4.60 ASSIGNED PC/Computer PR-L13398 INSPECTION 1904945 952622 9052622 ROBERTS, PATRICK 2 4.60 ASSIGNED PC/Computer PR-L13398 INSPECTION 1904945 952622 9052622 ROBERTS, PATRICK 8 19.72 ASSIGNED PC/Computer PR-L13398 INSPECTION 1904945 952622 9052622 ROBERTS, PATRICK 8 19.72 ASSIGNED PC/Computer PR-L13398 INSPECTION 1904946 952622 9052622 ROBERTS, PATRICK 8 19.72 ASSIGNED PC/Computer PR-L13399 INSPECTION 1904946 952622 9052622 ROBERTS, PATRICK 8 19.72 ASSIGNED PC/Computer PR-L13399 INSPECTION 1904946 952622 9052622 ROBERTS, PATRICK 8 19.72 ASSIGNED PC/Computer PR-L13399 INSPECTION 1904946 952622 9052622 ROBERTS, PATRICK 8 19.72 ASSIGNED PC/Computer PR-L13399 INSPECTION 1904946 952722 9052722 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PR-L13399 INSPECTION 1904946 952722 9052722 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PR-L13399 INSPECTION 1904946 952722 9052722 ROBERTS, PATRICK 8 45.22 ASSIGNED PC/Computer PR-L13399 INSPECTION 1904946 952722 9052722 ROBERTS, PATRICK 2 4.60 ASSIGNED PC/Computer PR-L13399 INSPECTION 1904946 952722 9052722 ROBERTS, PATRICK 2 4.60 ASSIGNED PC/Computer PR-L13399 INSPECTION 1904946 952722 905272 ROBERTS, PATRICK 2 4.60 ASSIGNED PC/Computer PR-L13399 INSPECTION 1904946 905272 9054722 9054722 9054723 9054723 905473 905473										
1998465										
1908445 1952-222 0.952-222 ROSERTS, PATRICK 1										
1994845				,						
1094845 105/26/22 05/26/22 ROBERTS, PATRICK 1 5.68 ASSIGNED 12 Ton Pilo-lup PRJ-13339 INSPECTION 1094845 05/26/22 05/26/22 ROBERTS, PATRICK 2 4.68 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/26/22 05/26/22 ROBERTS, PATRICK 3 3.20 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/26/22 05/26/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/26/22 05/26/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/26/22 05/26/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/26/22 05/26/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/27/22 05/27/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/27/22 05/27/22 ROBERTS, PATRICK 8 18.72 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/27/22 05/27/22 ROBERTS, PATRICK 8 45.52 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/27/22 05/27/22 ROBERTS, PATRICK 8 45.52 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/27/22 05/27/22 ROBERTS, PATRICK 8 45.52 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/27/22 05/27/22 ROBERTS, PATRICK 8 45.52 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/27/22 05/27/22 ROBERTS, PATRICK 8 43.20 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/27/22 05/27/22 ROBERTS, PATRICK 8 43.20 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/27/22 05/27/22 ROBERTS, PATRICK 8 43.20 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/27/22 05/27/22 ROBERTS, PATRICK 8 45.52 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/27/22 05/27/22 ROBERTS, PATRICK 8 45.52 ASSIGNED Cell Phone PRJ-13339 INSPECTION 1094845 05/27/22 05/27/22										
19684465										
1994845										
1994445	1094845		05/26/22	ROBERTS, PATRICK				PC/Computer		INSPECTION
1994465	1094845	05/26/22	05/26/22	ROBERTS, PATRICK	8	3.20	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845 05/28/22 05/28/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Call Phone PRI-13309 INSPECTION 1094845 05/27/22 ROBERTS, PATRICK 2 1.33 ASSIGNED 12 TON PICKUP PRI-13309 INSPECTION 1094845 05/27/22 ROBERTS, PATRICK 8 3.20 ASSIGNED 12 TON PICKUP PRI-13309 INSPECTION 1094845 05/27/22 ROBERTS, PATRICK 8 4.52 ASSIGNED PC/Computer PRI-13309 INSPECTION 1094846 05/27/22 ROBERTS, PATRICK 8 4.52 ASSIGNED PC/Computer PRI-13309 INSPECTION 1094846 05/37/22 ROBERTS, PATRICK 8 4.52 ASSIGNED PC/Computer PRI-13309 INSPECTION 1094846 05/37/22 ROBERTS, PATRICK 8 4.52 ASSIGNED 12 TON PICKUP PRI-13309 INSPECTION 1094846 05/37/22 ROBERTS, PATRICK 8 4.52 ASSIGNED 12 TON PICKUP PRI-13309 INSPECTION 1094846 05/37/22 CALLER ROBERTS, PATRICK 8 4.52 ASSIGNED 12 TON PICKUP PRI-13309 INSPECTION 1094846 05/37/22 CALLER ROBERTS, PATRICK 2 4.68 ASSIGNED 12 TON PICKUP PRI-13309 INSPECTION 1094846 05/37/22 CALLER ROBERTS, PATRICK 2 4.68 ASSIGNED 12 TON PICKUP PRI-13309 INSPECTION 1094846 05/37/22 CALLER ROBERTS, PATRICK 2 4.68 ASSIGNED 12 TON PICKUP PRI-13309 INSPECTION 1094846 05/37/22 CALLER ROBERTS, PATRICK 3 4.52 ASSIGNED 12 TON PICKUP PRI-13309 INSPECTION 1094846 05/37/22 CALLER ROBERTS, PATRICK 3 4.52 ASSIGNED 12 TON PICKUP PRI-13309 INSPECTION 1094846 05/37/22 CALLER ROBERTS, PATRICK 3 4.52 ASSIGNED 12 TON PICKUP PRI-13309 INSPECTION 1094846 05/07/22 ROBERTS, PATRICK 3 4.72 ASSIGNED 12 TON PICKUP PRI-13309 INSPECTION 1094846 05/07/22 ROBERTS, PATRICK 3 4.72 ASSIGNED 12 TON PICKUP PRI-13309 INSPECTION 1094846 05/07/22 ROBERTS, PATRICK 4 4.68 ASSIGNED PC/Computer PRI-13309 INSPECTION 1094846 05/07/22 ROBERTS, PATRICK 4 4.68 ASSIGNED PC/Computer PRI-13309 INSPECTION 1094846 05/07/22	1094845				8	18.72	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1994945	1094845	05/26/22	05/26/22	ROBERTS, PATRICK	8	45.52	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845 09527722 09527728 09527728 PATRICK 8 3.20 ASSIGNED PC-COmputer PR-L13309 INSPECTION 1094845 0952772 095272	1094845				2	0.80	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845 09527722 09527728 09527728 PATRICK 8 3.20 ASSIGNED PC-COmputer PR-L13309 INSPECTION 1094845 0952772 095272	1094845				2			1/2 Ton Pick-up	PRJ-13309	
1994845 0527722 0527722 NOBERTS, PATRICK 8 18.72 ASSIGNED P.Computer PRJ. 13399 INSPECTION 1994845 0531722 053122 ROBERTS, PATRICK 2 0.80 ASSIGNED P.Computer PRJ. 13399 INSPECTION 1994845 0531722 NOSE PRJ. 13399 PRJ. 13399 INSPECTION 1994845 053172 NOSE PRJ. 13399 PRJ. 13399 INSPECTION 1994845 053172 NOSE PRJ. 13399 PRJ. 13399 INSPECTION 1994845 053172 NOSE PRJ. 13399 PRJ. 13399 INSPECTION 1994845 050172 NOSE PRJ. 13399 INSPECTION 1994845 050072 050072 ROBERTS, PATRICK 1994845 1994845 050072 NOSE PRJ. 13399 INSPECTION 1994845 050072 050072 ROBERTS, PATRICK 1994845 1994845 050092 050092 ROBERTS, PATRICK 1994845 1994845	1094845									
1994845 0527722 0567722 NOBERTS, PATRICK B 45.52 ASSIGNED 121 FOR Pickup PR-I-13309 INSPECTION 1994845 0531722 0567122 NOBERTS, PATRICK B 3.20 ASSIGNED Cell Phone PR-I-13309 INSPECTION 1994846 0531722 0567122 NOBERTS, PATRICK B 8.20 ASSIGNED Cell Phone PR-I-13309 INSPECTION 1994846 0531722 05671722 NOBERTS, PATRICK B 16.72 ASSIGNED PC-Computer PR-I-13309 INSPECTION 1994846 0537122 05671722 NOBERTS, PATRICK B 46.52 ASSIGNED PC-Computer PR-I-13309 INSPECTION 1994846 0573122 05671722 NOBERTS, PATRICK B 46.52 ASSIGNED PC-Computer PR-I-13309 INSPECTION 1994846 0573122 05671722 NOBERTS, PATRICK B 3.20 ASSIGNED PC-Computer PR-I-13309 INSPECTION 1994845 0567122 0567122 NOBERTS, PATRICK B 3.20 ASSIGNED PC-Computer PR-I-13309 INSPECTION 1994846 0567122 0567122 0567122 NOBERTS, PATRICK B 3.20 ASSIGNED PC-Computer PR-I-13309 INSPECTION 1994846 0567122 056712										
1094445 05/31/22 05/31/22 O5/31/22										
1994845										
1994845 0531/22 0531/22 0561/22 NOBERTS, PATRICK 8 8.72 ASSIGNED 1/2 Ton Pick-up PRJ-13399 INSPECTION 1994845 0531/22 0531/22 NOBERTS, PATRICK 2 4.88 ASSIGNED 1/2 Ton Pick-up PRJ-13399 INSPECTION 1994845 0531/22 0501/22 NOBERTS, PATRICK 2 4.88 ASSIGNED 1/2 Ton Pick-up PRJ-13399 INSPECTION 1994845 0501/22 0601/22 NOBERTS, PATRICK 2 1.38 ASSIGNED 1/2 Ton Pick-up PRJ-13399 INSPECTION 1994845 0501/22 0601/22 NOBERTS, PATRICK 8 3.20 ASSIGNED 1/2 Ton Pick-up PRJ-13399 INSPECTION 1994845 0501/22 0601/22 NOBERTS, PATRICK 8 4.52 ASSIGNED 1/2 Ton Pick-up PRJ-13399 INSPECTION 1994845 0501/22 0601/22 NOBERTS, PATRICK 3 1.20 ASSIGNED 1/2 Ton Pick-up PRJ-13399 INSPECTION 1994845 0501/22 0601/22 NOBERTS, PATRICK 3 1.20 ASSIGNED 1/2 Ton Pick-up PRJ-13399 INSPECTION 1994845 0501/22 0601/22 NOBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13399 INSPECTION 1994845 0501/22 0601/22 NOBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13399 INSPECTION 1994845 0500/222 0600/222 NOBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13399 INSPECTION 1994845 0500/222 0600/222 NOBERTS, PATRICK 2 1.38 ASSIGNED PC/Computer PRJ-13399 INSPECTION 1994845 0500/222 0600/222 NOBERTS, PATRICK 2 1.38 ASSIGNED PC/Computer PRJ-13399 INSPECTION 1994845 0500/222 0600/222 NOBERTS, PATRICK 2 1.38 ASSIGNED PC/Computer PRJ-13399 INSPECTION 1994845 0500/222 0600/222 NOBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13399 INSPECTION 1994845 0500/222 0600/222 NOBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13399 INSPECTION 1994845 0500/222 0600/222 NOBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13399 INSPECTION 1994845 0500/222 0600/222 0600/222 NOBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13399 INSPECTION 1994845 0500/222 060										
1994845 05/31/22 09/31/22 ROBERTS, PATRICK 8 4.5.52 ASSIGNED 1/2 Ton Pick-up PR.113309 INSPECTION 1994845 05/31/22 05/31/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PR.113309 INSPECTION 1994845 05/31/22 06/01/22 ROBERTS, PATRICK 8 3.20 ASSIGNED 1/2 Ton Pick-up PR.113309 INSPECTION 1994846 06/01/22 06/01/22 06/01/22 ROBERTS, PATRICK 8 4.5.2 ASSIGNED 1/2 Ton Pick-up PR.113309 INSPECTION 1994846 06/01/22 06/01/22 ROBERTS, PATRICK 8 4.5.2 ASSIGNED 1/2 Ton Pick-up PR.113309 INSPECTION 1994846 06/01/22 06/01/22 ROBERTS, PATRICK 8 1.7.2 ASSIGNED 1/2 Ton Pick-up PR.113309 INSPECTION 1994846 06/01/22 06/01/22 ROBERTS, PATRICK 8 1.7.2 ASSIGNED 1/2 Ton Pick-up PR.113309 INSPECTION 1994846 06/01/22 06/01/22 ROBERTS, PATRICK 8 1.7.2 ASSIGNED 1/2 Ton Pick-up PR.113309 INSPECTION 1994845 06/01/22 06/01/22 06/01/22 ROBERTS, PATRICK 8 1.7.2 ASSIGNED PC/Computer PR.113309 INSPECTION 1994845 06/01/22 06/01/22 ROBERTS, PATRICK 8 1.7.2 ASSIGNED PC/Computer PR.113309 INSPECTION 1994845 06/01/22 06/01/22 ROBERTS, PATRICK 8 1.7.2 ASSIGNED PC/Computer PR.113309 INSPECTION 1994845 06/02/22 06/02/22 06/02/22 ROBERTS, PATRICK 2 0.80 ASSIGNED PC/Computer PR.113309 INSPECTION 1994845 06/02/22 06/02/22 ROBERTS, PATRICK 2 0.80 ASSIGNED PC/Computer PR.113309 INSPECTION 1994845 06/02/22 06/02/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PR.113309 INSPECTION 1994845 06/02/22 06/02/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PR.113309 INSPECTION 1994845 06/02/22 06/02/22 ROBERTS, PATRICK 8 4.52 ASSIGNED PC/Computer PR.113309 INSPECTION 1994845 06/02/22 06/02/22 ROBERTS, PATRICK 8 4.52 ASSIGNED PC/Computer PR.113309 INSPECTION 1994845 06/02/22 06/02/22 ROBERTS, PATRICK 1 0.40 AS										
1094945										
1094845 05/01/22 005/12/2 NOSERTS, PATRICK 2										
1094845 0601/122										
1094845 0601/122 0601/122 0601/122 0705/152										
1094845 0601/122 0601/122 0705/127										
1994845 0601122 0601122 060122 07058FTS, PATRICK 3 17.07 ASSIGNED 1/2 TOR PICK-UP PRJ-13309 INSPECTION 1994845 0601122 060122 07058FTS, PATRICK 3 7.02 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 060122 060122 07058FTS, PATRICK 3 7.02 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 0600222 0600222 07058FTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 0600222 0600222 07058FTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994846 0600222 0600222 07058FTS, PATRICK 2 11.88 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 0600222 0600222 07058FTS, PATRICK 2 11.88 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 0600222 0600222 07058FTS, PATRICK 8 45.52 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 060022 0600222 07058FTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 0600622 0600622 07058FTS, PATRICK 8 45.52 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 0600622 0600622 07058FTS, PATRICK 8 45.52 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 0600622 0600622 07058FTS, PATRICK 8 45.52 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 0600622 0600622 07058FTS, PATRICK 8 45.52 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 0600622 0600622 07058FTS, PATRICK 8 45.52 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 0600622 0600622 07058FTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 0600622 0600622 07058FTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 0600622 0600622 07058FTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 0600622 0600622 07058FTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 0600622 0600622 07058FT										
1994845 060/11/22 060/11/22 ROBERTS, PATRICK 8 18.72 ASSIGNED P.C.Computer PRJ-13309 INSPECTION 1994845 060/11/22 060/11/22 ROBERTS, PATRICK 8 18.72 ASSIGNED P.C.Computer PRJ-13309 INSPECTION 1994845 060/11/22 060/11/22 ROBERTS, PATRICK 2 0.80 ASSIGNED P.C.Computer PRJ-13309 INSPECTION 1994845 060/11/22 060/11/22 ROBERTS, PATRICK 2 11.88 ASSIGNED P.C.Computer PRJ-13309 INSPECTION 1994845 060/11/22 060/11/22 ROBERTS, PATRICK 8 3.20 ASSIGNED L/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 060/11/22 060/11/22 ROBERTS, PATRICK 8 45.52 ASSIGNED L/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 060/11/22 060/11/22 ROBERTS, PATRICK 8 45.52 ASSIGNED L/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 060/11/22 060/11/22 ROBERTS, PATRICK 8 3.20 ASSIGNED L/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 060/11/22 060/11/22 ROBERTS, PATRICK 8 3.20 ASSIGNED P.C.Computer PRJ-13309 INSPECTION 1994845 060/11/22 060/11/22 ROBERTS, PATRICK 8 45.52 ASSIGNED P.C.Computer PRJ-13309 INSPECTION 1994845 060/11/22 060/11/22 ROBERTS, PATRICK 8 45.52 ASSIGNED P.C.Computer PRJ-13309 INSPECTION 1994845 060/11/22 060/11/22 ROBERTS, PATRICK 8 18.72 ASSIGNED P.C.Computer PRJ-13309 INSPECTION 1994845 060/11/22 ROBERTS, PATRICK 1 2.34 ASSIGNED P.C.Computer PRJ-13309 INSPECTION 1994845 060/11/22 060/11/22 ROBERTS, PATRICK 1 5.69 ASSIGNED P.C.Computer PRJ-13309 INSPECTION 1994845 060/11/22 060/11/22 ROBERTS, PATRICK 1 5.69 ASSIGNED P.C.Computer PRJ-13309 INSPECTION 1994845 060/11/22 060/11/22 ROBERTS, PATRICK 1 5.69 ASSIGNED P.C.Computer PRJ-13309 INSPECTION 1994845 060/11/22 060/11/22 ROBERTS, PATRICK 1 2.34 ASSIGNED P.C.Computer PRJ-13309 INSPECTION 1994845 060/11/22 060/11/22 ROBERTS, PATRICK 1 2.34 ASSIGNED P.C.Co										
1994845 08/01/22 08/01/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PR,1-13309 INSPECTION 1994845 08/02/22 08/02/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PR,1-13309 INSPECTION 1994845 08/02/22 08/02/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PR,1-13309 INSPECTION 1994845 08/02/22 08/02/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PR,1-13309 INSPECTION 1994845 08/02/22 08/02/22 ROBERTS, PATRICK 8 4.52 ASSIGNED Cell Phone PR,1-13309 INSPECTION 1994845 08/02/22 08/02/22 ROBERTS, PATRICK 8 4.52 ASSIGNED Cell Phone PR,1-13309 INSPECTION 1994845 08/02/22 08/02/22 ROBERTS, PATRICK 8 4.52 ASSIGNED Cell Phone PR,1-13309 INSPECTION 1994845 08/06/22 08/06/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PR,1-13309 INSPECTION 1994845 08/06/22 08/06/22 ROBERTS, PATRICK 8 4.552 ASSIGNED Cell Phone PR,1-13309 INSPECTION 1994845 08/06/22 08/06/22 ROBERTS, PATRICK 8 4.552 ASSIGNED 1/2 Ton Pick-up PR,1-13309 INSPECTION 1994845 08/06/22 08/06/22 ROBERTS, PATRICK 8 4.552 ASSIGNED PC/Computer PR,1-13309 INSPECTION 1994845 08/06/22 08/06/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PR,1-13309 INSPECTION 1994845 08/06/22 08/06/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PR,1-13309 INSPECTION 1994845 08/06/22 08/06/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PR,1-13309 INSPECTION 1994845 08/06/22 08/06/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PR,1-13309 INSPECTION 1994845 08/06/22 08/06/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PR,1-13309 INSPECTION 1994845 08/06/22 ROBERTS, PATRICK 8 4.52 ASSIGNED PC/Computer PR,1-13309 INSPECTION 1994845 08/06/22 ROBERTS, PATRICK 8 4.52 ASSIGNED PC/Computer PR,1-13309 INSPECTION 1994845 08/06/22 ROBERTS, PA										
1994845 06/02/22 06/02/22 ROBERTS, PATRICK 2 0.80 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/02/22 06/02/22 ROBERTS, PATRICK 2 1.138 ASSIGNED 1/2 TOP PICK-up PRJ-13309 INSPECTION 1994845 06/02/22 06/02/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 TOP PICK-up PRJ-13309 INSPECTION 1094845 06/02/22 06/02/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 TOP PICK-up PRJ-13309 INSPECTION 1094845 06/02/22 06/02/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 TOP PICK-up PRJ-13309 INSPECTION 1094845 06/02/22 06/02/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 TOP PICK-up PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 TOP PICK-up PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 TOP PICK-up PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 8 14.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 8 14.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 1 5.69 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 1 5.69 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 8 14.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 8 14.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 8 14.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 8 14.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/06/22 ROBERTS, PATRICK 8 14.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION										
1994845 06/02/22 06/02/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PR.1-13309 INSPECTION 1994845 06/02/22 06/02/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PR.1-13309 INSPECTION 1994845 06/02/22 06/02/22 ROBERTS, PATRICK 8 45.52 ASSIGNED Cell Phone PR.1-13309 INSPECTION 1994845 06/02/22 06/02/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 06/02/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 06/06/22 06/06/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 06/06/22 06/06/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 06/06/22 06/06/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 06/06/22 06/06/22 ROBERTS, PATRICK 1 2.44 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 06/06/22 06/06/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 06/06/22 06/06/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 06/06/22 06/06/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 06/06/22 06/06/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 06/06/22 06/06/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 06/06/22 06/08/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 06/08/22 06/08/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 06/08/22 06/08/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 06/08/22 06/08/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1994845 06/08/22										
1994845 06/02/22 06/02/22 ROBERTS, PATRICK 2										
1994845 06/02/22 06/02/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 06/02/22 06/02/22 ROBERTS, PATRICK 2 4.68 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 06/06/22 06/06/22 ROBERTS, PATRICK 8 4.52 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 8 4.52 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 8 4.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 1 0.40 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/08/22 06/08/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/08/22 06/08/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/08/22 06/08/22 ROBERTS, PATRICK 8 4.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/08/22 ROBERTS, PATRICK 8 4.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/08/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/08/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/08/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/09/22 06/09/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/09/22 06/09/22 ROBERTS, PATRICK 1 0.40										
1994845 06/02/22 06/02/22 ROBERTS, PATRICK 8										
1994845 06/08/22 06/06/22										
1994845 06/06/22 06/06/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PR.1-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 8 4.55.2 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1094845 06/06/22 06/06/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PR.1-13309 INSPECTION 1094845 06/06/22 06/08/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 12 Ton Pick-up PR.1-13309 INSPECTION 1094845 06/08/22 06/08/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1094845 06/08/22 06/08/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1094845 06/08/22 06/08/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1094845 06/08/22 06/08/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1094845 06/08/22 06/08/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1094845 06/08/22 06/08/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1094845 06/09/22 06/08/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1094845 06/09/22 06/09/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1094845 06/09/22 06/09/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1094845 06/09/22 06/09/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PR.1-13309 INSPECTION 1094845 06/09/22 06/09/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PR.1-13309 INSPECTION 10										
1094845	1094845									
1994845	1094845	06/06/22	06/06/22	ROBERTS, PATRICK	8	3.20	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1994845 06/06/22 06/06/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/06/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1994845 06/06/22 06/06/22 ROBERTS, PATRICK 8 3.20 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1994845 06/08/22 06/08/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/08/22 06/08/22 ROBERTS, PATRICK 8 8.18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/08/22 06/08/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/08/22 06/08/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/08/22 06/08/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/08/22 06/08/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/09/22 06/09/22 ROBERTS, PATRICK 1 5.69 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/09/22 06/09/22 ROBERTS, PATRICK 8 8.12.7 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/09/22 06/09/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/09/22 06/09/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/09/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/09/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/09/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/09/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/10/22 ROBERTS, PATRICK 1 3.69 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1994845 06/10/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-1330	1094845	06/06/22	06/06/22	ROBERTS, PATRICK	8	45.52	ASSIGNED		PRJ-13309	INSPECTION
1994845	1094845	06/06/22	06/06/22	ROBERTS, PATRICK	8	18.72	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	1094845	06/06/22	06/06/22	ROBERTS, PATRICK	1	2.34	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	1094845	06/06/22	06/06/22	ROBERTS, PATRICK	1	0.40	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	1094845	06/06/22	06/06/22	ROBERTS, PATRICK	1	5.69	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	1094845		06/08/22	ROBERTS, PATRICK	8			Cell Phone	PRJ-13309	
1094845	1094845									
1094845										
1094845				,						
1094845 06/08/22 06/08/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/09/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/09/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/09/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/09/22 06/09/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/09/22 ROBERTS, PATRICK 1 0.40 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/09/22 ROBERTS, PATRICK 1 5.69 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/10/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up										
1094845										
1094845 06/09/22 06/09/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/09/22 06/09/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/09/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/09/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/09/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/10/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/10/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/10/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer										
1094845 06/09/22 06/09/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/09/22 06/09/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/09/22 06/09/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/09/22 06/09/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 18.72 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/10/22										
1094845 06/09/22 06/09/22 ROBERTS, PATRICK 1 2.34 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/09/22 06/09/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/09/22 06/09/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 11.38 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 11.38 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/10/22									PRJ-13309	
1094845 06/09/22 06/09/22 ROBERTS, PATRICK 1 0.40 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/09/22 06/09/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/10/22										
1094845 06/09/22 06/09/22 ROBERTS, PATRICK 1 5.69 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/10/22 06/13/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22										
1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 11.38 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/10/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/10/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK										
1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22										
1094845 06/10/22 06/10/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 3.20 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>										
1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/13/22 <										
1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 45.52 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/										
1094845 06/10/22 06/10/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/15/22										
1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 0.80 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/15/22										
1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/15/22										
1094845 06/13/22 06/13/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/15/22 <										
1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION										
1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 4.68 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION										
1094845 06/13/22 06/13/22 ROBERTS, PATRICK 2 11.38 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION										
1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 18.72 ASSIGNED PC/Computer PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION		06/13/22								
1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 3.20 ASSIGNED Cell Phone PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION	1094845									
1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION										
1094845 06/15/22 06/15/22 ROBERTS, PATRICK 8 45.52 ASSIGNED 1/2 Ton Pick-up PRJ-13309 INSPECTION 1094845 06/15/22 06/15/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION		06/15/22	06/15/22	ROBERTS, PATRICK	8					INSPECTION
1094845 06/15/22 06/15/22 ROBERTS, PATRICK 2 0.80 ASSIGNED Cell Phone PRJ-13309 INSPECTION	1094845				8	45.52	ASSIGNED	1/2 Ton Pick-up		
	1094845	06/15/22	06/15/22	ROBERTS, PATRICK	2	0.80	ASSIGNED	Cell Phone	PRJ-13309	

1094845	06/15/22	06/15/22	ROBERTS, PATRICK	2	4.68	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/15/22	06/15/22	ROBERTS, PATRICK	2	11.38	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/16/22	06/16/22	ROBERTS, PATRICK	8	3.20	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/16/22	06/16/22	ROBERTS, PATRICK	8	18.72	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/16/22	06/16/22	ROBERTS, PATRICK	8	45.52	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/16/22	06/16/22	ROBERTS, PATRICK	2	0.80	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/16/22	06/16/22	ROBERTS, PATRICK	2	4.68	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/16/22	06/16/22	ROBERTS, PATRICK	2	11.38	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/17/22	06/17/22	ROBERTS, PATRICK	8	3.20	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/17/22		ROBERTS, PATRICK	8	45.52	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/17/22	06/17/22	ROBERTS, PATRICK	8	18.72	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/17/22		ROBERTS, PATRICK	2	0.80	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/17/22	06/17/22	ROBERTS, PATRICK	2	11.38	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/17/22	06/17/22	ROBERTS, PATRICK	2	4.68	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/18/22	06/18/22	ROBERTS, PATRICK	8	3.20	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/18/22		ROBERTS, PATRICK	8	18.72	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/18/22		ROBERTS, PATRICK	8		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/20/22		ROBERTS, PATRICK	9		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/20/22		ROBERTS, PATRICK	9		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/20/22		ROBERTS, PATRICK	9		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/23/22		ROBERTS, PATRICK	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/23/22		ROBERTS, PATRICK	8	45.52	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/23/22		ROBERTS, PATRICK	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/23/22	06/22/22	ROBERTS, PATRICK	7	2.80	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/23/22		ROBERTS, PATRICK	7	16.38	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/23/22		ROBERTS, PATRICK	7	39.83	ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/23/22		ROBERTS, PATRICK	8		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/23/22		ROBERTS, PATRICK	8	3.20	ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/23/22		ROBERTS, PATRICK	8		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/23/22		ROBERTS, PATRICK	1		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/23/22		ROBERTS, PATRICK	1		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/23/22		ROBERTS, PATRICK	1		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/24/22		ROBERTS, PATRICK	8		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/24/22		ROBERTS, PATRICK	8	18.72	ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/24/22		ROBERTS, PATRICK	8		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/24/22		ROBERTS, PATRICK	1		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
1094845	06/24/22		ROBERTS, PATRICK	1		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/24/22		ROBERTS, PATRICK	1		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/30/22		ROBERTS, PATRICK	2		ASSIGNED	Cell Phone	PRJ-13309	INSPECTION
1094845	06/30/22		ROBERTS, PATRICK	2		ASSIGNED	PC/Computer	PRJ-13309	INSPECTION
1094845	06/30/22		ROBERTS, PATRICK	2		ASSIGNED	1/2 Ton Pick-up	PRJ-13309	INSPECTION
100.10.10	00,00,22	00,00,22	ROBERTS, PATRICK Total		3,228.69	7.00.0.122	., <u></u> .,	1110 10000	
1094849	07/08/22	02/18/22	PS Assigned Equipment	0		UNASSIGNED-		PRJ-13309	ENGINEERING
1094845	07/08/22		PS Assigned Equipment	0		UNASSIGNED-		PRJ-13309	INSPECTION
1094845	06/17/22		PS Assigned Equipment	0		UNASSIGNED-		PRJ-13309	INSPECTION
1094849	07/08/22		PS Assigned Equipment	0	(/	UNASSIGNED-		PRJ-13309	ENGINEERING
1094845	07/08/22		PS Assigned Equipment	0		UNASSIGNED-I		PRJ-13309	INSPECTION
1094849	07/08/22		PS Assigned Equipment	0		UNASSIGNED-		PRJ-13309	ENGINEERING
1094845	07/08/22		PS Assigned Equipment	0	(/	UNASSIGNED-		PRJ-13309	INSPECTION
1007043	01/00/22	04122122	PS Assigned Equipment	_	(4,613.16)	CIVACOIGINED-L		1 10-1000	INGI EGITON
			Grand Total	ı olai	407.14				
			Grand Total		407.14	1			

14/6:5	D. (. E	D.4. W. 1 1	N	11	O 1	0	A	D. 1	A
WOID	Date Entered		Name/Description	Hours/Units	Cost		Assign Equipment		Activity
1094815 1094815	5/11/22 5/11/22		BROWN, JOEL BROWN, JOEL	1.00 0.50		REGULAR REGULAR	WRCCON WRCCON	PRJ-13308 PRJ-13308	ENGINEERING ENGINEERING
1094815	5/11/22		BROWN, JOEL	2.50		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	5/11/22		BROWN, JOEL	3.50		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	5/11/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	5/11/22		BROWN, JOEL	2.50		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	2.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	1.50		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	3.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	2.50		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	2.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	2.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	6/20/22	5/24/22	BROWN, JOEL	0.50	62.73	REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	2.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	6/20/22	5/26/22	BROWN, JOEL	1.00	125.45	REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	6/20/22	5/27/22	BROWN, JOEL	0.50	62.73	REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	2.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	2.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	5.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	2.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	7/12/22		BROWN, JOEL	0.50		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	7/12/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	7/12/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815	7/12/22		BROWN, JOEL	1.00		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094815 1094815	7/12/22 7/12/22		BROWN, JOEL BROWN, JOEL	2.00 1.00		REGULAR REGULAR	WRCCON WRCCON	PRJ-13308 PRJ-13308	ENGINEERING ENGINEERING
1094815	7/12/22		BROWN, JOEL	1.50		REGULAR	WRCCON	PRJ-13308	ENGINEERING
1094013	1/12/22	1/1/22	BROWN, JOEL Total	1.50	6,523.45	REGULAR	WKCCON	FKJ-13306	ENGINEERING
1094815	6/2/22	5/16/22	LOCKHART, SIDNEY	1.00		REGULAR	WRCADM	PRJ-13308	ENGINEERING
1094815	6/2/22		LOCKHART, SIDNEY	1.00		REGULAR	WRCADM	PRJ-13308	ENGINEERING
1094815	6/6/22		LOCKHART, SIDNEY	1.00		REGULAR	WRCADM	PRJ-13308	ENGINEERING
1094815	6/17/22		LOCKHART, SIDNEY	2.00		REGULAR	WRCADM	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	2.00		REGULAR	WRCADM	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		REGULAR	WRCADM	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		REGULAR	WRCADM	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		REGULAR	WRCADM	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		REGULAR	WRCADM	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		REGULAR	WRCADM	PRJ-13308	ENGINEERING
1094815			LOCKHART, SIDNEY	1.00			WRCADM	PRJ-13308	ENGINEERING
1094815			LOCKHART, SIDNEY	1.00		REGULAR	WRCADM	PRJ-13308	ENGINEERING
1094815			LOCKHART, SIDNEY	1.00	136.37	REGULAR	WRCADM	PRJ-13308	ENGINEERING
1094815			LOCKHART, SIDNEY	1.00		REGULAR	WRCADM	PRJ-13308	ENGINEERING
1094815	7/15/22	7/13/22	LOCKHART, SIDNEY	1.00		REGULAR	WRCADM	PRJ-13308	ENGINEERING
			LOCKHART, SIDNEY To		2,318.29				
1094816			PARROTT, JEFFREY	1.00		REGULAR	WRCROW	PRJ-13308	ROW
1094816		5/5/22	PARROTT, JEFFREY	1.00		REGULAR	WRCROW	PRJ-13308	ROW
1094816	6/16/22	6/14/22	PARROTT, JEFFREY	2.00		REGULAR	WRCROW	PRJ-13308	ROW
			PARROTT, JEFFREY To	tal	326.60				
			Grand Total		9,168.34	1			

	J.11. 0 141 127 1 0	onstruction Pr	oject - WRC Labor/Fringes/N	on-Direct Labor Fac	tor for Trans D	oates - 04/23/202	2 - 07/15/2022 		
WOID D	ate Entered	Date Worked	Name/Description	Hours/Units	Cost	Cost Category	Assign Equipment	Project	Activity
1094815	5/11/22	4/26/22	BROWN, JOEL	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	5/11/22		BROWN, JOEL	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	5/11/22	4/26/22	BROWN, JOEL	1.00	0.25	ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	5/11/22	4/27/22	BROWN, JOEL	0.50	0.20	ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	5/11/22	4/27/22	BROWN, JOEL	0.50	1.17	ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	5/11/22		BROWN, JOEL	0.50		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	5/11/22		BROWN, JOEL	2.50		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	5/11/22		BROWN, JOEL	2.50		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	5/11/22		BROWN, JOEL	2.50		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	5/11/22		BROWN, JOEL	3.50		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	5/11/22		BROWN, JOEL	3.50		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	5/11/22		BROWN, JOEL	3.50		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	5/11/22		BROWN, JOEL	1.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815 1094815	5/11/22 5/11/22		BROWN, JOEL BROWN, JOEL	1.00		ASSIGNED ASSIGNED	Cell Phone PC/Computer	PRJ-13308 PRJ-13308	ENGINEERING ENGINEERING
1094815	5/11/22		BROWN, JOEL	2.50		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	5/11/22		BROWN, JOEL	2.50		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	5/11/22		BROWN, JOEL	2.50		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	2.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	2.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	2.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	1.50		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	1.50		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	1.50		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	5/26/22	5/12/22	BROWN, JOEL	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	5/26/22	5/12/22	BROWN, JOEL	1.00	0.40	ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	1.00	0.25	ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	5/26/22	5/13/22	BROWN, JOEL	3.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	3.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	3.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	2.50		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	2.50		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	2.50		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	1.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815 1094815	5/26/22 5/26/22		BROWN, JOEL BROWN, JOEL	2.00		ASSIGNED ASSIGNED	Tablet/iPad Cell Phone	PRJ-13308 PRJ-13308	ENGINEERING ENGINEERING
1094815	5/26/22		BROWN, JOEL	2.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	2.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	2.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	5/26/22		BROWN, JOEL	2.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	0.50		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	0.50		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	6/20/22	5/24/22	BROWN, JOEL	0.50	0.13	ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	6/20/22	5/25/22	BROWN, JOEL	2.00	0.80	ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	2.00	4.68	ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	2.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	1.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	0.50		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	0.50		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	0.50		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	2.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815 1094815	6/20/22		BROWN, JOEL BROWN, JOEL	2.00		ASSIGNED ASSIGNED	Cell Phone PC/Computer	PRJ-13308 PRJ-13308	ENGINEERING ENGINEERING
1094815	6/20/22 6/20/22		BROWN, JOEL	2.00		ASSIGNED	PC/Computer PC/Computer	PRJ-13308 PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	2.00		ASSIGNED	Tablet/iPad	PRJ-13308 PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	2.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	5.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	5.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	5.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	6/20/22	6/9/22	BROWN, JOEL	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	6/20/22	6/9/22	BROWN, JOEL	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	6/20/22	6/9/22	BROWN, JOEL	1.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	6/20/22	6/10/22	BROWN, JOEL	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	6/20/22	6/10/22	BROWN, JOEL	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	6/20/22	6/10/22	BROWN, JOEL	1.00	0.25	ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	6/20/22	6/13/22	BROWN, JOEL	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	1.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	2.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	2.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	6/20/22		BROWN, JOEL	2.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/12/22		BROWN, JOEL	0.50		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/12/22		BROWN, JOEL	0.50		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	7/12/22	6/21/22	BROWN, JOEL	0.50	0.20	ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING

1094815	7/12/22	6/22/22	BROWN, JOEL	1.00	0.40	ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	7/12/22	6/22/22	BROWN, JOEL	1.00	2.34	ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/12/22	6/22/22	BROWN, JOEL	1.00	0.25	ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	7/12/22		BROWN, JOEL	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/12/22		BROWN, JOEL	1.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
	7/12/22		,	1.00		ASSIGNED	Cell Phone	PRJ-13308	
1094815			BROWN, JOEL						ENGINEERING
1094815	7/12/22		BROWN, JOEL	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	7/12/22	6/24/22	BROWN, JOEL	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/12/22	6/24/22	BROWN, JOEL	1.00	0.25	ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	7/12/22	6/27/22	BROWN, JOEL	2.00	4.68	ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/12/22	6/27/22	BROWN, JOEL	2.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	7/12/22		BROWN, JOEL	2.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	7/12/22		BROWN, JOEL	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
			BROWN, JOEL						
1094815	7/12/22		- ,	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/12/22		BROWN, JOEL	1.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	7/12/22		BROWN, JOEL	1.50		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	7/12/22	7/1/22	BROWN, JOEL	1.50	3.51	ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/12/22	7/1/22	BROWN, JOEL	1.50	0.38	ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
			BROWN, JOEL Total		155.53				
1094815	6/2/22	5/16/22	LOCKHART, SIDNEY	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	6/2/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
			· · · · · · · · · · · · · · · · · · ·						
1094815	6/2/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Blazer/Suburbans	PRJ-13308	ENGINEERING
1094815	6/2/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	6/2/22	5/19/22	LOCKHART, SIDNEY	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	6/2/22	5/19/22	LOCKHART, SIDNEY	1.00	2.34	ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	6/2/22	5/19/22	LOCKHART, SIDNEY	1.00	5.69	ASSIGNED	Blazer/Suburbans	PRJ-13308	ENGINEERING
1094815	6/2/22	5/19/22	LOCKHART, SIDNEY	1.00	0.25	ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	6/6/22		LOCKHART, SIDNEY	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	6/6/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
			· · · · · · · · · · · · · · · · · · ·					PRJ-13300	
1094815	6/6/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	6/6/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Blazer/Suburbans	PRJ-13308	ENGINEERING
1094815	6/17/22	6/9/22	LOCKHART, SIDNEY	2.00		ASSIGNED	Blazer/Suburbans	PRJ-13308	ENGINEERING
1094815	6/17/22	6/9/22	LOCKHART, SIDNEY	2.00	0.50	ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	6/17/22	6/9/22	LOCKHART, SIDNEY	2.00	0.80	ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	6/17/22		LOCKHART, SIDNEY	2.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	2.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	2.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
			· · · · · · · · · · · · · · · · · · ·				<u> </u>	PRJ-13300	
1094815	7/1/22		LOCKHART, SIDNEY	2.00		ASSIGNED	Blazer/Suburbans	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	2.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	7/1/22	6/21/22	LOCKHART, SIDNEY	1.00	5.69	ASSIGNED	Blazer/Suburbans	PRJ-13308	ENGINEERING
1094815	7/1/22	6/21/22	LOCKHART, SIDNEY	1.00	0.40	ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	7/1/22	6/21/22	LOCKHART, SIDNEY	1.00	2.34	ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/1/22	6/21/22	LOCKHART, SIDNEY	1.00	0.25	ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
							•		
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Blazer/Suburbans	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	7/1/22	6/23/22	LOCKHART, SIDNEY	1.00		ASSIGNED	Blazer/Suburbans	PRJ-13308	ENGINEERING
1094815	7/1/22	6/23/22	LOCKHART, SIDNEY	1.00	0.25	ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	7/1/22	6/23/22	LOCKHART, SIDNEY	1.00	0.40	ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Blazer/Suburbans	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/1/22	6/28/22	LOCKHART, SIDNEY	1.00	5.69	ASSIGNED	Blazer/Suburbans	PRJ-13308	ENGINEERING
1094815	7/1/22	6/28/22	LOCKHART, SIDNEY	1.00	0.25	ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Blazer/Suburbans	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	7/1/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	7/1/22	6/30/22	LOCKHART, SIDNEY	1.00	5.69	ASSIGNED	Blazer/Suburbans	PRJ-13308	ENGINEERING
1094815	7/15/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	7/15/22		LOCKHART, SIDNEY	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/15/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	7/15/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Blazer/Suburbans	PRJ-13308	ENGINEERING
1094815	7/15/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	7/15/22		LOCKHART, SIDNEY	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/15/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Blazer/Suburbans	PRJ-13308	ENGINEERING
1094815	7/15/22	7/11/22	LOCKHART, SIDNEY	1.00	0.25	ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
1094815	7/15/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Cell Phone	PRJ-13308	ENGINEERING
1094815	7/15/22		LOCKHART, SIDNEY	1.00		ASSIGNED	PC/Computer	PRJ-13308	ENGINEERING
1094815	7/15/22		LOCKHART, SIDNEY	1.00		ASSIGNED	Blazer/Suburbans	PRJ-13308	ENGINEERING
1094815	7/15/22	1/13/22	LOCKHART, SIDNEY	1.00		ASSIGNED	Tablet/iPad	PRJ-13308	ENGINEERING
			LOCKHART, SIDNEY Total	1	147.56		1	<u> </u>	
1094816	5/5/22	4/29/22	PARROTT, JEFFREY	1.00	0.40	ASSIGNED	Cell Phone	PRJ-13308	ROW
·		·	· · · · · · · · · · · · · · · · · · ·		·				

1094816	5/5/22	4/29/22	PARROTT, JEFFREY	1.00	2.34	ASSIGNED	PC/Computer	PRJ-13308	ROW
1094816	5/5/22	4/29/22	PARROTT, JEFFREY	1.00	0.25	ASSIGNED	Tablet/iPad	PRJ-13308	ROW
1094816	5/5/22	5/5/22	PARROTT, JEFFREY	1.00	2.34	ASSIGNED	PC/Computer	PRJ-13308	ROW
1094816	5/5/22	5/5/22	PARROTT, JEFFREY	1.00	0.40	ASSIGNED	Cell Phone	PRJ-13308	ROW
1094816	5/5/22	5/5/22	PARROTT, JEFFREY	1.00	0.25	ASSIGNED	Tablet/iPad	PRJ-13308	ROW
1094816	6/16/22	6/14/22	PARROTT, JEFFREY	2.00	0.80	ASSIGNED	Cell Phone	PRJ-13308	ROW
1094816	6/16/22	6/14/22	PARROTT, JEFFREY	2.00	4.68	ASSIGNED	PC/Computer	PRJ-13308	ROW
1094816	6/16/22	6/14/22	PARROTT, JEFFREY	2.00	0.50	ASSIGNED	Tablet/iPad	PRJ-13308	ROW
			PARROTT, JEFFREY Total		11.96				
1094816	6/17/22	4/2/22	PS Assigned Equipment	0.00	(5.98)	UNASSIGNED-		PRJ-13308	ROW
1094815	7/8/22	4/22/22	PS Assigned Equipment	0.00	(54.53)	UNASSIGNED-		PRJ-13308	ENGINEERING
1094815	7/8/22	4/22/22	PS Assigned Equipment	0.00	(65.82)	UNASSIGNED-		PRJ-13308	ENGINEERING
			PS Assigned Equipment Total		(126.33)				
			Grand Total		188.72				



Applied Science, Inc. 21455 Melrose Ave. Bldg R Suite 12 Southfield, MI 48075

455 Melrose Ave. Bldg R Suite 12 Southfield, MI 48075 Phone: (313) 567-3990 Fax: (313) 567-3750 www.asi-detroit.com

August 2, 2022

Project Invoice #42 (ASI Inv. #8199)

Joel Brown, P.E. Civil Engineer III Oakland County Water Resources Commissioner's Office One Public Works Drive, Building 95 West Waterford, MI 48328

Re: Northeast Sanitary Pump Station

Contract #5470 (ASI Job No. 1815)

li# 41133 v#352

Invoice Period: 6/26/22-7/30/22

			Total This	
Task No.	Task Description		Invoice	
1	Transition & Basis of Design			
	Total:	\$	-	
			Total This	
Task No.	Task Description		Invoice	
2	Design Services for Pump & Electrical Upgrades			
	Total:	\$	-	
	Subconsultants:			
	FK Engineering:	\$	-	
	NTH Consultants	\$	-	
	ASI Markup 5%:	\$		
	Total Due This Invoice:	\$	-	
			Total This	
Task No.	Task Description		Invoice	
3	Additional Special Services	•		
	Total:	\$	-	
	Subconsultants:	φ		
	FK Engineering:	\$	-	
	ASI Markup 5%:	<u>\$</u> \$		
	Total Due This Invoice:	<u> </u>	- Total This	
Task No.	Task Description		Invoice	
5	Construction Services		IIIVOICE	
Ü	Total:	\$	44,162.00	
	Subconsultants:	Ψ	11,102.00	
	NTH Consultants	\$	28,691.24	
	Metco Services	\$	33,131.00	
	FK Engineering:	\$	3,411.75	
	ASI Markup 5%:	\$	3,261.70	
	Direct Expenses:	\$	623.20	
	Total Due This Invoice:	\$	113,280.89	
	Total Bas Tills involos.	<u> </u>	110,200.00	84917-149015-730639-1-3309
	Total Due This Invoice:	\$	113,280.89	engcon
	Previous Amount Invoiced:	\$:	3,223,837.51	
	Total Invoiced To-Date		3,337,118.40	ITD 0/44/0000
	Original Contract Task Total:		4,198,380.00	JTB 8/11/2022
		Ψ	+, 100,000.00	
		\$	284 076 60	
	Additional Budget:	\$ \$ 4	284,076.60 4 482 456 60	
		\$ 4	284,076.60 4,482,456.60 1,145,338.20	



Invoice: 1

1220403

Oakland-Macomb Interceptor Drain Drainage District

Date: 07/12/2022

Attn: Megan Koss, Esq. 1 Public Works Drive Client: 58434 Matter: 424741

Waterford, MI 48328

WRClegalinvoices@oakgov.com

82912 - 6010101 -149030 - 731073 -5113

-v#2788 - exp. 5/15/22

Matter Name: GLWA Model Wastewater Contract

If Bu

8/11/2022

LEGAL SERVICES RENDERED AND COSTS ADVANCED THROUGH JUNE 30, 2022

Total Fees: \$ 13,608.00 **Total Due This Invoice:** \$ **13,608.00**



84917 - 6010101 - 149015 - 731073 - 2603 - 1-3308 LEGAL- Ch.21 v#4716 - li#24138 - exp. 12/31/23

Il Bu

8/11/2022

Invoice: 1220405

Date: 07/12/2022

Client: 58434 Matter: 404547

Oakland-Macomb Interceptor Drain Drainage District Attn: Megan Koss, Esq.

1 Public Works Drive Waterford, MI 48328

WRClegalinvoices@oakgov.com

Matter Name: Northeast Interceptor East Arm Improvements

LEGAL SERVICES RENDERED AND COSTS ADVANCED THROUGH JUNE 30, 2022

Total Fees: \$ 135.00

Total Due This Invoice: \$ 135.00



2600 W. BIG BEAVER ROAD, SUITE 300

TROY, MI 48084-3312
TELEPHONE: (248) 433-7200
http://www.dickinsonwright.com

FEDERAL I.D. #38-1364333

INVOICE DATE: JULY 21, 2022 INVOICE NO.: 1715594

OAKLAND COUNTY WATER RESOURCES COMMISSIONER ATTORNEY & INSURANCE ADMINISTRATOR ONE PUBLIC WORKS DRIVE, #95 WATERFORD, MI 48328

ATTN: STEVE KORTH

82912 - 6010101 - 149030 - 731073 - 5089 - Ch.


CLIENT/MATTER NO.: 012840-00436 21 - v# 4978 - li# 39111

If Bu 8/11/2022

RE: PREPARE BOARD MEMORANDUM RE LOCKOUT-TAGOUT (LOTO) ISSUE

PRIVILEGED AND CONFIDENTIAL

FOR PROFESSION	IAL SERVICES THE	ROUGH JUNE 30, 2022				<u>USD</u>
TOTAL FEES (CURRENT INVOICE				\$	1,619.50
TOTAL CURRI	ENT INVOICE				\$	1,619.50
OUTSTANDING	G INVOICES ON TH	E MATTER BILLED ON	THIS CURRENT I	NVOICE AS OF JU	LY 21, 20	022
<u>INVOICE</u>	<u>DATE</u>	BILLED VALUE	<u>PAYMENTS</u>	OUTSTANDING		
1703938	06/16/22	3,002.00	(0.00)	3,002.00	Paid Ju	ily OMID
TOTAL OUTST	ANDING FROM PR	IOR INVOICES			\$	3,002.00
TOTAL AMOU	NT DUE				\$	4,621.50



Remittance Instructions						
Terms: Due and Payable Upon Receipt						
Wire Instructions:						
Morgan Chase Bank N.A. 660 Northwestern Highway uthfield, MI 48034 BA Number: 021 000 021 vift Code: CHASUS33 (International) count# 38852 lease Reference Invoice Numbers)						
)						



Knowledgeable · Professional · Attentive · Likeable

29770 Hudson Drive Novi, MI 48377 Phone: (586) 978-7200

hesco-mi.com

Invoice No. 2213786

Date: 07/18/2022

Billed To: OMID Drainage District

1 Public Works Drive Waterford MI 48328 82912 - 149130 - 730660 - 5819 - Ch. 21 - v#3091 - exp. 6/30/25 - li#42703

If Bu

8/11/2022

Contract ID: 5819

HESCO Project: 2019807S OMID Flow Control Structures2019565

Contact: Terry Moore	P.O.#	WO# 005673 CS-5	Salesperson:	Kevin Livingsto	n Due Date:	08/17/2022
Description			Ur	nit Qty	Rate	Amount
7/7/2022 - Preventative Maintena	nce visit					
Senior Tech			Но	urs 7.50	195.00	1,462.50
Tech 1			Но	urs 6.50	185.00	1,202.50
Tech 2			Но	urs 6.50	175.00	1,137.50
Parts						
Return Filter			Ead	ch 1.00	17.25	17.25
Pressure Filter			って Ead	ch 1.00	69.50	69.50
Nitrogen Charge		M-7-19-	V	1.00	127.50	127.50

Notes:

Preventative Maintenance and Inspection.

Amount Due	4,016.75
Payments/Credits:	0.00
Total Invoice	4,016.75
Sales Tax:	0.00
Taxable Amount:	0.00
Non-Taxable Amount:	4,016.75



Jacobs Consultants, Inc.

 Invoice No.:
 C6A19900-02

 Invoice Date:
 7/6/2022

 Jacobs Project No.:
 C6A19900

 Services From:
 5/28/2022

 Services Through:
 6/24/2022

Oakland-Macomb Interceptor Drain Drainage District c/o Oakland County Water Resources Commissioner's Office One Public Works Drive Bldg. 95 West Waterford, Michigan 48328

Attn: Mr. Joel Brown, P.E.

Project Description: OMID Odor and Corrosion Control Facilities

82912 - 149667- 730639 -1-17059- ENGCONSULT8/11/2022

JTB

Task Number	Task Description	E	Budget Total	Prev	viously Invoiced	С	Current Invoice	Pr	roject to Date	Ren	naining Budget
Task 1	Additional Investigation/Modeling	\$	148,364.90	\$	80,026.58	\$	49,693.13	\$	129,719.71	\$	18,645.19
Task 2	Basis of Design	\$	122,605.02	\$	20,937.98	\$	6,183.45	\$	27,121.43	\$	95,483.59
Task 3	ST-S-3 Vapor-Phase Treatment System - Subtask 3.1 - Design	\$	235,745.04	\$	-	\$	6,747.70	\$	6,747.70	\$	228,997.34
Task s	ST-S-3 Vapor-Phase Treatment System - Subtask 3.2 - Bidding	\$	17,154.74	\$	-	\$	-	\$	-	\$	17,154.74
T I. 4	CS-6 Pump Station Vapor-Phase System - Subtask 4.1 - Design	\$	191,218.29	\$	_	\$	5,441.96	\$	5,441.96	\$	185,776.33
Task 4	CS-6 Pump Station - Vapor-Phase System Subtask 4.2 - Bidding	\$	15,612.91	\$	-	\$	-	\$	-	\$	15,612.91
Task 5	CS-8 and ST-S-1 Local Odor Control - Subtask 5.1 - Design	\$	80,199.91	\$	-	\$	2,552.13	\$	2,552.13	\$	77,647.78
1838 3	CS-8 and ST-S-1 Local Odor Control - Subtask 5.2 - Bidding	\$	12,829.09	\$	-	\$	-	\$	-	\$	12,829.09
	Total	\$	823,729.90	\$	100,964.56	\$	70,618.37	\$	171,582.93	\$	652,146.97

Previously Invoiced \$100,964.56

Total This Invoice: \$70,618.37

Total Invoiced To Date: \$171,582.93

Budget Amount: \$823,729.90

Remaining Amount USD: \$652,146.97

Outstanding Invoices										
Date	Invoice No.	Invoiced Amount	Paid Date	Paid Amount	Amount Outstanding					
6/16/2022	C6A19900-01	\$100,964.56			\$100,964.56					

Signed

Jason Matteo Project Manager

Jasan G. Matter

Please remit payment electronically to: Beneficiary Bank: Bank of America Account Name: Jacobs Consultants, Inc. Transit for ACH: 111000012

Transit for Wires: 026009593 Account No (USD): 4451457732



INVOICE									
DATE	NUMBER	PAGE							
5/4/2022	630978	1 of 1							

B OMI100

I OAKLAND MACOMB INTERCEPTOR DRA

1 PUBLIC WORKS DR.

SUBMIT INVOICES TO NEXGEN

T WATERFORD, MI 48328

82912-6010101-149090-730660-5825ch.21-v#239 exp. 6/30/25

NORTH EAST PUMPING STATION

H 8598 E. STATE FAIR AVE

DETROIT, MI 48234

8/11/2022

ATTENTION:

TERRY MOORE

313-8297207

TMOORE@METCOSERVICES COM

TERRY MOORE 313-0297207 IMOORE@METCOSERVICES.COM										
CUST	OMER F	REF/PO#	JOB #		JOB TITLE	SLP	SHIPPING	TYPE	TERMS	
			0105960	NOR	THEAST PUMP STATION, FIELD SERVICE, SANITARY	KES/PM	FIELD SERV	VICE		NET 60
QUANTITY PART NO.			TNO		DESCRIPTION			LINITE DD	TOF	EVTENDED
B/O	Ship	PAR	TI NO.		DESCRIPTION	UNIT PR	ICE	EXTENDED		
0.00	13.50	GRE550N	ORTHEASTF	PS	GLWA, NORTHEAST PUMP STATI KENNEDY INDUSTRIES PROVIDE TECHNICIAN(S) ONSITE ON 4/29 PLEASE SEE THE ATTACHED SER	\$110.0	00	\$1,485.00		
0.00	1.00	TRAVEL			SERVICE TRUCK			\$33.0	00	\$33.00

PLEASE REMIT TO: KENNEDY INDUSTRIES, INC. P.O. BOX 930079 **WIXOM, MI 48393**

> This invoice is subject to and incorporates by reference Kennedy Industries, Inc.'s ("Kennedy") Terms & Conditions (Rev'd 4/2019) and Customer Warranty available at www.kennedyind.com which will be provided by email upon written request. Buyer expressly agrees to the provisions set forth in the Terms & Conditions and Customer Warranty posted on Kennedy's website

> *TERMS OF PAYMENT ARE NET 30 DAYS FROM DATE OF INVOICE *A 7% PER ANNUM SERVICE CHARGE SHALL BE APPLIED TO ANY BALANCE *CREDIT CARD PAYMENTS ARE SUBJECT TO AN ADDITIONAL 3% CHARGE

SUBTOTAL: \$1,518.00

TAX: \$0.00

TOTAL: \$1,518.00

P.O. Box 930079 Wixom, MI 48393 - 4925 Holtz Drive Wixom, MI 48393 - Phone: 248-684-1200 - Fax: 248-684-6011



INVOICE									
DATE	NUMBER	PAGE							
7/8/2022	631969	1 of 1							

NORTH EAST PUMPING STATION

н 8598 E. STATE FAIR AVE

DETROIT, MI 48234

B OMI100

I OAKLAND MACOMB INTERCEPTOR DRA

1 PUBLIC WORKS DR.

SUBMIT INVOICES TO NEXGEN

T WATERFORD, MI 48328

82912-6010101-149090-730660-5825ch.21-v#239 exp. 6/30/25

8/11/2022

ATTENTION: TERRY MOORE

313-8297207

TMOORE@METCOSERVICES.COM

I LI	KI MO	OKL	212-0	029/20	/ INDOREGINETOS	PLKAICE2'C	الاال		
CUST	OMER R	EF/PO#	JOB #	A A	JOB TITLE	SLP	SHIPPING	TYPE	TERMS
			0105960	NOR	THEAST PUMP STATION, FIELD SERVICE, SANITARY	KES/PM	FIELD SERV	/ICE	NET 60
QUANTITY PART NO.			T NO		DESCRIPTION			UNIT PRIC	E EXTENDED
B/O	Ship	FAR	CI NO.		DESCRIPTION	UNII PRIC	EXTENDED		
0.00	0.00 9.50 GRE550NORTHEASTPS GLWA, NORTHEAST PUMP STATION KENNEDY INDUSTRIES PROVIDED (2) FIELD SERVICE TECHNICIAN(S) ONSITE ON 6/28/2022. PLEASE SEE THE ATTACHED SERVICE REPORT.						\$110.00	\$1,045.00	
0.00	2.50	GRE550N	ORTHEAST	PS	GLWA, NORTHEAST PUMP STATI	ON			
0.00	1.00	TRAVEL			SERVICE TRUCK			\$66.00	\$66.00

-TM-8-3-22

PLEASE REMIT TO: KENNEDY INDUSTRIES, INC. P.O. BOX 930079 **WIXOM, MI 48393**

> This invoice is subject to and incorporates by reference Kennedy Industries, Inc.'s ("Kennedy") Terms & Conditions (Rev'd 4/2019) and Customer Warranty available at www.kennedyind.com which will be provided by email upon written request. Buyer expressly agrees to the provisions set forth in the Terms & Conditions and Customer Warranty posted on Kennedy's website

> *TERMS OF PAYMENT ARE NET 30 DAYS FROM DATE OF INVOICE *A 7% PER ANNUM SERVICE CHARGE SHALL BE APPLIED TO ANY BALANCE *CREDIT CARD PAYMENTS ARE SUBJECT TO AN **ADDITIONAL 3% CHARGE**

SUBTOTAL: \$ 1,111.00

CREDIT ON ACCOUNT: \$70.05

TAX:

\$ 0.00

TOTAL:

\$1,040.95



INVOICE NO. 1811-43 DATE: August 1, 2022

METCO PROJECT NO. 1811 INVOICE PERIOD: 6/27 thru 7/31/2022

Contract ID 00000000000000000005517

Vendor ID 0000020486

TO: OMIDD

Water Resources Commissioner One Public Works Drive Waterford, MI 48328

Attn: Mr. Sid Lockhart, PE

Deputy Chief Engineer/Special Projects Manager

TITLE: OMID & NESPS Operation and Maintenance

Operational Plan

OMID Operations - Fund 82912, Program 149130, Account 730373 (3.1-3.4A & 3.4B) JTB 8/11/2022

<u>Name</u>	<u>Title</u>	Hrs.	Rate/Hr.			<u>Amount</u>	
Raj Vijayendran, PE	Principal Engineer	0.0	\$	215.00	\$	-	
Terry Moore	Operations Manager	40.0	\$	145.00	\$	5,800.00	
Terry Moore	Operations Manager (Overtim	0.0	\$	195.00	\$	-	
Darrin Green	Staff Engineer	44.0	\$	90.00	\$	3,960.00	
Darrin Green	Staff Engineer-(Overtime)	10.3	\$	135.00	\$	1,383.75	
Anthony Vozza	Staff Engineer	52.0	\$	90.00	\$	4,680.00	
Anthony Vozza	Staff Engineer-(Overtime)	0.0	\$	135.00	\$	-	
Rosana Santos	Administrative Assoc.	0.0	\$	73.79	\$	-	
Subtotal OMID Operatons:						15,823.75	

NEPS Operations - Fund 82912, Program 149090, Account 730373 (3.1-3.4A & 3.4B)

JTB 8/11/2022

<u>Name</u>	<u>Title</u>	<u>Hrs.</u>	<u>R</u>	ate/Hr.	<u>Amount</u>
Raj Vijayendran, PE	Principal Engineer	8.0	\$	215.00	\$ 1,720.00
Terry Moore	Operations Manager	40.0	\$	145.00	\$ 5,800.00
Terry Moore	Operations Manager (Overtim	7.0	\$	195.00	\$ 1,365.00
Darrin Green	Staff Engineer	49.0	\$	90.00	\$ 4,410.00
Darrin Green	Staff Engineer-(Overtime)	2.5	\$	135.00	\$ 337.50
Anthony Vozza	Staff Engineer	17.0	\$	90.00	\$ 1,530.00
Anthony Vozza	Staff Engineer-(Overtime)	0.0	\$	135.00	\$ -
Rosana Santos	Administrative Assoc.	4.0	\$	73.79	\$ 295.16
		Subtotal NE	\$ 15,457.66		

ibiotal NEFS Operations \$ 15,457.00

Subtotal Operations \$ 31,281.41

Maintenance & Asset Management

OMID Maintenance – Fund 82912, Program 149130, Account 730646 (3.2-3.3-3.4C & ALLOWANCE) JTB 8

JTB 8/11/2022

<u>Name</u>	<u>Title</u>	<u>Hrs.</u>	<u>R</u>	ate/Hr.		<u>Amount</u>
Terry Moore	Operations Manager	40.0	\$	145.00	\$	5,800.00
Terry Moore	Operations Manager (Overtim	0.0	\$	195.00	\$	-
Anthony Vozza	Staff Engineer	46.0	\$	90.00	\$	4,140.00
Darrin Green	Staff Engineer	6.0	\$	90.00	\$	540.00
Subtotal OMID Maintenance:						10,480.00

NEPS Maintenance – Fund 82912, Program 149090, Account 730646 (3.2-3.3-3.4C & ALLOWANCE)

8/11/2022

<u>Name</u>	<u>Title</u>	Hrs.	<u>R</u>	ate/Hr.	<u>Amount</u>
Raj Vijayendran, PE	Principal Engineer	8.0	\$	215.00	\$ 1,720.00
Terry Moore	Operations Manager	40.0	\$	145.00	\$ 5,800.00
Terry Moore	Operations Manager (Overtim	7.0	\$	195.00	\$ 1,365.00
Daniel Martel	Sr. Project Coordinator	0.0	\$	145.00	\$ -
Sean Grant	Sr. Project Engineer	0.0	\$	145.00	\$ -

Travis Ford	Sr. Project Engineer	0.0	\$ 145.00	\$ -
Shailesh Patel	Sr. Project Engineer	0.0	\$ 145.00	\$ -
Darrin Green	Staff Engineer	51.0	\$ 90.00	\$ 4,590.00
Darrin Green	Staff Engineer-(Overtime)	0.0	\$ 135.00	\$ -
Anthony Vozza	Staff Engineer	23.0	\$ 90.00	\$ 2,070.00
Anthony Vozza	Staff Engineer-(Overtime)	1.5	\$ 135.00	\$ 202.50
Brandon Brochue	Designer/Drafter	0.0	\$ 85.00	\$ -

Subtotal: \$ 15,747.50

Maintenance Services (see attached invoices): \$ 6,720.00 Subtotal NEPS Maintenance: \$ 22,467.50

Subtotal Maintenance: \$ 32,947.50

NEPS Maintenance – Fund 82912, Program 149090, Account 730646 (Under NEXGEN ALLOWANCE) 8/11/2022

<u>Name</u>	<u>Title</u>	Hrs.	<u>R</u>	ate/Hr.	<u>Amount</u>	
Raj Vijayendran, PE	Principal Engineer	0.0	\$	215.00	\$	-
Terry Moore	Operations Manager	0.0	\$	145.00	\$	-
Terry Moore	Operations Manager (Overtim	0.0	\$	195.00	\$	-
Sean Grant	Sr. Project Engineer	17.0	\$	145.00	\$	2,465.00
Darrin Green	Staff Engineer	0.0	\$	90.00	\$	-
Darrin Green	Staff Engineer-(Overtime)	0.0	\$	135.00	\$	-
Anthony Vozza	Staff Engineer	0.0	\$	90.00	\$	-
Abhishek Shah	Staff Engineer	156.0	\$	90.00	\$	14,040.00
Brandon Brochue	Designer/Drafter	0.0	\$	85.00	\$	-

Subtotal Maintenance: \$ 16,505.00

Task 12.0 - As-Needed Services

Additional General/Excess Liability Insurance Fee: \$ -

Subtotal 12.0: \$ -

TOTAL AMOUNT DUE THIS INVOICE: \$ 80,733.91



MOTOR CITY ELECTRIC TECHNOLOGIES INC.

9440 GRINNELL DETROIT, MI 48213-1151 PHONE (313) 921-5300 FAX (313) 921-5310 "AN EQUAL OPPORTUNITY EMPLOYER"

INVOICE

OMID

ONE PUBLIC WORKS DRIVE, BUILDING 95

WATERFORD, MI 48328-

Customer PO Number

Job	Sub	Contract	Date	Applic	ation
Number	Job	Number	Performed	Date	Number
922567	0	001	5/19/2022	6/2/2022	94500

SID LOCKHART

Item No	Description of Work	Contract Amount	Previous Billings	Current Amount	To Date Complete & Stored	Balance To Finish	Current Retainage
001	NESP SCADA CUTOVER	\$351.00	ÿ	\$351.00	\$351.00	*	*
	Tota	als: \$351.00		\$351.00	\$351.00		
		Retained: ice Total:		\$351.00			

AS NEEDED ELECTRICAL AND ENGINEERING SERVICE

82912 - 6010101 - 149090- 730660 - 5469 - Ch. 21 - v# 7755 - li# 41132 - exp.

12/31/23

SEE ATTACHED INVOICE SUMMARY AND FIELD REPORT

WORK PERFORMED 5/19/2022 - WORK ORDER NO. 00632

M-8-3-22

complete electrical construction



MOTOR CITY ELECTRIC TECHNOLOGIES INC.

9440 GRINNELL DETROIT, MI 48213-1151 PHONE (313) 921-5300 FAX (313) 921-5310 "AN EQUAL OPPORTUNITY EMPLOYER"

INVOICE

OMID

ONE PUBLIC WORKS DRIVE, BUILDING 95

WATERFORD, MI 48328-

Customer PO Number

Job	Sub	Contract	Date	Application	
Number	Job	Number	Performed	Date	Number
922567	0	001	7/18/2022	8/1/2022	94596

II Bu 8/11/2022

SID LOCKHART

Item No	Description of Work		Contract	Previous	Current	To Date	Balance	Current
			Amount	Billings	Amount	Complete & Stored	To Finish	Retainage
001	NESP SCADA CUTOVER		\$252.00	-	\$252.00	\$252.00	-	-
		Totals:	\$252.00		\$252.00	\$252.00		
		Less Retained: Invoice Total:			- \$252.00			

AS NEEDED ELECTRICAL AND ENGINEERING SERVICE

SEE ATTACHED INVOICE SUMMARY AND FIELD REPORT

WORK PERFORMED 7/18/2022 WORK ORDER NO. 00457

82912 - 6010101 - 149130-730660 - 5469 - Ch. 21 - v# 7755 - Ii# 41132 -

exp. 12/31/23

TM 8-1-22

complete electrical construction



84917 - 6010101 - 149015 - 730639 - 2603 - 1-3308 - Ch.21 v#4716 - li#24138 - exp. 12/31/23

OMI Drain Drainage District One Public Works Drive Building 95 West Waterford, MI 48328 8/11/2022

Invoice #: 630201 Project: 61-190078 Invoice Group: NI-EA Invoice Date: 8/3/2022

Attention: Sid Lockhart

For Professional Services Rendered from 6/25/2022 - 7/22/2022

If Bu

Engineering Design Services for Rehabilitation of NI-EA Sections PCI-4

Task 01	Project Management	\$276,159.00
Task 02	Condition Assessment	\$241,609.00
Task 03	Subsurface Utility Engineering	\$65,579.00
Task 04	Basemap Survey	\$89,327.00
Task 05	Geotechnical Investigation	\$134,797.00
Task 05A	7-Mile Utility Exploration/Design	\$0.00
Task 05B	Additional Geotech for PCI-4 Shaft	\$0.00
Task 06	Environmental Study	\$60,642.00
Task 07	Basis of Design	\$379,785.00
Task 08	Rehabilitation Design	\$282,099.00
Task 09	Contract Drawings	\$235,070.00
Task 10	Contract Specifications	\$188,178.00
Task 11	Construction Costs	\$27,761.00
Task 12	Permits & Coordination	\$25,655.00
Task 13	Bidding Assistance	\$198,402.00
Task 14	Gate Automation	\$68,770.00
Task 15	Odor & Air Flow Study	\$84,926.00

Preliminary Budget Amount \$2,358,759.00
Percent Complete: 93.31%

Analysis of Costs	This Invoice	Cumulative
Direct Salaries	\$ 515.72	\$ 311,526.32
Overhead %	188.00 969.55	585,669.50
Total Regular Labor Expense	1,485.27	897,195.82
Total Direct Labor	1,485.27	897,806.47
Profit / Fixed Fee %	12.00 178.23	107,663.48
Direct Expenses Charge	0.00	27,671.41
Expense Multiplier %	5.00 0.00	1,383.61
Direct Subcontractor Charge	0.00	1,101,049.75
Subcontractor/Subconsultant Multiplier %	6.00 0.00	66,063.14
Total Other Direct Charges Reimbursables	0.00	1,196,167.91
Total Costs:	1,663.50	2,201,027.21
Total Due This Invoice	\$ 1,663.50	\$ 2,201,027.21

Phone: 248-553-6300



84917 -6010101 -149015 -731444 - 2603 -1-3308- ch 21 v#4716 - li#24138 - exp. 12/31/23

JTB 8/11/2022

OMI Drain Drainage District One Public Works Drive Building 95 West Waterford, MI 48328 Invoice #: 630202 Project: 61-200186 Invoice Group: ** Invoice Date: 8/3/2022

Attentior Sid Lockhart

For Professional Services Rendered from 6/25/2022 - 7/22/2022

Provide Engineering Services for OMID NI-EA Contract No.1 PCI-4 Rehabilitation Project and CS-9 Gate Installation Project D-425

 Task 01
 NI-EA OMID Contract No. 1 CCA
 \$2,251,268.82

 Task 02
 OMID CS-9 Gate CCA
 \$217,468.00

 Preliminary Budget Amount
 \$2,468,736.82

 Percent Complete:
 63.92%

Analysis of Costs		This Invoice	Cumulative
Direct Salaries	\$	16,317.09	\$ 310,228.00
Overhead %	188.00	30,676.13	583,228.65
Total Regular Labor Expense		46,993.22	893,456.65
Total Direct Labor		46,993.22	893,456.65
Profit / Fixed Fee %	12.00	5,639.19	107,214.82
Direct Expenses Charge		2,536.32	17,802.18
Expense Multiplier %	5.00	126.82	890.11
Direct Subcontractor Charge		12,644.27	526,993.98
Subcontractor/Subconsultant Multiplier %	6.00	758.67	31,619.70
Direct Unit Rate Charge		0.00	0.00
Total Other Direct Charges Reimbursables		16,066.08	577,305.97
Total Costs:		68,698.49	1,577,977.44
Total Due This Invoice	<u>\$</u>	68,698.49	\$ 1,577,977.44



84917- 6010101 - 149015 - 731458 - 2603 - 1-3309ch 21 - engcon v#4716 - li#24138 - exp. 12/31/23

8/11/2022

OMI Drain Drainage District One Public Works Drive Building 95 West Waterford, MI 48328 Invoice #: 630204
Project: 61-200280
Invoice Group: CMT
Invoice Date: 8/3/2022

Attentior Sid Lockhart

For Professional Services Rendered from 6/25/2022 - 7/22/2022

Provide Engineering and Consulting Services regarding NESPS Pumping and Electrical System Upgrade (D-421)

 Task 01
 CMT Services
 \$130,138.00

 Task 02
 Tnemec Coating Observation
 \$0.00

 Preliminary Budget Amount
 \$130,138.00

 Percent Complete:
 85.08%

Analysis of Costs This Invoice Cumulative **Direct Salaries** 308.07 29,358.63 188.00 Overhead % 579.17 55,194.25 Total Regular Labor Expense 84,552.88 887.24 **Total Direct Labor** 84,552.88 10,146.35 Profit / Fixed Fee % 12.00 106.47 15,253.16 Direct Expenses Charge 34.29 Expense Multiplier % 5.00 1.71 762.66 Direct Subcontractor Charge 10.00 0.00 Subcontractor/Subconsultant Multiplier % 6.00 0.00 0.60 Direct Unit Rate Charge 0.00 0.00 16,026.42 **Total Other Direct Charges Reimbursables** 36.00 1,029.71 110,725.65 **Total Costs: Total Due This Invoice** 1,029.71 110,725.65



82912 - 6010101 - 149662 - 731458- 2603 - Ch. 21 - v#238 - Ii#24138 - exp. 12/31/23

OMI Drain Drainage District One Public Works Drive Building 95 West Waterford, MI 48328 8/11/2022

Invoice # : 630205 Project : 61210124

Invoice Group: **

Invoice Date : 8/3/2022

Attention Sid Lockhart

For Professional Services Rendered from 6/25/2022

6/25/2022 - 7/22/2022

Consulting Services Regarding 2021 OMID System Inspection

Task 01 Inspection and Reporting Preliminary Budget Amount

\$526,974.00 \$526,974.00

50.28%

Percent Complete:

Analysis of Costs	٦	This Invoice	Cumulative	
Direct Salaries	\$	39.88	\$ 16,360.87	
Overhead %	188.00	74.97	30,758.44	
Total Regular Labor Expense		114.85	47,119.31	
Total Direct Labor		114.85	114.85	
Profit / Fixed Fee %	12.00	13.78	5,654.31	
Direct Expenses Charge		0.00	855.92	
Expense Multiplier %	5.00	0.00	42.82	
Direct Subcontractor Charge		1,131.95	199,331.91	
Subcontractor/Subconsultant Multiplier %	6.00	67.92	11,959.92	
Direct Unit Rate Charge		0.00	0.00	
Total Other Direct Charges Reimbursables		1,199.87	212,190.57	
Total Costs:		1,328.50	264,964.19	
Total Due This Invoice	\$	1,328.50	\$ 264,964.18	



82912 - 149090 - 730639 - 2603 - Ch 21 - v#4716 exp. 12/31/23 li#24138

8/11/2022

Invoice #: 630206 **Project**: 61-210313

Invoice Group: **

Invoice Date : 8/3/2022

One Public Works Drive **Building 95 West** Waterford, MI 48328

OMI Drain Drainage District

Attention Sid Lockhart

For Professional Services Rendered from

6/25/2022 - 7/22/2022

Consulting Services Regarding Additional OMID Rehabilitation Program 2021 Closeout Services and As-Needed NESPS Maintenance Tasks

Task 01	Contract 3 NESPS Rehab Closeout	\$9,563.00
Task 02	PCI-4 Liner Deterioration Closeout	\$10,939.00
Task 03	Discharge Pipe Coating Rehabilitation	\$27,930.00
Task 04	NESPS Wet Well Sediment Survey	\$19,639.00
	Preliminary Budget Amount	\$68,071.00
	Percent Complete:	66.02%

Analysis of Costs	7	This Invoice	Cumulative
Direct Salaries	\$	151.97	\$ 8,645.52
Overhead %	188.00	285.70	16,253.58
Total Regular Labor Expense	•••••	437.67	24,899.10
Total Direct Labor		437.67	24,899.10
Profit / Fixed Fee %	12.00	52.52	2,987.88
Direct Expenses Charge		0.00	0.00
Expense Multiplier %	5.00	0.00	0.00
Direct Subcontractor Charge		108.13	16,242.54
Subcontractor/Subconsultant Multiplier %	5.00	5.41	812.14
Total Other Direct Charges Reimbursables		113.54	17,054.68
Total Costs:		603.73	44,941.66
Total Due This Invoice	<u>\$</u>	603.73	\$ 44,941.65



OMI Drain Drainage District One Public Works Drive Building 95 West Waterford, MI 48328

Attentior Sid Lockhart

For Professional Services Rendered from

6/25/2022 - 7/22/2022

Authorization per Engineering Work Order D 439 date 12/03/2021

82912-149662-730639-Cont#1-2603 Exp (12/31/21-Rev)

82912- 6010101- 149662-730639- 2603 - Ch.21 - v# 4716 - li #24138 - exp. 12/31/23

8/11/2022

Invoice #: 630207

Invoice Date : 8/3/2022

Invoice Group:

Project: 61210495

Additional OMID NESPS Maintenance Engineering Services

Task 01NESPS Health and Safety Audit\$16,137.00Task 02Control Structure 6 (CS-6) Emergency Bypass System Design\$39,643.00Task 03Wet Wall Screen Cleaning Equipment\$17,069.00Task 04Control Structure Gate Inspection\$10,022.00

Preliminary Budget Amount \$82,871.00
Percent Complete: 68.40%

Analysis of Costs	1	Cumulative	
Direct Salaries	\$	286.36	\$ 12,953.13
Overhead %	188.00	538.36	24,351.88
Total Regular Labor Expense		824.72	37,305.01
Total Direct Labor		824.72	37,305.01
Profit / Fixed Fee %	12.00	98.97	4,476.60
Direct Expenses Charge		5.71	325.65
Expense Multiplier %	5.00	0.29	16.29
Direct Subcontractor Charge		0.00	13,738.10
Subcontractor/Subconsultant Multiplier %	6.00	0.00	824.29
Total Other Direct Charges Reimbursables		6.00	14,904.33
Total Costs:		929.69	56,685.94
Total Due This Invoice	\$	929.69	\$ 56,685.94

Rotor Electric Company of Michigan, LLC.



9522 GRINNELL
DETROIT, MI 48213-1151
PHONE (313) 891-0331 FAX (313) 921-5310
"AN EQUAL OPPORTUNITY EMPLOYER"



OMID

1 PUBLIC WORKS DRIVE WATERFORD, MI 48328-

Customer
PO Number
Professional Services Contrac

Job	Sub	Contract	Date	Application	
Number	Job	Number	Performed	Date	Number
719707	0	001	7/1/2022	7/13/2022	12530

JOEL BROWN

Item No	Description of Work	Contract Amount	Previous Billings	Current Amount	To Date Complete & Stored	Balance To Finish	Current Retainage
001	SWITCHGEAR MAINTENANCE AND TESTING	\$1,569.00	-	\$1,569.00	\$1,569.00	-	-
	Totals:	\$1,569.00		\$1,569.00	\$1,569.00		
	Less Retained: Invoice Total:			- \$1,569.00			

WO 655

P4 LOTO FOR PUMP INSPECTION

7M 8-1-22

Il Bu

8/11/2022

82912 - 6010101 - 149090 - 730660 - 5807 - Ch. 21 - v#22125 - Ii#42614 - exp. 6/28/25

Rotor Electric Company of Michigan, LLC.



9522 GRINNELL
DETROIT, MI 48213-1151
PHONE (313) 891-0331 FAX (313) 921-5310
"AN EQUAL OPPORTUNITY EMPLOYER"



OMID

1 PUBLIC WORKS DRIVE WATERFORD, MI 48328-

Customer PO Number

Professional Services Contrac

Job	Sub	Contract	Date	Appli	cation
Number	Job	Number	Performed	Date	Number
719707	0	001	7/1/2022	7/13/2022	12531

JOEL BROWN

Item No	Description of Work	Contract Amount	Previous Billings	Current Amount	To Date Complete & Stored	Balance To Finish	Current Retainage
001	SWITCHGEAR MAINTENANCE AND TESTING	\$7,082.93	-	\$7,082.93	\$7,082.93	-	-
	Totals:	\$7,082.93		\$7,082.93	\$7,082.93		
	Less Retained: Invoice Total:			- \$7,082.93			

WO 573

P2 VFD FAN MOTORS

TM 8-1-22

Jf Bu 8/11/2022

82912 - 6010101 - 149090 - 730660 - 5807 - Ch. 21 - v#22125 - Ii#42614 - exp. 6/28/25

Rotor Electric Company of Michigan, LLC.



9522 GRINNELL
DETROIT, MI 48213-1151
PHONE (313) 891-0331 FAX (313) 921-5310
"AN EQUAL OPPORTUNITY EMPLOYER"



OMID

1 PUBLIC WORKS DRIVE WATERFORD, MI 48328-

Customer
PO Number
Professional Services Contrac

Job	Sub	Contract	Date	Application		
Number	Job	Number	Performed	Date	Number	
719707	0	001	7/1/2022	7/13/2022	12532	

JOEL BROWN

Item No	Description of Work	Contract Amount	Previous Billings	Current Amount	To Date Complete & Stored	Balance To Finish	Current Retainage
001	SWITCHGEAR MAINTENANCE AND TESTING	\$2,357.42	-	\$2,357.42	\$2,357.42	-	-
	Totals:	\$2,357.42		\$2,357.42	\$2,357.42		
	Less Retained: Invoice Total:			- \$2,357.42			

WO 661

P5 BRUSH HOLDERS

TM 8-1-22

If Bu 8/11/2022

82912 - 6010101 - 149090 - 730660 - 5807 - Ch. 21 - v#22125 - li#42614 - exp. 6/28/25

Oakland-Macomb Interceptor Drain Drainage District

Regular Meeting – Wednesday, August 17, 2022

Agenda Item No. 11

Other Business

Oakland-Macomb Interceptor Drain Drainage District

Regular Meeting – Wednesday, August 17, 2022

Agenda Item No. 12

Adjourn